

VENDOR SERVICE PUBLICATION

TO: ☒ All Piper Distributors
☒ All Piper CORPAC's
☐ Affected Aircraft Owners/Operators
☐ All of the above

SUBJECT: Goodyear Aerospace Service Bulletin No. FT-77-1 Rev. B dated August 31, 1977; Recommended inspection of (Goodyear) fuel tanks, etc.

Models Affected:

Serial Numbers Affected:

Refer to Goodyear S.B. # FT-77-1 Section I. A. EFFECTIVITY for determination of affected aircraft.

Purpose: To provide distribution of the attached Service Publication (identified in SUBJECT, above) to Piper Field Service Facilities and, if applicable, to affected Piper owners/operators.

Detailed instructions relative to compliance action are specified on the attached Service Publication; any additional/supplemental data, if necessary, is contained in the following "Special Instructions" section.

Special Instructions:

Make appropriate aircraft log book entry relative to Goodyear Service Bulletin No. FT-77-1 (Rev. B) subsequent to applicable compliance action.



ENGINEERED FABRICS DIVISION
GOODYEAR AEROSPACE CORPORATION
AKRON, OHIO 44315/ROCKMART, GEORGIA 30153

SERVICE BULLETIN

SUBJECT: FUEL SYSTEMS - RECOMMENDED INSPECTION FOR POSSIBLE FUEL SEEPAGE FROM RUBBER-TYPE FUEL TANKS INCLUDING INSPECTION FOR POSSIBLE DETERIORATED OR SOFT RUBBER NIPPLE FITTINGS.

SECTION I - PLANNING INFORMATION

A. EFFECTIVITY:

This Service Bulletin affects the following list of Models of Aircraft and which are equipped with Goodyear Fuel Tanks.

BEECH

35-33
35
36
45 (T34A)
B45
D45 (T34B)
50
95-55
56TC
58
60
65-88
65
70
65-80
65-90
95
99
100
200

CESSNA - SINGLE

180
182
185
205
206
207
210
A188
U206
P206

CESSNA - TWIN

310
T310
320
340
401
402
411
414
404
421

ROCKWELL INTERNATIONAL
GENERAL AVIATION DIVN

500
560
680
681
720
685
690A

PIPER

PA25
PA31-310
PA31-325
PA31P
PA31T
PA34

August 31, 1977

Service Bulletin No. FT-77-1 Rev. B
Page 1 of 4

Ref.: (PAC) VSP-7

A.	<u>EFFECTIVITY:</u> (cont'd)	ROCKWELL INTERNATIONAL	ISRAEL AIRCRAFT
		<u>SABRELINER DIVN.</u>	
		40	1121
		60	1122
		75	1123

1124

AAR OF OKLAHOMA, INC.

680 Extended Range

- B. REASON: To inspect for possible deterioration and fuel seepage from rubber fuel tanks manufactured by Goodyear Aerospace or The Goodyear Tire & Rubber Co.
- C. DESCRIPTION: Aircraft bladder fuel tanks are an assembly of items made up of age sensitive rubbers. These rubbers are subject to deterioration by oxygen, ozone, sunlight, humidity and high temperature conditions that may be experienced in the course of storage or use. Therefore, a regular inspection of this type of fuel tank is warranted.
- D. COMPLIANCE: For aircraft affected, which incorporate Goodyear fuel cells or tanks that are five years old or older, Goodyear recommends a preflight inspection for signs of fuel seepage. Seepage due to tank leakage is usually found around drains and vent lines. If tank leakage is found, perform the inspection in Section II.
- E. APPROVAL: This bulletin has FAA approval.
- F. REFERENCE: Goodyear Aerospace Corporation
Fuel Tank Repair Manual AP 368

SECTION II - ACCOMPLISHMENT INSTRUCTIONS

A. INSPECTION AND/OR CHECK:

Inspection

1. Drain fuel tank and remove access plates.
2. Inspect the interior of each tank where seepage is suspected for cracking, porosity, or other signs of deterioration. Repair or replace fuel tank as necessary.
3. Ascertain that the tank retaining fasteners are properly positioned and fastened.
4. Inspect vent, drain and interconnect nipples. These may be inspected by the fingernail test to give an indication of the condition of the nipple.

The fingernail test consists of using the fingernail to attempt to scrape the rubber off the nipple fitting (see Figure 1). If the rubber has not degraded, the fingernail will glide across the rubber without damage to the rubber. If an unsatisfactory condition exists, the fingernail will dig into the rubber. The rubber will have a consistency of either art gum or chewing gum. Usually the deteriorated rubber will have changed from a light tan color to a dark reddish-brown or greenish color depending upon color of fuel used.

5. Any fuel tank found seeping or with soft nipples should be replaced.
6. Reinstall fuel tank, fuel system and access plate and functionally check the fuel system.

NOTE: Advisory circular AC 43.13-1A, Page 282, also gives information concerning fuel cell inspection.

August 31, 1977

Service Bulletin No. FT-77-1 Rev. B
Page 3 of 4

A. INSPECTION AND/OR
CHECK: (cont'd)



FIGURE 1

August 31, 1977

Service Bulletin No. FT-77-1 Rev. B
Page 4 of 4

Ref.: (PAC) VSP-7