

SERVICE



LETTER

Service Letter No. 216-A

December 14, 1953

TO: All Distributors, Dealers, Operators and Owners

SUBJECT: Replacement of Aileron Hinge Bearing Blocks Part No. 10921

MODELS AFFECTED: All Models


This letter is a correction to Service Letter Number 216.

It has been brought to our attention that dural rivets are being used when replacing the aileron hinge bearing block part number 10921-00 in the aileron hinge bracket.

We would like to advise that the rivets used in the original aileron hinge bracket assembly were 1/8" x 15/16" round head soft steel rivets and all replacement rivets must be of the same material. Any repairs made utilizing the dural rivets are unauthorized and all dural rivets must be removed and replaced with the soft steel round head rivets, 1/8" x 15/16".

Very truly yours,

PIPER AIRCRAFT CORPORATION


Rolland Boardman
Service Manager

RB:lh

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.