

SERVICE



LETTER

Service Letter No. 312

November 24, 1958

TO: All Distributors and Certified Service Centers

SUBJECT: Tooling - Piper AutoControl

MODELS AFFECTED: PA-22, PA-23 and PA-24

The following listing covers tooling and equipment required for proper servicing and installation of the Piper AutoControl units:

| <u>Part No.</u> | <u>Nomenclature</u> | <u>Unit Price</u> |
|-----------------|---|-------------------|
| 754 212 | *Kit - Pilot Tool (For drilling a 1/4" hole in the aileron control shaft on Comanche airplanes serial numbers 24-1 to 24-102 inclusive. This drilling operation required when accomplishing field installations reference paragraph C2 of Comanche installation instructions | \$ 1.81/ |
| 751 412 | Testing Equipment with Cables | \$90.00/ |
| 21827-00 | Tool - Servo Shaft Installation (For use when accomplishing field installation of Piper AutoControl in the Comanche aircraft - reference paragraph C3 of installation instructions. | \$ 1.60/ |

* This tool may be purchased outright or secured on a loan basis. Full credit to be issued upon its return to the factory duly authorized by a Warranty and Credit Claim form.

Very truly yours,

PIPER AIRCRAFT CORPORATION

A handwritten signature in dark ink, appearing to read "Robert Martin".
Robert Martin
Parts Manager

RM:mm

PIPER AIRCRAFT CORPORATION, LOCK HAVEN, PA., U. S. A.