



SERVICE No. 386 BULLETIN

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

"FAA DOA EA-1 Approved"

September 11, 1973

Subject: Circuit Protector Panel Moisture Shield Installation

Models Affected: Serial Numbers Affected:
Only aircraft listed below with factory installed pilot's door are affected:
PA-31 Navajo 31-752 to 31-7300923 incl.
PA-31-350 Navajo Chieftain 31-7305005 to 31-7305055 incl.

Compliance Time: Within the next fifty hours of operation.

Purpose: To provide material and instructions to install a moisture shield behind the circuit protector panel and to apply sealant to the pilot door frame, both of which will assist in excluding moisture which could affect the circuit protectors.

The sketch on the reverse side of this bulletin generally illustrates the location of the moisture shield.

Instructions: Contained in Circuit Protector Moisture Shield Installation Kit, Piper Part No. 760 772.

Material Required: One (1) each per aircraft (with production installed pilot's door only) Circuit Protector Moisture Shield Installation Kit, Piper Part No. 760 772.

Availability of Parts: Your Piper Dealer.

Effectivity Date: This Service Bulletin is effective September 24, 1973.

Summary: Please contact your Piper Dealer to make arrangements for compliance with this Service Bulletin in accordance with Compliance Time, above. Material and five (5) hours labor is provided free of charge by your Piper Dealer for a period of time not to exceed six months from Effectivity Date providing the installation is accomplished by a Piper Dealer.

A Service Publication Compliance/Credit Request form is enclosed with copies of this service release mailed to owners of record; subsequent to compliance with the provisions of this Service Bulletin, owners must complete the form per instructions on the reverse side of the form and leave the form with the Piper Dealer performing the modification.

