



SERVICE LETTER

No. 886

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

FAA Approved

January 6, 1981

M

Subject:

Master Switch Replacement

Models Affected:

PA-31/PA-31-325 Navajo
PA-31-350 Chieftain

Serial Numbers Affected:

31-842 through 31-8012041
31-5001 through 31-8052097

Compliance Time:

At owner/operator's discretion; recommended
at the next scheduled maintenance event.

Purpose:

On the above-listed aircraft, in some climates and weather conditions, moisture could accumulate in the master switch and cause the switch to activate in the OFF position, permitting the battery to discharge.

This Service Release announces the availability of a kit which contains environmentally sealed left and right switches along with all material and instructions necessary for installation.

Instructions:

All instructions are included in Master Switch Replacement Kit, Piper Part Number 764 090.

Material Required:

One (1) each per aircraft, Kit-Master Switch Replacement (Environmentally Sealed Switches), Piper Part No. 764 090.

Availability of Parts:

Your Piper Field Service Facility.

Effectivity Date:

This Service Release is effective upon receipt.

Summary:

Please contact your Piper Field Service Facility to arrange for installation of the above described kit.
