

FAA APPROVED



S.A. 31-1
June 15, 1982

To: All Piper Distributors and All Affected Owners

Subject: Nayak Fuel Vent System Modification

Models Affected:

PA-31-325 Navajo C/R
PA-31-350 Chieftain

Serial Numbers Affected:

31-8112013, 31-8112014, 31-8112037,
31-8152001, 31-8152013, 31-8152017,
31-8152024, 31-8152037, 31-8152042,
31-8152047, 31-8152056, 31-8152059,
31-8152061, 31-8152062, 31-8152067,
31-8152068, 31-8152074, 31-8152077,
31-8152080, 31-8152086, 31-8152092,
31-8152097

NOTE: The above aircraft were manufactured with optional Nayak nacelle fuel systems. Only these aircraft are affected by this Service Release.

Compliance Time: At owner/operators discretion; recommended at the next scheduled maintenance event.

Purpose: The fuel vent system has shown a tendency to siphon fuel overboard when expansion takes place or after short, abrupt taxiing turns are made.

This Service Release announces the availability of a Fuel Vent System Modification Kit, which includes a check valve to retain fuel.

Instructions: Instructions are contained in Piper Kit Part Number 764 373.

Material Required: One (1) each per aircraft, Nayak Fuel Vent System Modification Kit, Piper Part Number 764 373.

Availability of Parts: Your Piper Field Service Facility.

Effectivity Date: This Service Release is affective upon receipt.

Summary: Please contact your Piper Field Service Facility to arrange for installation of Kit 764 373. Credit is available for material and labor for all above-listed aircraft. Comply with Product Condition/Compliance Report procedure.

Any applicable factory participation remains in effect for a period of time not to exceed 180 days from the date of this release.