



SERVICE BULLETIN / SERVICE LETTER

INDEX

THE NEW PIPER AIRCRAFT, INC.

Published by
Technical Publications

©The New Piper Aircraft, Inc.
2926 Piper Drive
Vero Beach, Florida 32960
U.S.A.



Member
General Aviation
Manufacturers Association

AEROFICHE EFFECTIVITY

The current effective card set for the Service Bulletin and Service Letter Aerofiche (P/N 1762-331), originally issued November 1, 1987, is as follows:

<u>AEROFICHE CARD</u>	<u>SUBJECT</u>	<u>REVISION DATE</u>
1	INDEXES	03/01/04
2	Service Bulletins 1 thru 190A	06/04/02
3	Service Bulletins 191 thru 320A	06/04/02
4	Service Bulletins 321A thru 436	09/27/00
5	Service Bulletins 437A thru 539	06/04/02
6	Service Bulletins 540A thru 630A	03/10/97
7	Service Bulletins 631B thru 709	12/01/03
8	Service Bulletins 710 thru 789A	03/09/01
9	Service Bulletins 790A thru 852	02/10/95
10	Service Bulletins 853 thru 913A	08/14/97
10a	Service Bulletins 914 thru 973	06/04/96
10b	Service Bulletins 974 thru 1035	10/01/99
10c	Service Bulletins 1036 thru 1099	03/01/04
10d	Service Bulletins 1100A thru Latest	03/01/04
11	INTENTIONALLY BLANK	09/01/03
12	INTENTIONALLY BLANK	09/01/03
13	Service Letters 32 thru 367	11/01/87
14	Service Letters 368 thru 520	10/01/89
15	Service Letters 522 thru 626	11/01/87
16	Service Letters 627 thru 738A	11/01/87
17	Service Letters 739 thru 854	11/01/87
18	Service Letters 855 thru 958	03/12/96
19	Service Letters 959 thru 1052	06/01/03
20	Service Letters 1053 thru Latest	03/01/04

Revised cards are identified by the date on the card header. Revised cards are direct replacements for cards of the same number which carry an earlier date. Card numbers followed by a small letter shall be inserted in direct sequence after the same common numbered page. All cards are current until a revised card with a later date is received.

SERVICE BULLETINS / SERVICE LETTERS

This publication comprises the introduction to the Service Bulletins and Service Letters Aerofiche Set (P/N 1762-331) and is also available separately in paper form as P/N 762-332. An annual revision service subscription (P/N 1761-448) is available for the aerofiche only. The paper version is current only at the time it is printed.

The Service Bulletins and Service Letters Aerofiche Set (P/N 1762-331) provides all Piper Service Bulletins and Service Letters released up to the date of the current revision. Bulletins/Letters are arranged on the Aerofiche cards in numerical order (see Aerofiche Effectivity).

INDEXES

The following Service Bulletin Index and Service Letter Index are each arranged by aircraft model number (i.e. - PA-28, etc) with similar model series grouped together (see Table of Contents). Within these series, applicable service bulletins/letters are listed in numerical order. To locate a specific bulletin or letter, select the appropriate index and then locate the affected aircraft series grouping. Bulletins/letters which apply are listed therein and are identified by Subject, Model(s) Affected, and the Issue Date of the Service Bulletin/Letter. Additionally, the index may list part or kit numbers and related A.D. numbers. The Air Transport Association Code (ATA Spec. 100) is provided to assist in maintenance record keeping and researching publications. The last column on the right gives the Aerofiche Grid Number, specifying the Aerofiche card number and the grid location of the actual Service Bulletin/Letter on that card.

Explanation of Grid Numbers:

The first number is Aerofiche card number (i.e. 1 thru 19). The letter is the row running horizontally across the aerofiche card (i.e. - A thru L). The second number is the column running vertically up and down the aerofiche card (i.e. - 1 thru 24).

Example: 2J16 = Aerofiche card number 2; row J; column 16.

NOTES

1. Airworthiness Directives referred to by number in the A.D. No. column and A.D. numbers listed on the service release are those which applied at the time this listing was compiled. Refer to the latest FAA Bi-weekly listing for current A.D. information.
2. When ** appears in the Part/Kit No. column, material requirements are too extensive to be listed in the index; refer to the appropriate service release for material identification.
3. When Part/Kit No. and/or A.D. No. column is left blank, no material and/or Airworthiness Directive is involved.
4. Airworthiness Directives may be issued without an associated service release; therefore, refer to Airworthiness Directive Listings issued by the FAA to determine all Airworthiness Directives applicable to an aircraft.
5. Type Certificates (TC's) for the following aircraft models are not held by Piper: AE-1, HE-1, J5A, J5A-80, J5B, J5C, L-14, PA-12, PA-12S, PA-14, PA-25, PA-60, and Stinson 108-3. See Supersession List for affected service bulletins / letters. The current TC holder(s) may be identified through the FAA (see the "Regulatory and Guidance Library" at <http://www.faa.gov/avr/air/airhome.htm>).

SERVICE BULLETINS / SERVICE LETTERS INDEXES

TABLE OF CONTENTS

<u>SUBJECT</u>	<u>GRID NO.</u>
Supercession List	1A6

SERVICE BULLETINS

Classic Aircraft (B-2 thru PA-22)	1A7
PA-23, PA-23-250	1A15
PA-24, PA-30/39	1B1
PA-28, PA-28R, PA-44/PA-44T	1B5
PA-31-300/310/325, PA-31-350, PA-31P, PA-31P-350	1C1
PA-31T/31T1, PA-31T2/31T3, PA-42	1C13
PA-32 Series	1D1
PA-34-200/200T/220T	1D11
PA-36	1D17
PA-38-112	1D21
PA-46-310P, PA-46-350P, PA-46-500TP	1E1

SERVICE LETTERS

Classic Aircraft (B-2 thru PA-22)	1G1
PA-23, PA-23-250	1G7
PA-24, PA-30/39	1G15
PA-28, PA-28R, PA-44/PA-44T	1H1
PA-31-300/310/325, PA-31-350, PA-31P, PA-31P-350	1H11
PA-31T/31T1, PA-31T2/31T3, PA-42	1I1
PA-32 Series	1I7
PA-34-200/200T/220T	1I13
PA-36	1J1
PA-38-112	1J3
PA-46-310P, PA-46-350P, PA-46-500TP	1J5

SUPERCESSION LIST

The following service bulletins / letters have been superseded or are no longer maintained by Piper, as indicated. (See Note 5.)

<u>Superseded / Obsolete Pub</u>	<u>New Pub or Reason</u>	<u>Superseded / Obsolete Pub</u>	<u>New Pub or Reason</u>	<u>Superseded / Obsolete Pub</u>	<u>New Pub or Reason</u>	<u>Superseded / Obsolete Pub</u>	<u>New Pub or Reason</u>
SB 0005	Obsolete	SB 0101	PA-12	SB 0756	PA-60	SL 0331	PA-25
SB 0006	Obsolete	SB 0102	PA-12	SB 0757	PA-60	SL 0332A	PA-25
SB 0010	Obsolete	SB 0105	PA-12/14	SB 0761	PA-60	SL 0335	PA-25
SB 0011	Obsolete	SB 0106	PA-12/14	SB 0770	PA-60	SL 0337	PA-25
SB 0012	Obsolete	SB 0107	PA-12	SB 0793	SB 0809	SL 0342	PA-25
SB 0013	Obsolete	SB 0109	PA-12/14	SB 0815	PA-60	SL 0343	PA-25
SB 0014	Obsolete	SB 0114	STINSON 108-3	SB 0818	PA-60	SL 0344	PA-25
SB 0015	Obsolete	SB 0115	STINSON 108-3	SB 0830	PA-25	SL 0351	SB 0354B
SB 0016	Obsolete	SB 0137	SB 0140	SB 0832	PA-60	SL 0357A	PA-25
SB 0017	Obsolete	SB 0141	SB 0354B	SB 0864	SB 1008	SL 0361	PA-25
SB 0019	Obsolete	SB 0147	Obsolete	SB 0878	PA-25	SL 0376	PA-25
SB 0020	Obsolete	SB 0154	Obsolete	SB 0894	SB 1087	SL 0377	PA-25
SB 0022	Obsolete	SB 0170	Obsolete	SB 0902	PA-60	SL 0383	PA-25
SB 0024	Obsolete	SB 0204	PA-25	SB 0908	PA-60	SL 0385	PA-25
SB 0025	Obsolete	SB 0206	PA-25	SB 0909	SB 0913A	SL 0387	PA-25
SB 0026	Obsolete	SB 0215	PA-25	SB 0918	PA-60	SL 0392	SB 0924
SB 0027	Obsolete	SB 0217	PA-25	SB 0920	PA-60	SL 0399	PA-25
SB 0029	Obsolete	SB 0221	PA-25	SB 1096	Not Used	SL 0403	PA-25
SB 0030	Obsolete	SB 0227	SB 0230A	SB 1112	Not Used	SL 0455	PA-25
SB 0031	J5A/B/C	SB 0241A	PA-25	SB 1115	Not Used	SL 0463A	PA-25
SB 0032	Obsolete	SB 0247	PA-25	SB 1116	Not Used	SL 0468A	PA-25
SB 0033	Obsolete	SB 0298 (portions)	SB 0312	SB 1129	Not Used	SL 0479	PA-25
SB 0034	J5A/B/C	SB 0318A	SB 0343	SB 1142	Not Used	SL 0493	Obsolete
SB 0037	Obsolete	SB 0328	PA-25			SL 0515	PA-25
SB 0038	Obsolete	SB 0341	PA-25			SL 0536	PA-25
SB 0039	Obsolete	SB 0366	SB 0456A			SL 0563	PA-25
SB 0041	Obsolete	SB 0371	SB 0456A			SL 0570	SB 0343
SB 0051	Obsolete	SB 0372B	SB 0446A			SL 0586	PA-25
SB 0052	Obsolete	SB 0377	SB 0456A			SL 0588	SB 0840 - PT1
SB 0054	SB 0083	SB 0378	SB 0456A			SL 0590	SB 0840 - PT2
SB 0057	Obsolete	SB 0388	SB 0456A			SL 0597	SB 0965
SB 0059	Obsolete	SB 0410	PA-25			SL 0601	SB 0356
SB 0060	J5A/B/C	SB 0413	SB 1123			SL 0604	SB 0531
SB 0062	Obsolete	SB 0414	PA-25			SL 0632	PA-25
SB 0064	Obsolete	SB 0416	SB 0446A			SL 0640	PA-25
SB 0067	Obsolete	SB 0426	PA-25			SL 0646	PA-25
SB 0069	Obsolete	SB 0457	SB 0479B			SL 0702	PA-25
SB 0070	Obsolete	SB 0532	PA-25			SL 0703	Obsolete
SB 0087	J5A/B/C	SB 0551A	PA-25			SL 0721A	PA-25
SB 0090	PA-12	SB 0605	Obsolete			SL 0724	PA-25
SB 0092	PA-12	SB 0687	SB 1007			SL 0728	PA-25
SB 0093	PA-12	SB 0698A	SB 0811A			SL 0799	SB 0955
SB 0094	PA-12	SB 0720	PA-60			SL 0812	PA-25
SB 0096	PA-12	SB 0735	PA-25			SL 0953	SB 0896
SB 0097	PA-12	SB 0743	PA-60			SL 0955	SB 0868
SB 0098	PA-12	SB 0746A	PA-60			SL 0980	SB 0908
SB 0100	PA-12	SB 0750	PA-60			SL 1068	Not Used
		SB 0755	PA-60			SL 1070	Not Used
						SL 1071	Not Used
						SL 1073	Not Used

NOTE: The above list is not all inclusive. Additionally, it does not include supersessions by a normal (i.e. - A, B, C, etc.) revision within the same SB/SL number.

REVISED: 03/09/01

CLASSIC AIRCRAFT: B-2/E-2/F-2/
J-2/J-3/J-4/L-21/L-18/PA-11/
PA-15/PA-16/PA-17/PA-18/PA-19/
PA-20/PA-22

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1	How to Rig Cub E2, J2, J3 Airplanes	E2, J2 & J3	02/15/46				2A1
2	Special Tubing in Fuselage	All Models Manufactured thru December 1945	02/15/46				2A2
3	Nose Heavy Condiflon	All Models Manufactured thru December 1945	02/15/46				2A3
4	Maintenance of Fuel System	All Models Manufactured thru December 1945	02/15/46				2A4
7	Reinforcement of Stabilizer Yoke	J2	02/18/46				2A5
8	Reinforcement of Stabilizer Yoke	E2 and F2	02/18/46				2A7
9	Tail Surface Bracing	E2, F2 & J2	02/18/46				2A9
18	Replacement Tail Brace Wire Nipples	J2 and J3	02/18/46				2A11
21	Engine Mounting Bolt Failures	J3C-65 Cubs with Continental A50 Engine Installation	02/18/46				2A14
23	Removal of Bug Screen	J4	02/18/46				2A15
28	Electrical Wiring	J4	02/18/46				2A16
35	Reinforcement of Windshield Attachment	J3	02/19/46				2A20
36	Inspection of Motor Mount	J3	11/04/41				2A22
40	Outlet Reinforcement on 12 Gallon Fuel Tanks	J3	02/19/46				2A23
42	Elevator Bungee Installation	J3S	02/19/46				2B1
43	Stabilizer Link Tubes and Rear Support Bearing Bracket	J3	02/19/46				2B3
44	Operation of Airplanes with Enclosure Door Open	J3	02/19/46				2B6
45	Control System Interference	J3	02/19/46				2B7
46	Strainer Attachment Fittings	J3F-50, J3L-50, J3L-55, J4, J4A, J4B, J4D	02/19/46				2B9
47	Preparation for Winter Operation	J3 Series, E2, J2, J3, 40 H.P. (not equipped with Adequate Carburetor Heater.)	02/19/46				2B11
48	Mufflers: 1. Failure of Inner-Baffle End Attachments 2. Inspection 3. Remedial Measures for Preventing Engine Failure	J4A and J4F	02/19/46				2B13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
49	Revised Washer for Fin Brace Rod Clevis	J3	02/19/46				2B16
50	Ribstitching	E2, J2, J3 J4	02/19/46				2B17
53	Fuel Shut-Off Swivel Fitting	J3	02/20/46				2B19
55	Fuel Tank Vents	J4E	02/20/46				2B21
56	Wing Aileron Bellcrank Bracket Failures	J4	02/20/46				2B23
58	Steerable Tail Wheel Shock Cords	All Models Manufactured thru December 1945	02/20/46				2C2
61	Aging of Protective Finish on Wood Wing Spars	J3, J4, L4 and L4A	02/20/46				2C4
63	Stabilizer Aluminum Yoke Casting	J3, L-4, L-4A, L-4B.	02/20/46				2C5
65	Fuel Tank Repairs	J4E	02/20/46				2C7
66	Flexible Hose End Fittings (3/8" Synthetic)	J3, J4	02/20/46				2C10
68	Stabilizer Rear Bearing Bracket	J3	02/20/46				2C11
71	Exhaust Muffler Inspection and Repair	J3, J4 Airplanes Incorporating Exhaust Mufflers.	02/20/46				2C12
72	Rudder Pedal and Floorboard Attachment Lugs	J3	02/20/46				2C13
73	Cockpit Enclosure Modification	L4	02/20/46				2C16
74	Rigging Procedure	J4	02/20/46				2C18
75	Carburetor Heat Control	J3 Airplanes with Carburetor Heat Control	02/20/46				2C20
76	Windshield Replacement	J3 Airplanes with Formed Eyebrow Fairing Tubes.	02/20/46				2C24
77	Seats, Safety Belts and Control Cables	E2, F2, J2, J3	02/18/46				2D4
78	Wing Drag Wire Inspection	E2, F2, H2, J2	02/18/46				2D6
79	Reinforcing of Rib Nose Structure	J4	02/18/46				2D9
80	Fuel Valve Control	J3 and J4 (Except Those with Auxiliary Fuel Tanks Installed.)	02/18/46				2D14
81	Motor Mount Failure	All Models Manufactured thru December 1945	02/20/46				2D17

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

REVISED: 12/12/01

CLASSIC AIRCRAFT: B-2/E-2/F-2/
J-2/J-3/J-4/L-21/L-18/PA-11/
PA-15/PA-16/PA-17/PA-18/PA-19/
PA-20/PA-22

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
82	Safety Wire for Control System Turnbuckles	E2, J2, J3, J4	02/20/46				2D18
83	Tailskid Spring Attachment Reinforcement	E2, J2, J3	02/20/46				2D20
84	Winterization of J3C-65	J3	05/09/46				2E1
85	Reworking of Bottom Cowl for Replacing Airscoop EQ5259 and EQ5370	J3	04/25/46				2E4
86	J3 Lift Struts and Lift Strut Clevis Bolts	J3	10/16/46				2E5
88	Relocation of J3 Scott Brake Cylinders	J3	10/11/46				2E10
89	Replacement of Kem Gasoline Filter Gasket	J3	07/11/46				2E15
91	Inspection of Fuel Strainer Installation	J3	08/06/46				2E17
95	Defective Glass Fuel Strainer Bowls	J3	09/11/46				2E23
99	Header Tank Installation on PA-11 Airplanes	PA-11	07/29/47				2F6
103	Shock Strut Stop Discs	J3, PA-11	10/20/47				2F20
104	Fuel Line Fitting	PA-11	01/30/48				2F21
108	Model PA-11 Front and Rear Seats	PA-11	10/20/48				2G6
110	Windshield Attachment	PA-15	11/29/48				2G11
111	Torque Tube Connector Tube Assembly	J3, PA-11	03/14/49				2G12
112B	Service Inspection Notes	J3, J4, PA-11 PA-15, PA-16, PA-17	11/19/59				2G13
113	Weight and Balance Form	PA-11	05/03/49				2G16
116	Battery Box Lid	PA-20, 22	03/09/51				2G17
117B	Chafing of Master Switches	PA-20, 22	04/14/52				2G19
118	Battery Box Lid Modification	PA-16-,20,22	09/21/51				2G20
119	Freezing of Nose Wheels	PA-22	11/07/51				2G21
120	Replacing of Front and Rear Lift Strut Forks and Barrels	J3, PA-11	03/28/52				2G24

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
121	Oil Radiator Lines	PA-18, PA-18A, PA-20, PA-22-135 Models	08/25/52				2H3
122	Fuel Grade Specification Lycoming O-290-D2	PA-18, PA-18A, PA-18S PA-20, PA-22	11/21/52				2H4
123	Front Spar Interference	PA-20, 22	05/07/54				2H5
124	PA-22 Landing Gear	All PA-22's	08/30/54				2H6
135	Fuel Selector Valve Pointer	PA-20, 22	03/29/55				2I1
143	Magneto Ground Wire Terminal Attachment Fitting	J-Series, E-Sedes, PA-11, PA-15, PA-16, PA-17, PA-18, PA-19, PA-20, PA-22	10/07/55				2I12
148A	Fuel Tank Caps	PA-18,18A 22, 23, L21 B	05/29/57				2I17
153A	Brake Master Cylinder Diaphragm	PA-22	11/21/60	750-384		3240	2J1
157D	Lift Strut Fork Inspection And/Or Replacement	J-2/J-3/NE-1/ L4/J4/PA-11/ PA-15/PA-16/PA-17/ PA-18/L-21A/L-21B/ L-18/PA-19/PA-20/ PA-22	04/22/86	**		5701	2J5
158	All PA-20 Name Plates	PA-20	09/20/57				2J8
161A	Fire Hazard	PA-16, 20, 22	09/23/59	**	57-22-01	2600	2J12
163A	Fusing Of Cigar Lighter Circuit	PA-20, 22	07/07/58		58-16-01	3310	2J16
165	Aileron Hinge Reinforcing Bracket	J3, L4, L18B, PA-11, PA-15, PA-16, PA-17	05/22/58	**	58-12-02	5750	2J22
166	Chafing of Master Switch Wires	PA-22	08/05/58				2J24
174B	Fabric, Fuselage, Inspection and Maintenance Of In Area of Windshield Top Attachment Channel	J4, PA-15/16/17 PA-20 PA-22	11/30/61			5300	2K15
181	Cables, Control. 1/8" - 7 x 19 Flexible Stainless Steel, Replacement of	PA-18/18A/18S PA-18AS-150 PA-22/22S PA-22S-150 PA-22	11/05/59	**	61-16-05	2700	2L4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

REVISED: 06/04/02

CLASSIC AIRCRAFT: B-2/E-2/F-2/
J-2/J-3/J-4/L-21/L-18/PA-11/
PA-15/PA-16/PA-17/PA-18/PA-19/
PA-20/PA-22

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
182	Foreign Registered Airplanes- Inspection Of Control Cables And Replacement of 1/8" - 7 x 19 Flexible Stainless Steel Control Cables	J3/ PA-11/11S/15/16/ 16S/17/18/20/20S/ 20-115/20-135/22/ 22S-135/22-150/ 22S-160, L-4/L-18B/L-18C/ L-21A/L-21B/ L-21B Modified	11/05/59			2700	2L10
183	Tie Rods - Tail Brace Streamline	PA-20, PA-22, PA-22-135/150/160	11/09/59		60-01-07	5340	2L12
184	Safety Belt Attachment	PA-22-150/160	12/09/59	754-273	60-05-03	5340	2L13
198	Clevises, Tail Brace, Replacement of	PA-22-108	01/06/61	754-381		5510	3A13
203	Modification Of Cabin Heat Box Plate	PA-22-108	04/21/61	**		2140	3B1
207A	Rudder Pedal Assembly, Inspection of Weld (P/N 40892-04 And 05)	PA-18, PA-18A	05/10/62		62-02-05	2720	3B7
218	Vacuum Pump Spined Coupling, Replacement	PA-18 PA-22-108	11/11/63	**		3710	3C9
250A	Installation Of Right Fuel Tank Quantity Gauge Placard	PA-22	01/29/70	15306-00	67-24-02	2840	3F8
264	Aircraft Flight Manual Supplement, Revision To	PA-22S-135	12/22/67			PARA 15.0	3G10
305	Inspection Of Carburetor Drain Plugs	PA-18-150	11/25/69			7310	3K12
324	Vacuum Pump Adapter Drive Assembly	PA-18-150	09/24/70			3710	4A9
351	Fuel Line Replacement	PA-20	04/03/72	**	72-21-03	2820	4D9
354B	Fuel Selector Valve Lubrication	PA-18/PA-20 PA-22	05/19/82	**		2820	4D15
445	Fuel Cap Inspection	PA-18	01/24/75	454-039		2810	5A20
485	Rerouting of Rudder Control Cables	PA-18-150	01/27/76	**		2720	5F2
522	Fuel Tank Cap Modification, Wing	PA-11, PA-16, PA-18/18-150 PA-20, PA-22	09/28/76		78-10-03	2810	5J4
528D	Wing Lift Strut Assembly Inspection/Replacement	J-2/J-3/NE-I/ L-4/J-4/PA-11/ PA-15/PA-16/PA-17/ PA-20/PA-22	10/19/90	**	99-26-19 99-01-05	5701	5J21
573	Fuel Tank Cap Modification, Wing	PA-11, PA-16, PA-18/18-150, PA-20, PA-22	02/08/78		78-10-03	281	6E14

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
630A	Collins VIR-350 And VIR-351 Navigation Receiver Modification	PA-18-150	02/25/80			3450	6L14
677	Publications for Aircraft Operation	All Piper Models	05/20/80			PARA 15.0	7H4
706B	Tail Brace Wire Support Installation	PA-18-150	10/09/91	**	81-06-08	5510	7L7
759	Exhaust Muffler Inspection and Modification, Piper Part Number 12433-00, 12433-14, 12232-00	PA-18	06/22/83	452-093		7820	8H12
771	Parking Brake Application	PA-20, PA-22	05/19/84	81090-02		1130	8J1
819	Fuselage Door Frame Tube Corrosion: Repair and Protection	J-4/PA-15/ PA-16/PA-17/PA-20/ PA-22	02/28/86	**		5300	9G13
836A	Aluminum Wire Inspection	E-2/J-2/J-3/NE-1/ L-4/J-4/PA-11/ PA-15/PA-16/PA-17/ PA-18/PA-19/PA-20/ PA-22	08/26/86	**		2400	9J4
855	Use of Automobile Gasoline In Piper Aircraft	All Piston Powered Models	01/14/87	N/A		2800	10A7
868	Forward Fuel Header Tank Installation	PA-11, PA-18	08/19/87	60763-02		2810	10C3
910A	Wing Lift Strut Assembly Inspection	PA-18/18A/L-18/ PA-19/L-21A/L-21B	10/10/89	**	99-26-19 99-01-05	5701	10L3
924	Shimmy Dampener Replacement	PA-22	09/13/89	21701-06		3250	10aB17
935	Relocation of Aircraft Serial Number Data Plate	PA-18-150	03/13/90	765-400		1125	10aE5
966	Tail Surfaces Replacement	PA-18-150	01/24/94	**		5500	10aK3
979	Installation of Fuel Cap Cover	PA-18-150	01/12/95	**		5500	10bB6
1020	Inspection of the Artex 110-4 ELT and ELT Attachment Bracket	PA-18-150	07/10/98	**		2563	10b111
1026	Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings".	PA-18 PA-18-150 PA-22	11/05/98	753-910		3711	10bJ20
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements".	PA-18/18A/18S PA-18-150 PA-20/20S PA-22/22S	09/25/00	**		3714	10cB1
1044	Lift Strut Attachment Fitting Inspection Access Provision and Wing Component Corrosion Inspections.	E-2/F-2/TG-8 J-2/J-3/J-4/ PA-11/ PA-15/PA-16/PA-17/ PA-18/PA-19/PA-20/ PA-22	07/27/00	481-096		5701	10cB19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

REVISED: 03/0901

SERVICE BULLETIN INDEX

CLASSIC AIRCRAFT: B-2/E-2/F-2/
J-2/J-3/J-4/L-21/L-18/PA-11/
PA-15/PA-16/PA-17/PA-18/PA-19/
PA-20/PA-22

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1048	Stainless Steel Control Cables	PA-18-150	01/03/01	N/A		2702	10cC9

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

CLASSIC AIRCRAFT: B-2/E-2/F-2/
J-2/J-3/J-4/L-21/L-18/PA-11/
PA-15/PA-16/PA-17/PA-18/PA-19/
PA-20/PA-22

REVISED: 03/09/01

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

THIS PAGE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
125	Fuel System Model PA-23	PA-23	09/29/54				2H7
126	PA-23 Power Plant	PA-23	10/18/54				2H9
127	PA-23 Airplane Flight Manual	PA-23	10/15/54				2H11
128	PA-23 Landing Gears	PA-23	10/28/54				2H12
129	Carburetor Air Box	PA-23	12/28/54				2H13
130	Heater Fuel Line	PA-23	12/31/54				2H14
131	Addition of Rudder Extrusion Chafe Strip to Wing Root Fairing	PA-23	01/03/55				2H15
132	Fuel Valve Actuator Handle Locks	PA-23	01/05/55				2H17
133	Landing Gear Down Lock Latches	PA-23	01/18/55				2H19
134	Main Landing Gear Attachment Point	PA-23	03/31/55				2H22
136	Hydraulic System - Thermal Relief Valve	PA-23	04/26/55				2I3
137	Landing Gear CO2 Extension System	PA-23	04/26/55				2I4
138	Hydraulic Actuating Cylinders	PA-23	05/09/55				2I6
139	Flexible Fuel Valve Controls - right and left	PA-23	05/26/55				2I7
140	Landing Gear CO2 Extension System	PA-23	06/08/55				2I8
142	Wing Front Spar Attachment Fitting	PA-23	10/04/55				2I11
143	Magneto Ground Wire Terminal Attachment Fitting	PA-23	10/07/55				2I12
144	Hot Air Ducts	PA-23	11/11/56				2I13
145	New Anti-Retracton Device	PA-23	12/31/56				2I14
146B	Elevator Butt Rib And Torque Tube Attachment Casting Cracks	PA-23	10/25/62		63-12-02	5520	2I15
149	Reinforcement of Aileron Balance Weights	PA-23	12/10/56				2I19
150	Front Stabilizer Fittings - right and left	PA-23	12/21/56				2I21
151	Elevator Push Pull Tube Rollers	PA-23	02/11/57				2I22
152A	Oil Pressure Line	PA-23	08/29/58	17766-07	57-10-02	7930	2I24
155B	Empennage Casting Cracks	PA-23	10/28/63			5500	2J2
156	Thread Exposure on the Heim Rod End Bearing	PA-23	07/02/57				2J4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
159	Rudder Trim Tab Control Rod Attachment	PA-23	10/01/57				2J9
160	Stabilizer Attachment Fitting	PA-23	10/07/57	17093-00		5510	2J11
162	Rudder Trim Tab Adjustment Screw, Part No. 18453-00	PA-23	02/17/58	18453-02	58-04-03	2720	2J15
169	Placard, Operating Limitations	PA-23	02/04/59	754-224	59-08-03	1100	2K3
175	Circuit Protector, Starter Solenoid	PA-23	06/09/59	754-220	60-03-07	2400	2K17
176	Bellcrank Attachment, Elevator Control Tube	PA-23/23-160	07/03/59	**		2730	2K18
185A	Ribs, Wing Stations 95 And 110 Located Below the Main Wing Fuel Cell	PA-23/23-160	09/06/63	**		5710	2L14
186	Fuel Lines And Fuel Line Fittings, Replacement Of	PA-23-250(6)	04/12/60	492-222 492-223		2810	2L16
188	Baggage Compartment Doors, Positive Locking Of	PA-23-250	05/12/60			5230	2L19
189	Stabilator Tab Horn Modification	PA-23-250	06/22/60	754-329		2740	2L21
194	Instrument Panel Face Plate, Replacement Of	PA-23	08/16/60			2500	3A7
195A	Baffles, Right Engine, Modification Of	PA-23-250	05/12/60	754-335		7230	3A8
196	Rudder Tab Horn Bolt Installation	PA-23-250	09/09/60	754-344		2720	3A10
199A	Stabilator Tab Horn Assembly, Inspection Of	PA-23-250	04/03/61	754-393		2740	3A15
200	Oil Radiator Lines, Replacement Of	PA-23-250	04/18/61	754-387		7920	3A19
213	Rudder Trim Tab Horn, Inspection Of	PA-23/23-160	03/05/63			2720	3B23
214	Carburetor Airbox Throat Vanes, Removal Of	PA-23-235/23-250	04/19/63			7160	3C1
218	Vacuum Pump Spined Coupling, Replacement Of	PA-23-235/23-250	11/11/63	**		3710	3C9
219A	Heater, 940DB, Modification And Rewiring Of	PA-23-250	09/23/64	**		2140	3C12
225	Vacuum Pump Mounting Gasket, Replacement Of	PA-23-235/23-250/ E23-250	11/09/65	751-886		3710	3D12
226	Vacuum Pump Drive Couplings, Replacement Of	PA-23-235/23-250/ E-23-250	12/20/65	**		3710	3D13
230A	Alternate Air System Modification, Engine Induction	PA-23-250/ E23-250	05/06/66	757-021	66-18-03	7160	3D21
242	Fuel System, Modification Of	PA-23-250/ E23-250	01/09/67	757-106		2800	3E17
243	Starter Vibrator, Replacement Of	PA-23-250 E23-250	01/06/67	757-103		8010	3E18
269	Manifold Pressure Gauge Line Filter	PA-23-250	02/23/68	760-167		7710	3G19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
273	Tailpipe, Turbocharger, Clearance To Firewall, Inspection Of	PA-23-250 PA-E23-250	05/06/68	**		8120	3H1
280	Artificial Horizon, R.C. Allen 3", Case Leakage Of	PA-23-250	07/10/68			3420	3H20
290	Fuel Flow Gauge Assemblies, Replacement Of	PA-23-250"D"	05/23/69	760-293		7330	3J3
296	Fuselage Aft Section Assembly, Inspection Of	PA-23-250"D"	05/26/69	760-324		5310	3J16
300	Hydraulic Pump Hose Assembly Inspection	PA-23-250	06/03/69	17766-05		2910	3K3
303	Autocontrol III And Altimatic III Series Roll Servo Modification and Roll Bridle Cable Replacement	PA-23-250 PA-E23-250	11/10/69	760-364		2210	3K8
306	Alternator System Modification	PA-23-250(6)"D"-	01/09/70	760-346	70-22-05	2430	3K14
319	Exhaust System Inspection And Modification	PA-23-250(6)	04/19/71	33178-02 33178-03	72-14-05	7810	3L17
320A	Autopilot Servo And Bridle Cable Installations, III Series, Inspection Of	PA-23-250(6)	07/06/72			2210	3L23
324	Vacuum Pump Adapter Drive Assembly	PA-23-250	09/29/70			3710	4A9
331	Electric Trim Switch Inspection And Modifications	PA-23-250(6)	02/05/71	760-505	71-12-05	2730	4B3
334	Alternate Air Hose Replacement	PA-23-250(6)T	03/17/71	48076-02	71-21-06	7160	4B14
335A	Engine Controls Support Bracket Assembly Inspection	PA-23 PA-23-160 PA-23-250	11/17/71	16975-00	71-12-01	7610	4B16
340	Fuel Cell Vent/Drain Lines	PA-23 PA-23-160/-235 PA-23-250 PA-23-250(6)	05/24/71		88-21-07	2810	4C2
345	Bunges Installation, Stabilator	PA-23-250(6)	10/07/71	760-565	72-21-07	2740	4C21
349	Master Switch Modification, Electrical System	PA-23-250(6)	04/26/72	760-602 760-606		2450	4D5
353	Fuel Filter Assembly Outlet Port, Inspection Of	PA-23-250(6)	06/01/72	**		7310	4D13
375	Firewall Sealing, Lower	PA-23-250(6)	06/20/73	757-758		5310	4F15
380	Pitch Servo Bridle Cable Installation, Revised	PA-23-250(6)	07/09/73			2210	4F23
385	Wing Leading Edge Modification	PA-23-250(6)	05/04/73	**		5720	4G10
389	Bridle Cables and Bridle Cable Clamp Installation	PA-23-250(6)	08/13/73			2210	4G17
401A	Heater Fuel Valve, Inspection Of	PA-23 PA-23-160/-235 PA-23-250 PA-23-250(6)	05/16/00	19460-00	74-22-05	2148	4H24

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
404	Flux Sensor Caution Placard Installation	PA-23-250(6)	11/12/73	33564-00		3420	4I11
408B	Flap Outboard Hinges, Replacement	PA-23-250(6)	05/14/75	**	74-10-01	5750	4I24
441	Manifold Pressure Hose Clamping Of	PA-23-250(6)	01/02/75	760-602 760-606		7710	5A12
451	Throttle Control Shaft, Inspection Of	PA-23-250(6)	02/26/75			7610	5B14
452	Instrument Glare Shield Panel Replacement	PA-23-250(6)	03/03/75	760-932	75-11-05	2510	5B16
455	Fuel Selector Valve Inspection	PA-23-250(6)	04/30/75	492-222 492-223		2820	5B20
456A	Warning Placard Replacement	PA-23-250(6)/ 23-250(6) "B" PA-E23-250(6)	05/28/75	**		2840	5B24
461	Encoding Altimeter Harness Rewiring	PA-23-250(6)	04/17/75	760-971		3410	5C10
486	Wing Tip Navigation Light Wire Insulation	PA-23-250(6) "F"	10/11/76	761-099	77-01-05	3340	5F5
493	Magnetic Compass Deviation	PA-23-250(6)	03/25/75	761-044	76-11-07	3440	5G4
498	Fuel Cell Vent Line Assemblies, Inboard, Inspection Of	PA-23-250(6) "F"	04/05/76			2810	5G18
507	Fuel System Control Cables At Swivel Fittings, Inspection Of	PA-23 PA-23-160/-235 PA-23-250 PA-23-250(6)	11/10/76	**	77-26-02	7320	5H15
511A	Oxygen System Outlet Refinement	PA-23-250(6)	08/24/76	**		3510	5I3
514	Stabilator Tab Modification	PA-23-250(6) "F"	09/20/76	761-083		2740	5I8
515	Control Cable Ball Joint Retainer Installation	PA-23-250(6)	01/17/77	**		7610	5I10
523	Cigar Lighter Element, 24 Volt, Replacement	PA-23-250(6) "F"	10/08/76	55674-02		3310	5J7
527	Electric Trim Switch Modification	PA-23-250(6)	11/05/76	756-047	77-09-10	2740	5J18
530	Fuel Crossfeed Operation	PA-23-250(6) PA-E23-250(6)	12/10/76	**	77-23-09	2820	5K5
540A	Stabilator Tip Tube And Weight Assembly, Inspection And Reinforcement	PA-23-250(6) "F"	10/20/80	**	78-02-03	2740	6A1
546	Whelen Wing Tip Strobe Lights, Reference FAA Airworthiness Directive, Inspection Of	PA-23-250(6)	05/18/77	**	75-05-04	3340	6A16
547	Stabilator Tip Rib, Inspection Of	PA-23-250(6) "F"	03/01/77	**	78-02-03	2740	6A20
550	Engine Control Cable Inspection	PA-23-250(6) "F"	03/29/77	**		7230	6B4
558	Altimatec V and V F/D Series; M-4D F/D Series: And Sperry SPZ-200 F/D	PA-23-250(6)	06/10/77			2210	6C1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
559	Rudder Tail Light Inspection	PA-23-250	08/13/77	472-956		3340	6C3
564	Inspection Of Emergency Gear Extension Control	PA-23-250 PA-E-23-250	04/25/77			3200	6C16
566	Horizontal Situation Indicator, EDO Aire Mitchell NSD-360, Modification To	PA-23-250(6)	10/11/77	**		3420	6D9
569	Stabilator Tab Horn Replacement	PA-23-250	08/24/77	761-143	78-02-03	5510	6E2
590	Inspection Of Stabilator Tab Horn/ Stabilator Trim Control Rod Attachment	PA-23-250	01/20/78			2740	6G11
604A	Forward Baggage Door Locking System Modification	PA-23-250	06/08/79	**		5230	6I4
606	Stabilator Assembly Lower Surface Rivet And Rib Attachment Inspection	PA-23-250	07/12/79	**	79-26-01	2730	6I10
629	Landing Gear Hose Assembly Inspection And Replacement	PA-23-250(6)	11/15/78	17766-27		3230	6L10
630A	Collins VIR-350 and VIR-351 Navigation Receiver Modification	PA-23-250(6)	02/25/80			3450	6L14
635	Landing Gear Selector Lever Inspection And Replacement	PA-23 PA-23-235 PA-23-250 PA- 23-250(6)	01/03/79	761-213	79-11-06	3200	7A23
662	Exhaust System Inspection And Modification	PA-23-250(6)	11/01/79	763-975		7810	7E15
663	Fuel Line/Electrical Harness Inspection	PA-23-250	09/24/79	**		2810	7E17
671	Flap Control System Inspection and Reinforcement	PA-23 PA-23-160/-235 PA-23-250 PA-23-250(6)	10/02/80	**	81-04-05	2750	7F14
672A	Step Attachment Area Inspection/ Reinforcement	PA-23 PA-23-160/-235 PA-23-250 PA-23-250(6)	04/16/81		80-26-04	5340	7F23
677	Publications for Aircraft Operation	All Piper Models	05/20/80			PARA 15.0	7H4
683	Propeller Feathering, Minimum Engine RPM	PA-23 PA-23-160/-235 PA-23-250 PA-23-250(6)	05/16/80	Placard **		6120	7H18
721	Heater Fuel Regulator Valve Shroud/ Drain Modification	PA-23-250	04/05/82	764-141		2820	8B12
771	Parking Brake Application	PA-23 PA-23-160/-235 PA-23-250 PA-23-250(6)	05/19/84	81090-02	85-02-05	1130	8J1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
797B	Fuel Port Restrictor Installation	PA-23-250 "F"	09/01/87	566-500		2812	9B14
798	"TURBO" Marking Removal	PA-23-250	12/11/84	N/A		1110	9B19
805A	TRW Hartzell Propeller Products Service Bulletin No. 142B (O-ring Deterioration)	PA-23-250	03/14/86	N/A		6110	9D15
822	Special Inspection Of Hydraulic Hose, Piper Part Number 17766-02 (465-138)	PA-23 PA-23-160/-235 PA-23-250	04/02/86	17766-02	96-21-04	2912	9H3
827A	Part I - Fuel System Draining Procedure - Water Contamination	PA-23 PA-23-160	11/04/88	N/A	90-23-18	2824	9H20
827A	Part II - Apache Dual-Fuel Drain Installation	PA-23 PA-23-160	11/04/88	765-363	92-13-04	2824	9H22
836A	Aluminum Wire Inspection/Replacement	PA-23 PA-23-160/-235 PA-23-250	08/26/86	**		2400	9J4
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	01/14/87	N/A		2800	10A7
884	Lock Wiring Of V-Band Couplings	PA-23-250	04/08/88	**		7800 2100	10G20
932A	Part I - Fuel Cell System Inspection and Wedge Kit Installation for Unbaffled Fuel Cells	PA-23 PA-23-160/-235 PA-23-250	08/30/90	**	90-23-18	2815 2824	10aD16
932A	Part II - Fuel Cell System Inspection and Enlarged Fuel Bowl Installation for Baffled Fuel Cells	PA-23-250	08/30/90	**	90-23-18	2815 2824	10aD18
980	Shoulder Harness Installation	PA-23 PA-23-235 PA-23-250	01/18/95	**		5500	10bB10
991A	Replacement or Modification of the Alternator Out Light Fuse	PA-23-250	01/29/96	**		2437	10bD16
1022	Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01	PA-23-235 PA-23-250	09/22/98	460-632	99-05-09	7167	10bI20
1026	Distribution of Parker Hannifin Airbourne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings".	PA-23-250	11/05/98	766-656		5741	10bJ20
1035	Distribution of Textron Lycoming Service Bulletin 529A, "Reprint of Crane/Lear Service Bulletin No. 101SB020, Rev. 2"	PA-23-250 PA-E23-250	09/03/99	**		7311	10bL17
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements".	PA-23 Series PA-23-250 Series	09/25/00	**		3714	10cB1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1051B	Flap Torque Tube Replacement	PA-23 PA-23-160/-235 PA-23-250 PA-23-250 (6) PA-E23-250	11/05/02	104622-002	81-04-05R1	2755	10cC20
1079	Untested Fuel Pump	PA-23-250 Series	07/20/01	62220-005		2825	10cI4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

**GRIDS 1A22 THRU 1A24
INTENTIONALLY BLANK**

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
164	ADF Indicator Excess Wire, Battery Cable Insulation, Muffler Replacement, Nose Gear Door Retraction Rod, Control Wheel Replacement and Reinforcement Nose Wheel Steering Arm Mounting Bracket	PA-24	05/16/58				2J17
167	Oil Cooler Line Clearance	PA-24	01/06/59	451-855	59-07-05	7920	2K1
168	Nose Gear Retraction Assist Cord	PA-24	01/16/59	754-205	58-25-05	3230	2K2
171	Weight And Balance	PA-24/24-250	03/18/59			0800	2K4
172	Control Wheel Sprocket Mounting Hole, Inspection Of	PA-24-180/24-250 (W/Autocontrol)	04/27/59	**	59-12-09	2700	2K5
173	Aileron Balance Weight Attachment, Bulkhead	PA-24-180/24-250	06/23/59	754-233	59-13-02	2710	2K13
177	Fuel Cell Filling Instructions	PA-24/24-250	08/05/59	21994-00		2810	2K20
178	Control Tube Guide Blocks Safety Wiring Of	PA-24/24-250	09/24/59			2700	2K22
179	Door Window, Refitting Of	PA-24/24-250	11/06/59			5630	2K24
180	Fuel Cell Vent Tubes, Modification Of	PA-24/24-250	11/06/59		59-26-02	2810	2L2
187	Safety Switches. PA-24 and 24-250 Landing Gear-Service Letter 314A, Dated June 8, 1954	PA-24	04/15/60	754-221		3230	2L18
190A	Insulation-Cabin Heat Induction System	PA-24	03/14/60	754-308		2140	2L23
191	Hinge Bracket, Aileron—Part No. 20211-00	PA-24	06/06/60			5150	3A1
192	Throttle Limit Switch Bracket	PA-24	06/17/60	754-334		7610	3A3
193	Fuel Cell Vent Tube, Modification Of	PA-24	06/17/60		60-24-03	2810	3A5
197	Master Cylinder, Brake, Replacement Of	PA-24	12/02/60	455-929		3240	3A12
201	Vacuum Pumps, Dry, Replacement Of	PA-24	04/13/61	481-681		3710	3A21
202	Exhaust System, Comanche. Inspection Of	PA-24	05/22/61	754-396	61-20-02	7810	3A22
205	Circuit Protector Wiring, Inspection Of	PA-24	08/15/61			2400	3B3
208	Gascolator Bowl Drain Valve	PA-24	12/19/61			7310	3B9
210	Muffler Shrouds, Replacement Of	PA-24/24-250	10/03/62	754-484	62-26-05	7810	3B12
211	Main Fuel Cell Cavity Modification	PA-24-250	11/02/62	754-492		2810	3B17
212	Engine-Driven Fuel Pump, Installation Of Vent Lines (PA-24-250 W/Fuel Injection)	PA-24-250	12/05/62	756-700		2820	3B20
216	Fuel Cell Drain Modification	PA-24/24-250	08/05/63	756-756	68-13-03	2810	3C4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
218	Vacuum Pump Spined Coupling, Replacement Of	PA-24/24-250 PA-30	11/11/63	753-865		3710	3C9
219A	Heater, 940DB, Modification And Rewiring	PA-30	09/23/64	756-815		2140	3C12
220	Alternate Air Doors, Replacement Of	PA-30	03/03/64	756-794	64-09-05	7160	3C14
222A	Airspeed Limits, Restriction To, Removal Of (Replacement Of Stabilator Torque Tube)	PA-30	08/10/64	756-827	64-28-03	3410	3C17
224	Pitch Servo—Modification Of— Mitchell Bulletin No. A55	PA-24-250 PA-24-260 PA-24-400 PA-30	04/07/65	756-923	65-11-04	2210	3D3
228	Fuel Purge Valve Hose Assembly, Replacement Of	PA-24-400	01/07/66	756-994	66-30-07	2810	3D15
229A	Airspeed Limits, Restriction, Removal Of	PA-30	06/17/66	**	66-28-06	3410	3D16
231A	Fuel Tank Caps	PA-24/24-250	10/10/66	25983-00	68-13-03	2810	3D23
232	Brake Disc Assembly, Inspection Of	PA-30	06/08/66	757-039		3240	3D24
235	Airspeed Limit, Never-To-Exceed Standardization Of	PA-30	09/16/66	**	66-28-06	3410	3E6
236	Oxygen Cylinder	PA-30	12/29/66	757-094	67-19-05	3510	3E8
238	Fuel Purge Valve Hose Replacement	PA-24-400	12/07/66	757-099		3420	3E10
246	Oxygen Cylinder Rear Retaining Strap Modification Of	PA-30	03/21/67	758-109	67-19-05	3510	3E22
263	Flight Manual Revision	PA-30	01/15/68	760-168		General	3G9
280	Artificial Horizon, R.C. Allen 3", Case Leakage Of	PA-24-260 PA-30	07/10/68			3420	3H20
299	Flight Manual Revision	PA-30 "C"	05/29/69	**		General	3K2
301A	Airplane Flight Manual And New Placards	PA-30	11/25/69	760-354 760-355	69-24-04	1100	3K5
306	Alternator System Modification	PA-30 "C"	01/09/70	760-347	70-22-05	2430	3K14
310	Modifications, Twin Comanche (Airspeed Marking, Stall Warning Horn Installation)	PA-30	05/06/70	760-408 760-373		3410 2700	3K24
314A	Selector Valve, Fuel Modification	PA-30/39	09/28/70	760-444		2820	3L8
315	Limit VNE Airspeed	PA-30	07/08/70	**		1100	3L10
320A	Autopilot Servo and Bridle Cable Installation, III Series, Inspection Of	PA-24-260 PA-30/39	07/06/72			2210	3L23
324	Vacuum Pump Adapter Drive Assembly	PA-24 PA-30/39	09/29/70			3710	4A9
331	Electric Trim Switch Inspection and Modification	PA-24-260 PA-30/39	02/05/71	760-505	71-12-05	2730	4B3

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
336	Seat Frame Tube Replacement, Vertically Adjustable	PA-24-260 PA- 30/39	03/11/71			2510	4B18
343	Hartzell Service Bulletin No. 96, Ammended 8/18/71 And Supplement No. 1 Amended 8/18/71	PA-30	09/09/71	**		6110	4C13
349	Switch Modification, Master, Electrical System	PA-30/39	04/26/72	**		2450	4D5
354B	Fuel Selector Valve Lubrication	PA-24-180/24-250	05/19/82	**		2820	4D15
362	VNE Speed Limit	PA-24-250/24-260	08/14/72	**		3410	4E19
362A	Rudder Balance Weight Installation (Does not cancel Service Bulletin No 362)	PA-24-180/24-250/ 24-260	10/06/72	760-705		2720	4E22
381	Manual Revision, Pilot's Operating/Airplane Flight	PA-39	08/29/73	**		General	4G1
394	Rudder Pedal, Warning, Improper Use Of	PA-24-180/24-250/ 24-260/24-400 PA-30/39	09/28/73	757-436		2720	4H7
411A	Stabilator Torque Tube Bearing Block Attachment Fitting Rivet Replacement	PA-24-180/24-250/ 24-260/24-400 PA-30/39	04/10/74	760-835	94-13-10	2740	4J9
456A	Warning Placard Replacement	PA-24-250/260/400 PA-30/39	05/28/75	**		2840	5B24
464A	Stabilator Torque Tube Bearing Block Attachment Fitting Rivets, Inspection Of	All PA-24 Series PA-30/39	03/22/76	760-835	75-27-08	5530	5C16
496	Stabilator Balance Weight Tube Replacement	PA-24-250/260	6/4/76	28035-00	76-19-07	2740	5G13
511A	Oxygen System Outlet Refinement	PA-24-260/ PA-24-400 PA-30/39	9/24/76	761-032 752-583		3510	5I3
515	Control Cable Ball Joint Retainer Installation	PA-24-250 PA-24-260/400 PA-30/39	1/17/77	55447-02		7610	5I10
527	Electric Trim Switch Modification	PA-24-260 PA-30/39	11/15/76	756-047	77-09-10	2740	5J18
597	Fuel Selector Valve Replacement	PA-30/39	4/19/78	492-137	78-12-07	2840	6H10
677	Publications for Aircraft Operation	All Piper Models	5/20/80			PARA 15.0	7H4
751	Spar Cap Chafing Inspection	PA-24-400 PA-24-180/250/260 PA-30/39	5/24/83	**	83-19-03	5740	8G13
771	Parking Brake Application	PA-24 PA-24-250/260 PA-24-400 PA-30/39	5/19/84	81090-02	85-02-05	1130	8J1
798	"TURBO" Marking Removal	PA-24 Series PA-30/39	12/11/84	N/A		1110	9B19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
805A	TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration)	PA-24-260 PA-30/-39	3/14/86	N/A		6110	9D15
836A	Aluminum Wire Inspection/Replacement	PA-24 PA-24-250/-260 PA-24-400 PA-30/-39	8/26/86	**		2400	9J4
855	Use of Automobile Gasoline In Piper Aircraft	All Piston Powered Models	1/14/87	N/A		2800	10A7
861	Heated Alternate Air Induction System Installation	PA-24-260	5/4/87	760-516	91-21-09	7314	10B1
884	Lock Wiring Of V-Band Couplings	PA-24-260 PA-30/-39	4/8/88	**		7800 2100	10G20
980	Should Harness Installation	PA-24 PA-24-250/-260 PA-24-400 PA-30/-39	1/18/95	**		5500	10bB10
1022	Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01	PA-24 PA-24-250/-260	09/22/98	460-632	99-05-09	7167	10bI20
1026	Distribution of Parker Hannifin Airbourne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings".	PA-24 PA-24-250/-260 PA-24-400 PA-30/-39	11/05/98	753-910		3711	10bJ20
1035	Distribution of Textron Lycoming Service Bulletin 529A, "Reprint of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 2"	PA-24-260 PA-24-400	09/03/99	**		7311	10bL17
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements".	PA-24 PA-24-250/-260 PA-24-400 PA-30/-39	09/25/00	**		3714	10cB1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
209	Propeller Bolts, Replacement Of	PA-28	04/17/62	754-462V	62-19-03	6110	3B11
223	Sender Unit, Stewart-Warner Fuel Quantity Gauge, Modification Of	PA-28-140/150/235	02/16/65	756-906V	65-06-06	2840	3D1
234	Spinner Modification	PA-28	08/02/66	757-046V 757-047V	66-20-05	6110	3E4
237	Rudder Trim Installation Modification	PA-28	11/01/66	757-085V		2720	3E9
240	Inspection Of Aileron Balance Weight, Assembly, Rudder Horn Assembly And Stabilator Balance Weight Assembly For Corrosion	PA-28	12/03/66		67-12-06	2710	3E12
245	Family Seats Center Safety Attachment, Inspection Of	PA-28-140	03/08/67			5340	3E20
248	Torque Links, Main Landing Gear	PA-28	05/12/67	65691-00V 757-123V	70-18-05 67-20-04	3210	3F2
249A	Fuel System Improvement Kit	PA-28-235	03/01/68	757-139V	67-26-02	2800	3F6
251B	Fuel Tank Inspection	PA-28-140/150/ 160/80/235	03/13/68	757-572V	67-26-03	2810	3F10
253	Fuel Line Modification, Tip Tank	PA-28-235	07/07/67	757-151V 757-152V	67-26-02	2810	3F14
261	Aft Spar Wing Attachment Bolts, Inspection Of	PA-28-140/150/ 160/180/235	11/10/67	760-162V		5710	3G5
274	Retraction Fitting Replacement, Main Gear	PA-28R-180	06/03/68	760-208V	68-12-04	3230	3H5
279	Bridle Cable, Servo, Inspection	PA-28	06/24/68	**		3210 2210	3H16
281	Artificial Horizon, R.C. Allen 3", Case Leakage Of	PA-28 PA-28R-180	07/10/68			3420	3H24
285	Fuel Selector Control Stop Assembly	PA-28-235	11/22/68	760-251V		2820	3I11
287	Tail pipe Replacement	PA-28-140/150/ 160/180	01/15/69	63666-02V		7810	3I15
288	Engine Breather Line Modification	PA-28R-180	01/16/69			7160	3I17
292	Landing Gear Modification, Cherokee Arrow	PA-28R-180	03/06/69	760-292V 67150-00V		7110 3230 3200 2910	3J6
293	Brace, Baggage Floor	PA-28-140"B"	03/05/69	760-314V		5230	3J10
295	Retaining Pin, Control Wheel	PA-28-180/235 PA-28R-180/200	04/30/69		69-15-01	2700	3J14
297	Hose Replacement, Air Induction Inlet	PA-28R-180/200	05/22/69	700-328V	69-12-01	7160	3J18
298 (see also SB 312)	Carburetor Heat Control Assembly	PA-28-140"B"/ 180"D"/235"C"	06/02/69	760-320V		7310	3J23

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

REVISED: 06/04/02

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
305	Drain Plugs, Carburetor, Inspection Of	PA-28-140/150/ 160/180/235	11/25/69			7310	3K12
309	Spinner/Bulkhead Inspection And Replacement	PA-28R-180/200	05/08/70	760-410V	70-09-02	6110	3K20
311A	Selector Valve, Fuel Modification	PA-28-235	09/28/70	760-438V		2820	3L3
312	Carburetor Heat Cable Replacement	PA-28-140"B"	06/09/70	760-387V		7310	3L5
313	Terminals, Magneto Filter	PA-28	07/01/70	23969-02	71-14-06	7430	3L6
316	Flight Manual Weight And Balance Data Revision	PA-28R-180/200	10/20/70	**		0800	3L12
317	Rib, Vertical Fin, Inspection	PA-28 PA-28R-180/200	11/18/70	760-451V		5530	3L14
322	Vacuum Pump Adapter Drive Assembly	PA-28 PA-28R-180/200	09/29/70	760-477V		3710	4A3
326	Selector Handle (2Tank) Fuel Valve, Inspection Of The	PA-28 PA-28R-180/200	11/09/70			2820	4A14
327	Stabilator Balance Weight Tube Assembly Inspection	PA-28 PA-28R-180/200	12/09/70	**	70-26-04	2740	4A16
332	Switch, Electric Trim, Inspection And Modification	PA-28-180/235 PA-28R-180/200	04/16/71	760-517V	72-17-05	2730	4B7
337	Seat Frame Tube Replacement Vertically Adjustable	PA-28 PA-28R-180/200	03/11/71	**		2510	4B20
339	Owner's Handbook Revision	PA-28R-180/200	06/16/71	**		2720	4B24
342	Fuel System Instructions And Modification	PA-28-235	09/07/71	760-560V	77-12-01	2800	4C6
348	Air Conditioning System. Improvement	PA-28-140	01/25/72	760-581V		2150	4D4
350	Stabilator Hinge Attaching Bolts, Inspection Of	PA-28-140/180/235, PA-28R-200	03/30/72	**		5550	4D7
355	Valve, Fuel Selector, Lubrication	PA-28-140/150/ 160/180	06/05/72	**		2820	4E1
356	Duct, Induction Air Inlet And Induction Alternate Heat, Inspection And Replacement	PA-28 PA-28R-180/200	09/01/72	**		7160	4E7
357A	Terminal Replacement, Alternator Output Wire	PA-28 PA-28R-180/200	11/14/72	588-398V		2420	4E9
360	Hose System, Modification, Air Induction	PA-28 PA-28R-180/200	11/09/72	**		7160	4E14
368	Antenna Protector, Transponder, Installation	PA-28-140/180/235, PA-28R-200	11/22/72	760-697V		3450	4F7
376	Fuel Selector Control System Modification	PA-28-235	04/19/73	**	77-12-01	2820	4F18
387	Alternator Installation Modification	PA-28 PA-28R-180/200	02/04/74	760-741V 760-742V		2430	4G15

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
393	Seat Belt, Rear, Attachment Modification	PA-28 PA-28R-200	12/18/73	760-794		5340	4H4
395	Rudder Pedal, Warning, Improper Use Of	PA-28 PA-28R-180/200	11/09/73	757-436		2720	4H9
424	Wing Reinforcement Modification	PA-28-151	06/21/74	760-878V	74-14-04	5710	4K16
427	Air Conditioning System Modification	PA-28-140/180 PA-28R-200	08/09/74	760-822V		2150	4K23
435	Aileron Centering—(I) Cable Inspection—(II) Modification	PA-28-151	11/04/74	**	74-24-12	2710	4L15
436	Placard Inspection, Operating Limitations	PA-28-180	12/10/74	76206-00V 76298-00V	74-26-07	1110	4L18
444	Fuel Valve Replacement	PA-28-235	01/15/75	760-895V		2820	5A19
448	Cable Operation Inspection, Throttle and Mixture Control	PA-28 PA-28R-180/200	02/19/75	**		7320	5B4
449A	Alternator (Chrysler) Modification And Wire End Terminal Replacement	PA-28 PA-28R-200	05/07/75	558-398V		2430	5B8
450	Quick Drain Valve Inspection Fuel Gascolator	PA-28 PA-28R-200	02/10/75		75-08-03	2820	5B12
454	Induction Air Shroud Modification	PA-28-151	03/10/75	760-922V		7160	5B19
474	Carburetor Air Box Modification	PA-28-151	06/27/75	760-985V	75-16-04	7160	5D21
475	Instrument Panel Dimmer Control Assembly Modification	PA-28-140 PA-28-151 PA-28-180 PA-28-235 PA-28R-200	07/10/75			3310	5E1
510B	Landing Gear, Nose, Trunnion Modification	PA-28R-200	08/31/76	761-074V	76-15-08	3220	5I1
519A	Fuel Selector Valve Inspection And Replacement	PA-28-235	09/02/76	492-259 492-262	76-18-04	2820	5I21
531	Engine Oil Hose Replacement	PA-28-140	01/10/77	63901-72V	76-25-06	7920	5L5
533	Fuel Gauge Calibration Inspection	PA-28-140/180/ 151/181/235 PA-28R-200	01/06/77	**	77-01-01	2840	5L8
536	Carburetor Air Filter Box, Inspection Of	PA-28-151	01/13/77		77-01-03	7310	5L15
538	Engine Control Cable Inspection	PA-28-151	01/14/77	67639-06V		7610	5L20
541	Throttle Attachment Inspection	PA-28-140/151/ 181/235 PA-28R-200	02/15/77	**		7610	6A5
543	Starter/Magneto Switch Inspection And Replacement	PA-28-151/181/ 235,PA-28R-200	02/09/77	757-597V		7410	6A9
548	Engine Control Rod End Bearing Inspection	PA-28-140/151/ 161/180/181/235 PA-28R-200/201 PA-28R-201T	03/07/77	**	77-23-03	7230	6A23

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
556	Electric Trim Switch Modification	PA-28-180/235 PA-28R-180/200	07/25/77			2730	6B20
561	Battery Power Lead Relocation	PA-28R-201/201T	04/06/77			2430	6C7
563	Landing Gear, Nose, Actuator Rod End Bearing Change	PA-28R-201/201T	05/13/77	452-357V		3230	6C14
565	Horizontal Situation Indicator Modification To Edo Aire Mitchell, Edo Aire Mitchell Service Bulletin No. MB-13	PA-28R-200/ 201/201T	06/02/77	**	77-12-01	3420	6C20
571A	Fuel Valve Leak Check/Fuel Cap Replacement/Fuel Tank Vent Check/Fuel Line Inspection	PA-28-235/260	05/26/77	**	77-12-01	2810	6E5
576	TCM-TS10360 Series Engines, To Disseminate Information	PA-28R-201T	11/30/77			7200	6E23
577	Single Mask Oxygen System Turbo Arrow III	PA-28R-201T	05/01/78	763-808V		3500	6F1
578B	Nose Landing Gear Down Lock Replacement	PA-28R-201/ 201T	09/27/78	67150-04V		3230	6F3
580	Engine Cowling Air Scoop Drain Hole	PA-28-181/235	10/19/77		76-25-06	7100	6F13
582	Pitot and Static Sump Drain Inspection	PA-28-161/181	12/06/77	**		3410	6F15
611	Hose Assembly Inspection and Replacement	PA-28R-200 PA-28R-201T PA-44-180	11/14/78	**		2820	6J5
612	Fuel Gascolator Assembly Inspection	PA-28-161 PA-28R-201T PA-28R-201	10/25/78		79-02-05	7310	6J10
623	Diode Assembly Inspection	PA-28-140/151/ 161/180/181/235 PA-28R-200 PA-28R-201 PA-28R-201T	11/01/78			2450	6K16
625A	Fuel And Vapor Return Lines Support	PA-28R-201T	08/15/80	63882-73V		2810	6K22
627	Fuel Line Inspection And Modification	PA-44-180	10/24/78	63976-34	79-02-02	2810	6L5
630A	Collins VIR-350 And VIR-351 Navigation Receiver Modification	PA-28-161/181 PA-28-236 PA-28R-201 PA-28R-201T PA-44-180	02/25/80			3450	6L14
631B	Battery Protection and Correct Rear Seat Installation	PA-28-151/161	10/29/81	**	81-23-05	2430 2510	7A1
632	Wing Tip Strobe Light Modification	PA-44-180	12/07/78	481-193 761-237V		3340	7A8
634	Engine Primer Modification	PA-44-180	12/28/78	763-908V	79-12-11	7310	7A21

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
638	Inspection Of Fuel Line Union Fitting	PA-28-161/181 PA-28-236 PA-28-201T PA-28R-201/201T PA-28RT-201/201T	04/23/79	**	79-13-03	2810	7B13
639	Throttle Cable Installation Modification	PA-44-180	01/10/79	**	79-05-11	7610	7B17
642	Air Filter Seal Inspection	PA-28-140	02/01/79			7160	7C2
646A	Fuel Tank Vent Modification And Vent Hose Replacement	PA-28-161/181 PA-28-201T PA-28-235 PA-28-236 PA-28R-201/201T PA-28RT-201/201T	03/05/80	763-934V	79-22-02	2810	7C17
650	"P" Lead - Bendix Magnet	PA-28-236 PA-44-180	07/20/79	470-864V		7410	7D3
666	Carburetor Air Box Rivet Replacement	PA-44-180	10/31/79	420-859		7310	7F2
667	Part I - Carburetor Air Box Modification	PA-28-236	10/03/79	763-926V		7310	7F4
667	Part 11 - Engine Induction Air Scoop	PA-28-236	10/03/79	763-953V		7160	7F5
677	Publications for Aircraft Operation	All Piper Models	05/20/80			PARA 1 5.0	7H4
678	Nose Landing Gear Down Lock Bushing Replacement	PA-44-180	03/24/80	764-010V	80-12-03	3230	7H5
679	Throttle Linkage Modification	PA-28-181	03/24/80	764-009V	80-14-02	7610	7H6
681	Boom Microphone Isolation Relay	PA-28-161/181 PA-28-201T PA-28-236 PA-28R-201/201T PA-28RT-201/201T PA-44-180	04/24/80	456-703 180-500	80-14-03	2350	7H11
689A	Aileron Push Rod Functional Check	PA-44-180	10/24/80	**	80-21-11	2710	7J7
691A	Muffler Assembly Inspection	PA-28R-180 PA-28R-200 PA-28R-201 PA-28RT-201	10/08/80	**	80-19-01	7820	7J11
694	Throttle Rod End Assembly	PA-28R-200 PA-28R-201 PA-28RT-201	09/09/80	MS-24665-132		7610	7J22
695	Part I - Nose Cone Spar Check	PA-44-180	09/10/80	764-080V	81-10-01	5350	7K1
695	Part II - Nose Cone Spar Reinforcement	PA-44-180	09/10/80				7K2
696	Master and Alternator	PA-44-180 PA-44-180T	03/16/81	99377-60V		2450	7K4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

REVISED: 06/04/02

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
699	Rudder Torque Tube Attachment Fitting and Hardware Inspection	PA-28RT-201 PA-28RT-201T	04/01/81	**		2720	7K11
702	Aileron Reinforcement	PA-44-180	12/04/80	764-088V	81-10-04	5710	7K19
714	Oil Cooler Hose Installation Inspection	PA-44-180T	06/10/81	35801-09V		7920	8A12
717	Fuel Selector Line Inspection	PA-28-140 PA-28-150/160 PA-28-151 PA-28-161 PA-28-180 PA-28-181 PA-28-236 PA-28R-180/200 PA-28R-201 PA-28RT-201	07/08/81			2820	8A22
719	Engine Mount Reinforcement	PA-44-180	10/15/81	**		7120	8B3
724A	Part I - Nose Landing Gear Inspection and Rigging	PA-28R-201T PA-28RT-201T	04/20/82	**	82-06-11	3220	8C1
724A	Part II - Nose Landing Gear Inspection and Modification	PA-28R-200 PA-28R-201 PA-28RT-201	04/20/82	**	82-06-11	3220	8C2
725B	Aileron Balance Weight Attachment Inspection and Rework	PA-44-180 PA-44-180T	11/03/97	764-148V	81-16-10	2715	8C9
738	Part I - Nose Landing Gear Actuator Rod End Replacement	PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	04/20/82	452-729V		3230	8D14
738	Part II - Nose Landing Gear Actuator Rod End Inspection/ Replacement	PA-28R-180 PA-28R-200 PA-28R-201 PA-28R -201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	04/20/82	452-729V		3230	8D15
749	Stabilator Assist Springs Inspection	PA-44-180 PA-44-180T	11/08/82	**		2370	8G8
753	Expanded Spin Recovery Procedures	PA-28-140	12/15/82	87369-44		2700	8G18
769	Landing Gear Back-Up Actuator Override Mechanism	PA-28R-180 PA-28R-200	10/19/83	**		2920	8I18
771	Parking Brake Application	PA-44-180/180T	05/19/84	81090-02	85-02-05	1130	8J1
774	Baggage Door Latch Replacement	PA-28-150/160 PA-28-180 PA-28R-180	02/22/84	**		5230	8J9
775	Electrical Bus Modification	PA-44-180/180T	06/20/84	764-937V		2430	8J11
787C	Main Landing Gear Trunnion Housing Inspection	PA-44-180/180T	11/07/00	02599-002	94-13-11	3211	8L8

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
789A	Aft Inboard Wing Access Panel & Aft Wing Spar Modification	PA-28-140 PA-28-150/160 PA-28-180 PA-28-235 PA-28R-180/200	05/07/85	765-106V N/A		5711	8L16
798	"TURBO" Marking Removal	PA-28-201T PA-28R-201T PA-28RT-201T	12/11/84	N/A		1110	9B19
801	King Auto Pilot Servo Bridle Clamp Installation	PA-28-161/181 PA-28-236 PA-28RT-201T	12/11/84	**		2200	9C6
804	Battery Strap Installation	PA-28-180/181 PA-28-201T PA-28-235 PA-28-236 PA-28R-200 PA-28R-201/201T PA-28RT-201T	04/26/85	765-157		2430	9D12
805A	TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration)	PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	03/14/86	N/A		6110	9D15
811A	Ammeter Replacement	PA-28-150/160 PA-28-180 PA-28-181 PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T	05/12/86	**	86-17-01	2430	9F4
836A	Aluminum Wire Inspection/Replacement	PA-28-140 PA-28-150/160 PA-28-151/161 PA-28-180 PA-28-181 PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	08/26/86	**		2400	9J4
839	Muffler/Stack Modification	PA-28-181	06/19/86	765-191		7822	9J14

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

REVISED: 03/15/00

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
840	Fuel Selector Valve Cover Replacement	PA-28-140 PA-28-150/160 PA-28-180 PA-28R-180 PA-28R-200	06/19/86	**		2822	9J17
847	Ammeter Replacement	PA-44-180T	08/28/86	765-302	86-20-11	2430	9K23
848	Niagara Oil Cooler Inspection/Replacement	PA-28-236	10/03/86	16599-00		7921	9L1
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	01/14/87	N/A		2800	10A7
856	Stabilator Attach Fitting Corrosion Inspection	PA-28-140 PA-28-150/160 PA-28-151/161 PA-28-180 PA-28-181 PA-28-201T PA-28-235 PA-28-236 PA-28R-180 PA-28R-200 PA-28R-201/201T	02/17/87	**		5550	10A9
866A	Part I - Back Up Landing Gear Extender Removal	PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T	03/04/88	765-303		3236	10B22
866A	Part II - Alternate Means of Compliance	PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T	03/04/88	N/A		3236	10B22
884	Lock Wiring Of V-Band Couplings	PA-28-201T PA-28R-201T PA-28RT-201T PA-44-180T	04/08/88	**		7800 2100	10G20
886	Wing Spar Inspection	PA-28-140 PA-28-150/160/180 PA-28-151/161 PA-28-181 PA-28-235 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T	06/08/88	**		5711	10H3
896	Shoulder Harness Installation & Usage	PA-28-140 PA-28-150/160/180 PA-28-151/161 PA-28-181 PA-28-201T PA-28-235 PA-28-236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	11/28/88	**		5340	10I13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
901	Maneuvering Airspeed Placard Replacement	PA-28-161 Cadet	03/14/89	35669-143		2501	10J14
905	Auxiliary Primer Switch Replacement	PA-28-201T PA-28R-201T PA-28RT-201T	04/06/89	**		7315	10K7
906	Oildyne Hydraulic Pump Replacement	PA-28R-201 PA-28RT-201T	04/10/89	**		2911	10K12
916B	Addition Of Wing Stall Strips	PA-28-161 Cadet PA-28-161 Warrior II PA-28-181	11/22/89	**		1130	10aA8
933A	Trunnion Replacement	PA-28R-201 PA-28R-201T	02/20/90	67054-03		3222	10aD21
937	Engine Mount Inspection and Modification	PA-44-180 PA-44-180T	04/02/90	86212-024		7120	10aE11
938	Wire Protection	PA-28R-201 PA-28R-201T	06/12/90	181-531 488-698		3262	10aE15
940A	Throttle Microswitch	PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T	11/28/90	67210-08 487-925		7613	10aE21
965	Inspection of Flap Lever and Bolt	PA-28-140 PA-28-150/160/180 PA-28-151/161 PA-28-181 PA-28-201T PA-28-235 PA-28-236 PA-28R-180/200 PA-28R-201/201T PA-28RT-201/201T PA-44-180/180T	09/01/93	**		2750	10aJ22
975	Aging Landing Light Seal Replacement and Landing Light Support Modification	PA-28-140 PA-28-150/160/180	11/02/94	**		7160	10bA5
977	Inspection of Wing Rear Attach Fitting and Addition of Inspection Access Panels	PA-28-140 PA-28-150/160/180 PA-28-151 PA-28-161 Warrior II & III PA-28-161 Cadet PA-28-181 PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	12/12/94	**		5740	10bA12

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
978A	Wing Spar Inspection	PA-28-161 Cadet PA-28-161 Warrior III PA-28-181 Archer III PA-28R-201 PA-28R-201T	08/06/99	**		5711	10bB1
990	Pacific Scientific Seat Belt Replacement	PA-28-161 PA-28-181 PA-28R-201 PA-44-180	01/03/96	**		5346	10bD12
991A	Replacement of Modification of the Alternator Out Light Fuse	PA-28-161 Cadet PA-28R-201 PA-28R-201T	01/29/96	**		2437	10bD16
992	Replacement of Spinner and Additional of New Forward Spinner Bulkhead	PA-28-181	03/14/96	**		6110	10bD22
996	Missing Rivet in Upper Door Frame, Forward and Aft	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	09/12/96	**		5311	10bE16
1005	Addition of Drain Holes to the Engine Induction Air Inlet Scoops	PA-28-181	08/11/97			7162	10bG1
1006	Corrosion Inspection of Main Spar Behind Fuel Tanks	PA-28-140 PA-28-150/160/180 PA-28-151 PA-28-161 Warrior II & III PA-28-161 Cadet PA-28-181 Archer II & III PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T	08/15/97	**		0530	10bG4
1016	Aileron Replacement	PA-44-180 PA-44-180T	05/15/98	86562-24 86562-25		2715	10bH19
1019	Inspection of the Engine Oil Cooler	PA-28-181 III	06/03/98	85472-10		7925	10bI6
1020	Inspection of the ARTEX 110-4 ELT and ELT Attachment Bracket	PA-28-161 Cadet PA-28-161 III PA-28-181 III PA-28-236 PA-28R-201 PA-44-180	07/10/98	**		2563	10bI11
1022	Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01	PA-28-140 PA-28-150/160/180 PA-28-181 II & III PA-28-235 PA-28-201T PA-28R-201T PA-28RT-201T	09/22/98	460-632	99-05-09	7167	10bI20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1023	Inspection of Landing Gear Cylinders and Distribution of Parker Hannifin Service Bulletin SB7063	PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	10/08/98	**		2902	10bJ6
1026	Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings."	PA-28-140 PA-28-150/160/180 PA-28-151 PA-28-161 CADET PA-28-161 WARRIOR II & III PA-28-181 ARCHER II & III PA-28-235 PA-28-236 PA-28-201T PA-28R-180 PA-28R-200 PA-28R-201 PA-28R-201 III PA-28R-201T PA-28RT-201 IV PA-28RT-201T PA-44-180 PA-44-180T	10/05/98	753-910		3711	10bJ20
1028	Inspection of the Aileron Control Rod Attached Fitting and the Addition of Safety Clips	PA-44-180 PA-44-180T	12/02/98	**		5755	10bk12
1033	Engine Mount Inspection and Modification	PA-44-180	07/27/99	**		7121	10bL9
1036	Garmin Service Bulletin No. 9905 "GNS430 Mod 1"	PA-28-181 III	10/01/99	**		3426	10cA1
1037	Inspection for Gascolator Bowl Drain Security	PA-28-161 III PA-28-181 III PA-28R-201	10/28/99	**		2824	10cA5
1040	Flight Control Wheel Collar Retainer Modification	PA-28-161 III PA-28-161 Cadet PA-28-181 III PA-28R-201 PA-44-180	03/20/00			2701	10cA19
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-28-140 PA-28-150/-160/-180 PA-28S-160/-180 PA-28-151/-161 PA-28-181 PA-28-235 PA-28-236 PA-28-201T PA-28R-180/-200 PA-28R-201/-201T PA-28RT-201/-201T PA-44-180/-180T	09/25/00	**		3714	10cB1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

REVISED: 12/01/03

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1048	Stainless Steel Control Cables	PA-28-161 II/III PA-28-161 CADET PA-28-181 II/III PA-28-236 PA-28R-201 PA-28R-201T PA-44-180	01/03/01	N/A		2702	10cC9
1050	Engine Baffle Assemblies, Installation of Longer Screws	PA-28-161 III PA-28-181 III	03/07/01	418-421 408-051 690-611		7236	10cC15
1057	Low Noise Muffler Replacement	PA-28-181 III	07/12/01	766-681		7821	10cD24
1079	Untested Fuel Pump	PA-28-161 III PA-28-181 III	07/20/01	62220-004		2825	10cI4
1083C	S-TEC System 55X Autopilot	PA-28-181 III PA-28R-201 PA-44-180	05/30/02	767-316 767-317 767-320		2218	10cI19
1104	Air Box Interference	PA-28-181 III	03/22/02	104606-002		7160	10dA18
1109	Gear Warning Indication	PA-44-180	04/12/02	472-054 473-028		3264	10dB14
1110	Air Box Inspection	PA-44-180	05/16/02	86245-034		7160	10dB18
1117	Rudder Trim System Bolt Inspection	PA-44-180	06/03/02	402-285 691-306		2721	10dC16
1118	Alternate Air Inlet Adapter Inspection	PA-28R-180 PA-28R-200 PA-28R-201 PA-28RT-201	04/19/02	99047-000		7164	10dC20
1119	Toe Brake Installation Inspection	PA-28R-201	08/16/02	424-184 762-587		3241	10dD1
1122	Wing Rib Inspections	PA-28-151 PA-28-161 WARRIOR II & III PA-28-181 ARCHER II & III PA-28-236 PA-28-201T PA-28R-201 PA-28R-201 III PA-28R-201T PA-28RT-201 IV PA-28RT-201T	03/07/03	35617-001 104721-002		5712	10dD14
1127A	Combustion Heater Fuel Pump Leakage (Kelly Aerospace SIL A-110A)	PA-44-180 PA-44-180T	07/18/03	767-367 **	03-11-14	2800	10dE13
1131	Inspection of Cast Main Landing Gear Strut Cylinders (P/N's 65319-002, 65319-003, and 65319-004)	PA-28-140 PA-28-150/160/180 PA-28-151 PA-28-161 II/III PA-28-161 Cadet PA-28-235	08/18/03	65489-002 65490-000		3210	10dF10

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1134	Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105)	PA-28R-180 PA-28R-200 PA-28R-201 III PA-28R-201 PA-28RT-201	06/10/03	**		2800	10dG1
1135	GMA-340 Audio Panel Wiring	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	07/16/03	N/A		2370	10dG9
1136	Auxiliary Fuel Pump Switch	PA-28-201T PA-28R-201T PA-28RT-201T	09/02/03	588-006 (99377-029)		2800	10dG13
1137	Stabilator Balance Weight Tube Assembly	PA-28-161 III PA-28-181 III PA-28R-201	11/06/03	N/A		2749	10dG16
1138	GNS-430 / GI-106 Wiring	PA-28-161 III	10/30/03	N/A		3457	10dG21
1139	Control Wheel Attachment Inspection	PA-28-161 III PA-28-181 III PA-28R-201 PA-44-180	08/28/03	**		2701	10dH1
1141	Clip Nut Replacement	PA-28-161 III PA-28-181 III PA-28R-201	12/09/03	477-640		5351	10dH11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

GRIDS 1B18 THRU 1B24
INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
254	Oil Cooler Hoses, Engine Replacement & Rerouting Of	PA-31	08/17/67	757-167	67-25-06	7920	3F16
255	Emergency Exit Window Mechanism, Modification Of	PA-31	08/09/67	757-159		5220	3F17
256	Pneumatic Pump Hose, Replacement	PA-31	08/25/67	757-175		3710	3F18
257	Modifications, Piper Navajo (Five Sections)	PA-31	10/10/67	**		7720 3210 6110 7920 2810 2910 3200	3F19
258	Alternate Air Box Assembly	PA-31	11/01/67	757-189		7160	3F24
262	Terminals, Solenoid, Insulation Of	PA-31	12/19/67	757-185		3310	3G8
265	Louvered Access Plates, Wing Fillet	PA-31	02/05/68	**		5710	3G11
266	Fasteners, Engine Cowling	PA-31	02/23/68	760-190 757-179		7110	3G13
267A	Flight Manual Revision	PA-31	05/28/68	**		General	3G15
268	Valve Assembly, Manifold And Check	PA-31	02/28/68	760-174		7710	3G18
270	Deicer Boot Installation, Elevator Tip	PA-31	02/23/68	757-200		3010	3G20
271	Filter, Inline, Pneumatic System	PA-31	03/01/68	460-866		3710	3G21
272A	Terminal Screws, Electrical, Security Of - Voltage Regulator Selector Switch And Master Switch	PA-31	05/06/68	**		2430	3G22
276	Channel Clearance, Aileron Cable/Floorboard Support	PA-31	05/23/68	**		2710	3H11
277	Level, Fuel Selector, Cable Attachment Assembly	PA-31-300	07/10/68	760-214	77-26-02	2820	3H13
278	Control Panel (Fuel) Area, Rerouting And Securing Of Wire In The, And Clearance Of The Cross Feed Line	PA-31-300	05/27/68	760-216	68-13-01	2800	3H15
280	Artificial Horizon, R.C. Allen 3", Case Leakage Of	PA-31-300	07/10/68			3420	3H2
283	Warning System, Landing Gear, Modification To The	PA-31-300	10/4/68	760-250		3260	3I5
284	Torque Tube Assembly, Elevator, Inspection Of - Section I; Replacement Of The Steel Elevator Torque Tube Assembly, Part Numbers 40070-00 or 40070-04 With Aluminum Elevator Torque Tube Assembly, Part Number 40070-05 - Section II	PA-31/300	09/27/68	40070-05		2740	3I6
286	Hinge Attaching Rivets, Door, Main Landing Gear (In Board)	PA-31/300	10/29/68	420-236		3210	3I13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
289	Friction, Elevator Control System	PA-31/300	02/17/69		69-06-04	2730	3I19
294	Stall Strips	PA-31/300	05/16/69	760-321 760-322	69 11 05	5720	3J12
304	Stall Strip Inspection	PA-31/300	11/17/69	**		5720	3K9
306	Alternator System Modification	PA-31/300	01/09/70	760-349 760-358	70-22-05	2430	3K14
307	Electrical System Modification, Wing Flap	PA-31/300	03/23/70	760-381		2750	3K16
308A	Seats, Aft Facing	PA-31/300	05/04/70	**		2570	3K17
320A	Autopilot Servo And Bridle Cable Installations, III Series, Inspection Of	PA-31/300 PA-31P	07/06/72			2210	3L23
323	Spar Assemblies, Rudder And Elevator, Modification Of The	PA-31/300	09/21/70	**	70-26-06	5520	4A6
325	Battery Drain Relocation	PA-31/300	11/23/70	760-436	71-01-04	2430	4A12
330	Selector Mechanism Modification Landing Gear 11A	PA-31	01/20/71	760-510		3200	4B1
331	Switch, Electric, Trim Inspection And Modification	PA-31/300 PA-31P	02/05/71	760-505	71-12-05	2730	4B3
333	Safety Strap, Cabin Entrance Door, Inspection And Replacement	PA-31	02/18/71	**		5210	4B10
338	Rivet Installation, Longitudinal Bulkhead	PA-31P	04/21/71	**		5300	4B22
344	Emergency Gear Extension Operation Information, Revised	PA-31 PA-31P	10/12/71	760-570		3200	4C19
346	Flight Manual, Airplane, Mandatory Revision	PA-31	03/23/72	**		2430	4C22
347	Weldon Service Bulletin WPSB-2 (Electric Fuel Pumps)	PA-31	11/17/71	760-573 760-574		2820	4C24
361	Elevator Hinge Bracket Reinforcement, Inspection	PA-31	08/17/72	43757-17 43757-18		5550	4E16
363	Cowl Shield Installation	PA-31/300/310 PA-31-350	02/19/73	760-689		7110	4E24
365	Torquemeter Oil Pump, Replacement Of (Reference Avco Lycoming Service Bulletin No. 350 Dated July 21, 1972)	PA-31P	08/29/71	LW-12637		7920	4F3
379A	Rudder Control Cable Routing, Inspection Of	PA-31-350	10/25/74	41953-03 41953-04	75-06-04	2720	4F20
383	Fuel Selector Valve Control Handle, Modification Of	PA-31-350 PA-31P	04/25/73	760-755		2820	4G4
384	Propeller Blade Shank, Inspection Of (Hartzell Service Bulletin No. 94A Dated March 1, 1973)	PA-31/300/310	04/25/73	**		6110	4G5
386	Moisture Shield Installation, Circuit Probe	PA-31-310 PA-31-350	09/11/73	760-772		2450	4G13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
389	Bridle Cable And Bridle Cable Clamp Installation	PA-31-310 PA-31-350 PA-31P	08/13/73			2210	4G17
391	Loading Instructions, Cargo	PA-31-310	06/06/74	**		5230	4G23
392	Automatic Flight Control System (V Series) Precautionary Operating Placard And System Modification	PA-31-310 PA-31-350 PA-31P	07/11/73	760-793		2210	4H2
394	Rudder Pedal, Warning, Improper Use Of	PA-31/300/310 PA-31-350 PA-31P	09/28/73	757-436		2720	4H7
398	Copilot Gyro Operation - Altimatec V Series Automatic Flight Control System	PA-31-310 PA-31-350 PA-31P	09/13/73	**		2210	4H15
399	High Altitude Operation. Ignition System For (Avco Lycoming Service Instruction No. 1291, Dated November 2. 1973)	PA-31-350	10/29/73	**		7420	4H16
400	Alternator Pulley And Belt Replacement	PA-31-310 PA-31-350	02/06/74	760-805		2430	4H21
405	Fuel Crossfeed Control Mod	PA-31-350	10/31/73	760-814		2820	4I13
407	Ball Joint Assemblies Control Attachment, Inspection Of	PA-31/300 PA-31-350 PA-31-P	11/14/73	469-142		5340	4I22
409	Elevator Control Tube, Inspection Of	PA-31P	06/07/74	40847-04	75-09-10	2730	4J4
415	MAA Plate Replacement And Tailpipe Gasket Installation	PA-31-310	01/21/74	462-062		7810	4J19
417	Heater (Manual) Fuel Shut-Off Valve, Removal Of	PA-31-300	08/26/74		74-26-04	2140	4J22
419	Elevator Control Tube Attachment, Inspection Of	PA-31-310 PA-31-350 PA-31P	02/20/74			2730	4K2
420	Windshield, Heated, Inspection Of	PA-31P	08/07/74	760-882		3040	4K4
421	Fuel Selector Valve Replacement	PA-31P	03/18/74	492-239		2820	4K9
422	Fuel Selector Valve Control Handle, Inspection Of	PA-31-350	03/11/74			2820	4K11
423	Deicer (Propeller Electric) Solenoid Replacement	PA-31P	03/13/74	487-167		6110	4K13
430	Exhaust System Couplings	PA-31P	08/07/74	555 3661 LW-12125-3	76-06-09	7810	4L5
431	Placard, Electric Razor Outlet	PA-31-350	08/05/74	SK-23601 SK-2361		3320	4L8
432	Fuselage Bulkhead, Modification To The	PA-31-310 PA-31-350	09/06/74	760-295		5310	4L9
433	Elevator Control Tube Inspection Of	PA-31/300/310 PA-31-350	12/17/74	**	75-09-10	2730	4L11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
442	Circuit Breaker Rewiring, Emergency Fuel Pump	PA-31/300/310 PA-31-350	01/22/75	760-905		2820	5A15
443	Fuel Cell Fitting (Main) Inspection Of	PA-31/300	04/04/75	760-929 40518-00/01		2810	5A16
446A	Cable Replacement, Rudder/Nose Gear Steering	PA-31P	07/08/75	760-923	75-16-02	2720 3250	5A23
456A	Warning Placard Replacement	PA-31/300/310/325 PA-31-350 PA-31P	05/28/75	**		2840	5B24
458	Propeller Air Charge Loss, Aircraft Operating Advisory	PA-31P	04/11/75	**	75-22-14	6100	5C3
460A	Battery Drain And Vent Relocation	PA-31-350	01/23/76	761-029 760-941	76-04-10	2430	5C8
461	Encoding Altimeter Harness Rewiring	PA-31-310 PA-31-350 PA-31P	04/17/75	**		3410	5C10
462A	Tailpipe Support Bracket Installation	PA-31P	11/03/75	760-974	76-06-09	7810	5C12
470	Propeller Feather Assist Spring Assembly Installation	PA-31P	10/27/75			6110	5D6
473	Alternator Switch Bus Bar Link Installation	PA-31P	03/24/76	49167-03	76-11-06	2450	5D19
478A	Airspeed Limitation Placard, Installation Of	PA-31P	08/20/76	761-075	76-11-01	3410	5E7
479B	Alternate Air Door Magnetic Catch Assembly Modification/Replacement; Engine Induction Air System	PA-31-325 PA-31-350	03/23/76	761-037 761-038	80-13-06	7160	5E9
480	Emergency Fuel Pump Circuit Breaker Placards, Inspection Of	PA-31-310/325 PA-31-350	10/10/75	**		2820	5E11
487	Control Shaft Collar Attachment Modification	PA-31-300/310 PA-31-325 PA-31-350 PA-31P	11/07/75	401-264 407-584	76-04-11	2710	5F7
488	Landing Gear Selector Cable Forward Attachment Pin, Modification Of	PA-31-310/325 PA-31-350 PA-31P	10/24/75	**	96-24-13	3200	5F10
492	Exhaust System Modification TIG0-541 -E1A	PA-31P	03/30/76	**	76-06-09	7810	5F19
494B	Flap Control System, Inspection Of	PA-31-300/325 PA-31-350 PA-31P	07/17/79	**	82-27-13	2750	5G6
497	Throttle And Propeller Pitch Control Attachment Modification	PA-31P	03/29/76	761-031		7610 6120	5G16
500	Elevator Balance Weight Modification	PA-31-325 PA-31-350	04/23/76	761-040 761-041	76-15-07	2730	5G23
507	Fuel System Control Cables At Swivel Fittings, Inspection Of	PA-31/300/325 PA-31P	11/10/76	**	80-18-10	7320	5H15

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
509	Engine Mount Assembly Attachment Nuts, Replacement Of	PA-31-310/325 PA-31-350	06/25/76	404-890		7120	5H22
511A	Oxygen System Outlet Refinement	PA-31/300/325 PA-31-350 PA-31P	09/24/76	761-032 752-583		3510	5I3
512	Seat Track Modification	PA-31/325	10/21/76	761-086		5340	5I5
515	Control Cable Ball Joint Retainer Installation	PA-31/300/325 PA-31/350	01/17/77	55447-02		7610	5I10
521	Stabilizer Stringer Attachment, Inspection Of	PA-31/325 PA-31/350	09/20/76	522-881	77-01-06	5530	5J1
523	Cigar Lighter Element Replacement, 24 Volt	PA-31/325 PA-31-350 PA-31P	10/08/76	55674-02		3310	5J7
525	Seat Latch Mechanism Modification, Pilot/Copilot	PA-31/300 PA-31-350 PA-31P	11/15/76	55842-02		5340	5J12
526A	Microphone And Phone Jack Relay Modification, Pilot/Copilot	PA-31/300/325 PA-31-350 PA-31P	07/25/77	48757-02	77-08-02	2350	5J15
527	Electric Trim Switch Modification	PA-31/300 PA-31-350 PA-31P	11/05/76	756-047	77-09-10	2740	5J18
529	Aircraft Data (MAA) Plate Inspection And Replacement	PA-31	11/05/76	53750-02	77-03-03	5330	5K3
534	Turbine Tailpipe Coupling Replacement	PA-31P	01/24/77	556-053	76-06-09	7810	5L11
535	Radio Power Relay Cover Spacer Bushings, Replacement Of	PA-31/325 PA-31-350	12/15/76		77-07-03	2450	5L13
544	Airspeed Placard Installation	PA-31-325	03/08/77	761-125	77-10-09	3410	6A11
546	Whelen Wing Tip Strobe Lights, Reference FAA Airworthiness Directive, Inspection Of	PA-31/325 PA-31-350 PA-31P	05/18/77	**		3340	6A16
549	Elevator Bungee Link Modification	PA-31/325 PA-31-350	02/16/77		78-01-02	2730	6B2
550	Engine Control Cable Inspection	PA-31/325 PA-31-350	03/29/77	**		7230	6B4
554	Spar Reinforcement, Front, Right Wing	PA-31/325 PA-31-350	03/07/77		77-14-14	5710	6B15
558	Servo Bridle Cable Clamp Bolt Torque Revision; Altimatic V And V F/D Series; M-4D F/D Series; And Sperry SPZ-200 F/D	PA-31/325 PA-31-350 PA-31P	06/10/77			2210	6C1
560	Flap Condition. Asymmetric, Recommended Operating Procedure	PA-31/300/325 PA-31-350 PA-31P	04/04/77	**		2750	6C5

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
566	Horizontal Situation Indicator, Modification To Edo-Aire Mitchell NSD-360	PA-31/325 PA-31-350	10/11/77	**		3420	6D9
567	Flap Solenoid Repositioning	PA-31/300/325 PA-31-350	06/07/77		77-19-06	2750	6D20
574	Fuel Crossfeed Control Shaft Security	PA-31-350	07/13/77	**		2820	6E17
575	Inspection Of Horizontal, Stabilizer And Vertical Fin Stringer Attachment Rivets	PA-31/325 PA-31-350	08/03/77	522-881	77-24-01	5510	6E19
591	Inspection Of Goodyear BTC-39 Fuel Cells	PA-31/300 PA-31-350 PA-31P	03/22/78	**		2810	6G13
592	Inspection Of Fuel Selector Lever Assembly Installation	PA-31/325	02/16/78		78-08-10	2820	6G24
595	Elevator Outboard Hinge Bracket Rivets Replacement	PA-31/325 PA-31-350	06/05/78	762-575		5550	6H4
604A	Forward Baggage Door Locking System Modification	PA-31/300/325 PA-31-350 PA-31P	06/08/79	**		5230	6I4
621	Elevator Cable Inspection And Cable Guard Installation	PA-31-350	10/13/78	71045-02 189-545	78-26-11	2730	6K10
626C	Elevator Down Spring Inspection/Replacement	PA-31/300 PA-31-325 PA-31-350	02/28/97	**	98-08-18 79-01-04	2730	6L1
629	Landing Gear Hose Assembly Inspection And Replacement	PA-31-325 PA-31-350	11/15/78	17766-27		3230	6L10
630A	Collins VIR-350 And VIR-351 Navigation Receiver Modification	PA-31 PA-31-325 PA-31-350 PA-31P	02/25/80			3450	6L14
636A	Bulkhead Reinforcement At STA. 317.75	PA-31/300/325 PA-31-350	08/26/80	**	80-22-04	5310	7B2
641	Heater Fuel Drain Hose Modification	PA-31/300/325 PA-31-350	04/05/79	**		2140	7B22
643A	Oil And Manifold Pressure Tubes Inspection	PA-31 PA-31-325 PA-31-350	12/08/80	41907-00 41913-00		7930 7710	7C4
644D	Turbo-Charger Exhaust Coupling Inspection/Replacement	PA-31/31-325 PA-31-350 T-1020	05/29/86	**	82-16-05	8123	7C7
645A	Crossfeed Valve Inspection	PA-31/31-325 PA-31-350	07/02/79	**		2820	7C14
647A	Outboard Flap Track Inspection Inspection And Reinforcement	PA-31 PA-31-325 PA-31-350 PA-31P	11/24/80	763-986	80-14-06 81-23-06	2750	7C19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
648A	Part I - Scott Fuel Selector Valve Inspection	PA-31 PA-31-300 PA-31-350 PA-31P	04/27/87	760-504		7324	7C21
648A	Part II - Fuel Selector Valve Control Cable Inspection	PA-31 PA-31-300/325 PA-31P	04/27/87	**		7324	7C23
648A	Part III - Fuel Selector Valve Control Cable Replacement	PA-31 PA-31-300/325 PA-31P	04/27/87	**		7324	7C24
649	Elevator Control Stop Inspection	PA-31/31-300 PA-31-325 PA-31-350	03/29/79		79-12-02	2730	7D1
651	Control Shaft Roll Pin Inspection	PA-31/31-300 PA-31-325 PA-31-350 PA-31P	05/11/79	480-732	79-14-02	2710	7D6
653	Modification of Weight and Balance Plotters	PA-31 PA-31-325 PA-31-350	12/03/79	Placard**		0800	7D11
654	Cigar Lighter Installation Modification	PA-31 PA-31-325 PA-31-350	06/23/80	**		3310	7D13
658	Elevator Inspection And Reinforcement	PA-31P	07/31/79	763-943	80-02-15	2730	7E5
659	Rudder And Aileron Trim Tab Attachment Inspection	PA-31P	07/19/79	406-829		2710 2720	7E7
664	Elevator Torque Tube Attachment Inspection	PA-31 PA-325 PA-31-350	12/14/79	**		2730	7E20
677	Publications for Aircraft Operation	All Piper Models	05/20/80			PARA	7H4
682	Main Landing Gear Inboard Door Hinge Inspection/Replacement	PA-31 PA-31-325 PA-31-350 PA-31P	07/24/80	**	80-26-05	3210	7H15
684	PA-31-350 Chieftain/Takeoff Flaps	PA-31-350	04/14/80	**	80-08-05	2750	7I16
685	Elevator Bellcrank Assembly Inspection	PA-31 PA-31-325 PA-31-350	09/23/80	**		2730	7I18
688	Placards Installation Check	PA-31 PA-31-325 PA-31-350	07/01/80	Placard**	80-17-06	1130	7I24
690	Elevator Balance Weight Inspection	PA-31 PA-31-325 PA-31-350	07/07/80	**	80-17-02	2730	7J9

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
693	Engine Baffle Seats Inspection/ Modification	PA-31/31-300 PA-31-350	07/28/80	**	80-20-04	7230	7J16
697	PA-31, PA-31-325 Takeoff Flaps	PA-31 PA-31-325	08/11/80	**	80-21-07	2750	7K7
700A	Nose Wheel Inspection/ Replacement	PA-31 PA-31-325 PA-31-350 PA-31P	10/12/81	551-791	97-07-03	3240 N/A	7K14
704	Cabin Fan Fuse Installation	PA-31 PA-31-325 PA-31-350	06/07/82	**		2120	7L1
705	Main Landing Gear Door Actuator Fitting	PA-31P	06/20/81			3250	7L5
707	PA-31-350 Chieftain Takeoff Flaps	PA-31-350	02/04/81	764-101		2750	7L11
708	PA-31 and PA-31-325 Takeoff Flaps (Refer to SB 697)	PA-31 PA-31-325	04/07/81	764-101		2750	7L16
737	Elevator Outboard Hinge Installation Inspection	PA-31P	04/23/82	764-381		5550	8B12
739	Restriction of Flap Travel and Inspection of Wing Flap Flexible Drive Shaft	PA-31 PA-31-325 PA-31-350 PA-31P	03/01/82	**	82-27-13	2750	8D19
752	Cigar Lighter Circuit Modification	PA-31P	10/18/82	454-656		3310	8G16
771	Parking Brake Application	PA-31P	05/19/84	81090-02	85-02-05	1130	8J1
779B	Part I - Landing Gear Upper Bearing Retaining Pin Replacement And Strut Assembly Inspection	PA-31/31-300 PA-31-325 PA-31-350 T-1020 PA-31P	10/12/87	**	85-08-05	3200	8K1
797B	Fuel Port Restrictor Installation	PA-31, 31-310 PA-31-325 PA-31-350 T-1020 PA-31P-350 PA-31P	09/01/87	**	87-21-01	2812	9B14
798	"TURBO" Marking Removal	PA-31, 31-310 PA-31-325 PA-31-350 PA-31P	12/11/84	N/A		1110	9B19
802	Aft Bulkhead (Fuselage Station 332 0) Inspection	PA-31P	12/12/84	764-983	85-05-01	5310	9C10

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
805A	TRW Hartzell Propeller Service Bulletin No 142B (O-ring Deterioration)	PA-31 PA-31-325 PA-31-350 T-1020 PA-31P-350 PA-31P	03/14/86	N/A		6110	9D15
822	Special Inspection Of Hydraulic Hose, Piper Part Number 17766-02 (465-138)	PA-31-300 PA-31-310 PA-31-325 PA-31-350 T-1020 PA-31P-350 PA-31P	04/02/86	17766-02	96-21-04	2912	9H3
825	Crossover Fuel Line Inspection	PA-31-300 PA-31-310	04/08/86			2823	9H14
826A	Elevator Hinge Inspection/Replacement	PA-31P	04/22/86	45253 03		5550	9H17
829	Oil Separator Assembly Replacement	PA-31P-350	04/18/86	02564-02		7250	9I9
836A	Aluminum Wire Inspection/Replacement	PA-31-300 PA-31-310 PA-31-325 PA-31-350 PA-31P	08/26/86	**		2400	9J4
845A	Main Landing Gear Forward Side Brace Inspection/Replacement	PA-31-300/310 PA-31-325/350 T1020/PA-31P-350 PA-31P	10/09/87		88-05-05	3218	9K16
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	01/14/87	N/A		2800	10A7
859	Nose Gear Shuttle Valve Bracket Installation	T-1020	03/30/87	765-315		3225	10A18
860	Main Landing Gear Downlock Cable Anti-Rotation Stop Replacement	PA-31-300 PA-31-310 PA-31-325 PA-31-350 T-1020 PA-31P	04/14/87	**		3210	10A20
884	Lock Wiring Of V-Band Couplings	PA-31 PA-31-325 PA-31-350 T-1020 PA-31P PA-31P-350	04/08/88	**		7800 2100	10G20
897B	Elevator Butt Rib Refinement	PA-31P	07/15/97	**		5520	10I21

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
907	Windshield Heat Fuse Installation	PA-31-300 PA-31-310 PA-31-325 PA-31-350 T-1020	04/11/89	**		3047	10K15
923	Main Landing Gear Actuator Reinforcement Bracket Replacement	PA-31-300 PA-31-310 PA-31-325 PA-31-350 T-1020 PA-31P PA-31P-350	08/16/89	73786-02	96-21-11	5740	10aB13
926A	Hartzell Service Bulletin No. 165E, Inspection for Cracks in Certain Three Blade "Y" Shank Aluminum Propeller Hubs	PA-31 PA-31-325 PA-31-350 PA-31P-350	03/07/94	**		6113	10aC1
927	Hartzell Service Bulletin No. 164, Inspection for Cracks in Certain Two Blade "Y" Shank Aluminum Propeller Hubs	PA-31-300	12/04/89	**		6113	10aC18
967	Aileron Hinge Inspection and Replacement	PA-31P	1/24/94	**	96-21-03	5750	10aK15
974	Aileron Hinge Inspection and Replacement	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31P-350	10/19/94	**	96-21-03	5750	10bA1
991A	Replacement or Modification of the Alternator Out Light Fuse	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T 1020 PA-31P	01/29/96	**		2437	10bD16
998A	Elevator Spar Inspection	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T 1020 PA-31P-350	08/04/97	**	99-12-05	2730	10bDF1
1002	Elevator Down Spring Inspection /Replacement	PA-31P	06/05/97	**	98-08-18	2739	10bF ¹ 17
1003	Wing Spar Splice Plate Replacement	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T 1020	06/16/97	**	98-09-25	5711	10bF20
1004	Inspection of the E303 Electrical Connector and Heater Blower Power Wire	PA-31-350 PA-31-350 T 1020	06/06/97	**		2451	10bF22

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1007	Horizontal Stabilizer Spar and Outboard Hinge Inspection and Modification	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T-1020 PA-31P-350	09/30/97	766-646	99-06-01	5511	10bG13
1008	Elevator Butt Rib Refinement	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T-1020 PA-31P-350	09/30/97	766-642		5521	10bG15
1026	Distribution of Parker Hannifin Airbourne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings".	PA-31-300 PA-31-325 PA-31-350 PA-31-350 T-1020	11/05/98	753-910		3711	10bJ20
1035	Distribution of Textron Lycoming Service Bulletin 529A, "Reprint of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 2"	PA-31 PA-31-300 PA-31-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	09/03/99	**		7311	10b17
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	09/25/00	**		3714	10cB1
1045	Forward Wing Spar Attach Bracket Inspection	PA-31 PA-31-300	09/18/00	**		5741	10cB23
1105A	Rudder Torque Tube Assembly Inspection	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	09/22/03	767-349		2725	10dA22
1125	Elevator Trim Wheel Replacement	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	04/15/03	43751-000		2733	10dE7
1134	Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105)	PA-31 PA-31-300/-325 PA-31-350 PA-31-350 T-1020 PA-31P PA-31P-350	06/10/03	**		2800	10dG1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

THIS PAGE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
440	Refinement Modifications, Cheyenne	PA-31T	12/17/74	**		2750 6110 3420 2150 6140	5A9
446A	Cable Replacement, Rudder/Nose Gear Steering	PA-31T	07/08/75	760-923	75-16-02	2720 3250	5A23
453A	Scoop Modification, Engine Air Inlet	PA-31T	04/07/75	760-942		7160	5B18
456A	Warning Placard Replacement	PA-31T	05/28/75	**		2840	5B24
459	Servo Cable Clamp Replacement, Aileron And Rudder, M-4D Automatic Flight Control System	PA-31T	04/22/75	33078-03		2210	5C6
465	Fuel Vent Line, Inspection Of	PA-31T	04/30/75			2810	5C20
466	Air Conditioning System Modification	PA-31T	06/02/75	760-979		2150	5C22
468	Elevator Trim Tab Attachment Hinges And Screw Assembly, Inspection Of	PA-31T	05/09/75	**		5550	5D2
476	Elevator Trim Control Cable Turnbuckles, Inspection Of	PA-31T	10/09/75	454-867		2730	5E4
477A	Elevator Control Tube And Trim Tab System Modification	PA-31T	11/03/75	760-989	76-03-01	2730	5E6
481A	Elevator Assembly Inspection And Elevator Butt Rib Replacement	PA-31T	11/03/75	**	76-03-01	5520	5E14
484	Starter Generator System Modification	PA-31T	12/05/75	761-019		8010	5E24
487	Control Shaft Collar Attachment Modification	PA-31T	11/07/75	401-264 407-584	76-04-11	2710	5F7
488	Landing Gear Selector Cable Forward Attachment Pin, Modification Of	PA-31T	10/24/75	**	96-24-13	3200	5F10
494B	Flap Control System, Inspection Of	PA-31T	07/17/79	**	82-27-13	2750	5G6
504	Elevator Hinge System Modification	PA-31T	06/01/76	761-056	76-18-06	5550	5H8
511A	Oxygen System Outlet Refinement	PA-31T	09/24/76	761-032 752-583		3510	5I3
515	Control Cable Ball Joint Retainer Installation	PA-31T	01/17/77	55447-02		7610	5I10
517	Engine Oil Temperature Gauge Placard Installation	PA-31T	10/05/76	757-487		7930	5I17
523	Cigar Lighter Element Replacement, 24 Volt	PA-31T	10/08/76	55674-02		3310	5J7
525	Seat Latch Mechanism Modification, Pilot/Copilot	PA-31T	11/15/76	55842-02		5340	5J12
526A	Microphone And Phone Jack Relay Modification, Pilot/Copilot	PA-31T	11/30/76	48757-02	77-08-02	2350	5J15
546	Whelen Wing Tip Lights, Reference FAA Airworthiness Directive, Inspection Of	PA-31T	05/18/77	**		3340	6A16

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
558	Servo Bridle Cable Clamp Bolt Torque Revision; Altimatic V And V F/D Series; M-4D F/D Series; And Sperry SPZ-200 F/D	PA-31T	06/10/77			2210	6C1
560	Flap Condition, Asymmetric, Recommended Operating Procedure	PA-31T	04/04/77	**		2750	6C5
562	Annunciator Panel Oil Temperature Indicator System Modification	PA-31T	10/04/77	**		3310	6C10
568	Nose Wheel Replacement (High Flotation Tire Option)	PA-31T	04/26/77	45520-07		3240	6E1
570A	Inspection Of Main Landing Gear Actuating Cylinder Rod End Bearing Assy.	PA-31T	08/30/78	762-554	78-02-01	3230	6E3
572	Pilot's Operating Manual/Pilot's Operating Handbook Revision	PA-31T	06/09/77	**		0800	6E12
585	Air Control Cable Stand-Off Installation	PA-31T	03/09/78	763-821		2130	6F22
588	Operating Manual Pilot's/Operating Handbook Rev. Flap Selector Operation Advisory	PA-31T	06/09/77	**		2750	6G7
589B	Inspection Of Turn And Bank Suction System Check Value/ Vacuum System Modification	PA-31T	09/25/79	**		3420	6G8
591	Inspection Of Goodyear BTC-39 Fuel Cells	PA-31T	03/22/78	**		2810	6G13
594A	Modification Of Left And Right Circuit Protector Mounting Board Installation	PA-31T/31T1	07/07/78	763-873		3910	6H2
598A	Inspection Of Main Landing Gear Brake Discs (Cleveland)	PA-31T	04/05/78	754-618 754-626		3240	6H12
599A	Replacement Of Cleveland High Flotation Nose Wheel Assembly	PA-31T PA-31T1	10/04/78	551-782		3240	6H14
604A	Forward Baggage Door Locking System Modification	PA-31T	06/08/79	**		5230	6I4
629	Landing Gear Hose Assembly Inspection And Replacement	PA-31T PA-31T1	11/15/78	17766-27		3230	6L10
630A	Collins VIR-305 And VIR-351 Navigation Receiver Modification	PA-31T PA-31T1	02/25/80			3410	6L14
640	Electroluminescent Panel Inverter Replacement And/Or Relocation	PA-31T PA-31T1	06/22/79	763-929 763-944	79-19-09	3910	7B20
647A	Outboard Flap Track Inspection and Modification	PA-31T PA-31T1	11/24/80	763-986	81-23-06	2750	7C19
651	Control Shaft Roll Pin Inspection	PA-31T PA-31T1	05/11/79	480-732	79-14-02	2710	7D6
658	Elevator Inspection And Reinforcement	PA-31T PA-31T1	07/31/79	763-943	80-02-15	2730	7E5

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
659	Rudder And Aileron Trim Tab Attachment Inspection	PA-31T PA-31T1	07/19/79	406-829		2710 2720	7E7
660	Gyro Inverter Power Selector Switch Guard Installation	PA-31T1	09/26/79	29321-02		3940	7E9
665A	Throttle Control Ball Joint Connector and Rod End	PA-31T PA-31T1	05/30/80	**		7320	7E23
670	Aircraft Data Plate Modification	PA-31T1	12/03/79		80-11-06	5300	7F12
674	Rudder Trim Mechanism Modification And Trim Tab Rigging	PA-31T PA-31T1	01/23/80	**		2720	7G13
677	Publications for Aircraft Operation	All Piper Models	05/20/80			PARA 15.0	7H4
680	Ground Clearance Switch Fuse Installation	PA-31T PA-31T1	04/23/80	**		3450	7H7
682	Main Landing Gear Inboard Door Hinge Inspection/Replacement	PA-31T PA-31T1	07/24/80	**	00-25-01 80-26-05	3210	7H15
692	Oxygen Mask Replacement	PA-31T	08/06/80	474-108		3510	7J14
704	Cabin Fan Fuse Installation	PA-31T2 PA- 42	06/07/82	**		2120	7L1
705	Main Landing Gear Door Actuator Fitting	PA-31T PA-31T1	06/20/81			3250	7L5
715A	Elevator Control Tube Inspection	PA-31T PA-31T1 PA-31T2	04/25/83	**		2730	8A15
722	Avionics Cooling Fan Inspection/ Replacement	PA-31T PA-31T1	04/16/82	764-375		2300	8B14
726	Razor Inverter Wiring Inspection	PA-42	07/21/81			3320	8C11
727	Powerplant Firewall Inspection	PA-42	07/21/81	411-583 404-559		5410	8C13
728	Hydraulic Pump Replacement	PA-42	09/17/82	**		2910	8C15
731	Heater Air Distribution Box Thermal Switch Installation	PA-31T PA-31T1	03/17/82	764-227 764-228		2140	8C21
733	Emergency Exit Window Installation	PA-31T PA-31T1 PA-31T2	01/25/82	189-743	82-11-04	5630	8D3
734	Fuel Scavenge Pump Check Valves Relocation	PA-31T PA-31T1 PA-31T2	12/11/81			2820	8D6
736	Nacelle Fuel Tank Check Valve Installation	PA-42	12/17/82	492-233 57761-06		2820	8D10
740	Ice Vane and Control Circuit Breaker Replacement	PA-42	04/15/83	454-722		3020	8E18

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
741	Part I - Wing Flap Travel Restriction and Inspection of Wing Flap Flexible Drive Shaft	PA-31T	03/01/82	**		2750	8E19
741	Part II - Wing Flap Operating Procedures	PA-31T PA-31T1	03/01/82	**		2750	8E24
742	Engine Oil Hose and Fitting Replacement	PA-42	10/12/82	764-407		7920	8F11
754	Air Conditioning Condenser Fan Impeller Replacement	PA-31T PA-31T1	02/14/83	460-102 506-501		2100	8H1
764	Pilot's Side Window Inspection	PA-42	07/27/83	**		5610	8I4
765	Rivet Installation/Replacement, Tail Fin Fuselage	PA-42	07/11/83	**		5530	8I6
766	Main Landing Gear Slotted Up Lock Hook Brackets Replacement	PA-31T2 PA-31T3	10/24/83	**		3210	8I9
767	Cleveland 40-106 Main Landing Gear Wheels Replacement	PA-31T PA-31T1	10/25/83	551-775		3240	8I13
768A	Main Landing Gear Pivot Shaft Assy Bolts Inspection/Replacement	PA-42 PA-42-720 PA-42-1000	05/24/85	**		3210	8I15
773A	Bulkhead (Fuselage Station 332.0) Inspection	PA-31T PA-31T1 PA-31T2 PA-31T3	05/03/84	**	96-10-13	5310	8J5
776A	Part I - Fuel Quantity Placards Replacement	PA-31T/T1 PA-31T2	02/16/88	**		1100	8J13
776A	Part II-Weight And Balance Plotter Replacement	PA-31T/T1 PA-31T2	02/16/88	**		1100	8J15
777	Fuel Quantity Placards	PA-42	03/19/84	**		1100	8J17
778	Aileron Trim Tab Control Tube & Rudder Cable Retainer Hardware Inspection	PA-42	04/24/84	**		2700	8J19
779B	Part I - Landing Gear Upper Bearing Retaining Pin Replacement And Strut Assembly Inspection	PA-31T/T1 PA-31T2/T3 PA-42	10/12/87	**	85-08-05 N/A	3200	8K1
779B	Part II - Landing Gear Upper Bearing And Strut Assembly Inspection	PA-42	10/12/87	**		3200	8K3
785	Inline Fuel Filter Mod - Janitrol	PA-42 PA-42-720	07/19/84	**		7312	8L1
788	Avionics (Copilot) Bus Lead Hardware Replacement	PA-42 PA-42-720	07/19/84	**		2457	8L14
795A	Electrical Connector Improvement	PA-31T/T1 PA-31T2	04/29/85	**		2430	9B1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
806	Revision Of Airspeed Markings Due To Position Error Change	PA-42-720	07/01/85	765-181		3412	9E1
807	Flow Strip Position Inspection	PA-42 PA-42-720	06/19/85	N/A		5721	9E4
812	Rudder Stop Inspection And Replacement	PA-42-1000	11/04/85	75695-05		2720	9F11
814	Generator Control Unit Sleeve Installation	PA-42-1000	03/14/86	765-190		2430	9F18
816C	Ignition Select Mode During Approach and Landing	PA-42-1000	03/28/89	765-306	86-21-10	7428	9G1
817C	Main Landing Gear Forward Side Brace Inspection/Replacement	PA-42-1000	05/21/90	**		3218	9G5
821A	Special Inspection Of Fuel Quantity Probes	PA-31T/PA-31T1 PA-31T2/PA-31T3	05/14/86	**		2842	9G23
822	Special Inspection Of Hydraulic Hose, Piper Part Number 17766-02 (465-138)	PA-31T/T1/T2 PA-31T3 PA-42 PA-42-720	04/02/86	17766-02	96-21-04	2912	9H3
823	Engine Control Cables Modification	PA-42-1000	03/19/86	765-195		7324	9H6
826A	Elevator Hinge Inspection/Replacement	PA-31T/31T1 PA-31T2/31T3	04/22/86	45253-03		5550	9H17
831	Ice Deflector Vane Modification	PA-31T1 PA-31T3	04/18/86	765-156		7250	9I16
835	Wing - Nose Rib, Station 0.50, Modification And Wire Harness Inspection	PA-42-1000	05/15/86	765-305		5712	9J1
836A	Aluminum Wire Inspection/Replacement	PA-31T/T1	08/26/86	**		2400	9J4
838	Fuel Vent System Installation-Wing Panel Modification	PA-42-1000	06/23/86	765-192		2814	9J11
841A	Main Landing Gear, Forward Side Brace Inspection/Replacement	PA-31T3 PA-42 PA-42-720/720R	10/08/87	**		3218	9J19
842	Rudder Trailing Edge Rework	PA-42-1000	06/23/86	765-200		5523	9K1
843	Part I - Garrett Service Bulletin No TPE331-72-7029	PA-42-1000	03/27/87	**		7201	9K4
843	Part II - Starter/Generator Bracket Retrofit Installation	PA-42-1000	03/27/87	**		7201	9K4
844	Stick Pusher Relay Box Modification	PA-42-1000	07/28/86	765-307		2201	9K12

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
845A	Main Landing Gear Forward Side Brace Inspection/Replacement	PA-31T/31T1 PA-31T2	10/09/87	**	88-05-05	3218	9K16
846A	Wing Tip Tank Vent Line Assembly Inspection (Piper Part Number 75389-02)	PA-42-1000	09/19/86	**	86-18-10	2813	9K21
849	Improved Brake Piston/Insulator And Pressurized Brake Reservoir Installation	PA-42-1000	10/08/86	**		3243	9L5
850	Part I - Garrett Service Bulletin No. TPE331-75-7001	PA-42-1000	10/08/86	**		7120	9L7
850	Part II - Left Engine Mount Inspection	PA-42-1000	10/08/86	**		7120	9L7
857	Tailcone Drain Holes, Fuselage Station 332.00	PA-42 PA-42-720 PA-42-720R PA-42-1000	03/10/87	N/A		5305	10A12
859	Nose Gear Shuttle Valve Bracket Installation	PA-42 PA-42-720 PA-42-720R PA-42-1000	03/30/87	765-315		3225	10A18
860	Main Landing Gear Downlock Cable Anti-Rotation Stop Replacement	PA-31T/31T1/31T2 PA-31T3 PA-42	04/14/87	**		3210	10A20
867	Fuel Quantity Sensor Replacement	PA-42-1000	06/24/87	765-335		2840	10C1
869	Fire Extinguisher Annunciator Circuit Modification	PA-42 PA-42-720 PA-42-1000	09/09/87	**		2600	10C5
870	Lear Siegler Power Equipment Corporation (LSPEC) Service Information Letter No. 23090-004-01	PA-42-1000	09/25/87	**		2400	10C7
873	Part I - Engine Mount Inspection And Barrel Nut Replacement	PA-42-1000	12/22/87	**		7100	10D13
873	Part II - Engine Inlet Inspection And Modification	PA-42-1000	12/22/87	**		7100	10D14
874	Nacelle Rework	PA-42-1000	02/08/88	765-320 765-334		5410	10E4
877	Control Column Chain Inspection	PA-42-720 PA-42-720R PA-42-1000	01/06/88	472-684		2702	10F19
881B	TPE 331-14 Engine Idler Gear Bearing Replacement	PA-42-1000	02/19/88	**		7261	10G10

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
882	Outboard Flap Transmission Clearance Inspection/ Modification	PA-42 PA-42-720 PA-42-720R PA-42-1000	03/08/88	89140-02 89141-02		2758	10G14
884	Lock Wiring Of V-Band Couplings	PA-31T/31T1 PA-31T2/31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000	04/08/88	**		7800 2100	10G20
885	Main Landing Gear Actuator Attach Bolt	PA-42-1000	05/04/88	**		3213	10H1
887	Elevator Skin/Stringer Inspection/Modification	PA-42 PA-42-720 PA-42-720R PA-42-1000	06/29/88	**		2730	10H10
888	Rudder Pedal Torque Tube Attach Bracket Modification	PA-42 PA-42-720 PA-42-720R PA-42-1000	07/12/88	**		2721	10H13
889	Main Landing Gear Uplock Hook Bracket Inspection and Roller Modification	PA-31T1	07/01/88	41413-79		3230	10H17
897B	Elevator Butt Rib Refinement	PA-31T/31T1 PA-31T2	07/15/97	**		5520	10I21
911	Tip Tank Tailcone Attachment Improvement	PA-42-1000	05/30/89	765-379		5722	10L9
912	Rework of Plug - Main Landing Gear Oleo Tube	PA-42-1000	06/08/89	**		3212	10L11
914	Bleed Air Hose Replacement	PA-42 PA-42-720 PA-42-720R	07/12/89	**		2181	10aA1
922	Main Landing Gear Actuator Attach Bracket Replacement	PA-42 PA-42-720 PA-42-720R	08/16/89	765-372		5740	10aB11
923	Main Landing Gear Actuator Reinforcement Bracket Replacement	PA-31T PA-31T1/31T2 PA-31T3	08/16/89	73786-02	96-21-11	5740	10aB13
925	Addition Of Check Valve To Motive Flow Supply Line	PA-42 PA-42-720 PA-42-720R	11/13/89	**		2823	10aB20
929A	Main Landing Gear Upper Strut Housing Inspection	PA-42-1000	08/09/94	75215-04		3211	10aD3
931	Elevator Trim Wheel Shaft Roll Pin Safety Wire Installation	PA-42-720 PA-42-720R PA-42-1000	01/09/90	**		2733	10aD13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
945	Cheyenne Rudder Torque Tube Assembly	PA-42 PA-42-720 PA-42-720R PA-42-1000	10/19/90	**		5541	10aG8
954	Instrument Static Line Installation	PA-31T/31T1 PA-31T2//31T3	03/03/92	**		3410	10aH20
957	Engine Fuel Pump Overboard Drain Line Installation	PA-42 PA-42-720 PA-42-720R	02/04/92	766-257		2820	10aI9
967	Aileron Hinge Inspection and Replacement	PA-31T PA-31T1 PA-31T2 PA-42 PA-42-720 PA-42-720R PA-42-1000	01/24/94	**	96-21-03	5750	10aK15
969	Upper Main Gear Housing Inspection and Replacement	PA-42 PA-42-720 PA-42-720R	07/24/94	57680-09		3211	10aK23
972	Emergency Exit Window Inspection and Replacement	PA-42-1000	09/21/94	**		5620	10aL10
974	Aileron Hinge Inspection and Replacement	PA-31T3	10/19/94	**	96-21-03	5750	10bA1
984	Inspection and Replacement of Outer Side Windows	PA-42 PA-42-720 PA-42-720R	07/14/95	**		5750	10bC10
1032	Elevator Spar Refinement	PA-31T PA-31T1 PA-31T2	07/15/99	766-655		2730	10bL6
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000	09/25/00	**		3714	10cB1
1047	Elevator Spar Refinement	PA-31T3 (T1040)	12/04/00	766-655		2730	10cC6
1048	Stainless Steel Control Cables	PA-42 PA-42-720 PA-42-1000	01/03/01	N/A		2702	10cC9
1105A	Rudder Torque Tube Assembly Inspection	PA-31T PA-31T1 PA-31T2 PA-31T3	09/22/03	767-349		2725	10dA22

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1125	Elevator Trim Wheel Replacement	PA-31T PA-31T1 PA-31T2 PA-31T3 PA-42 PA-42-720 PA-42-720R PA-42-1000	04/15/03	43751-000		2733	10dE7
1128	Engine Fuel Valve Inspection (Honeywell OIL OI331-19)	PA-42-1000	02/21/03	N/A		2800	10dE20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

PA-31T/31T1
PA-31T2/31T3
PA-42

SERVICE BULLETIN INDEX

REVISED: 03/15/00

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

GRIDS 1C22 THRU 1C24
INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
233	Brake Disc Assembly, Inspection Of	PA-32	06/08/66	757-039V		3240	3E2
237	Rudder Trim Installation Modification	PA-32-260	11/01/66	757-085V		2720	3E9
239	Windshield Collars, Inner And Outer, Replacement Of	PA-32-260	12/12/66	757-095		5610	3E11
240	Balance Weight Assembly Aileron And Stabilator, Inspection Of, For Corrosion	PA-32-260	12/13/66		67-03-07	2710	3E12
244	Heater Duct Tunnel Modification Cabin	PA-32-260/300	02/02/67	757-110V		2140	3E19
248	Torque Links, Main Landing Gear	PA-32-260/300	05/12/67	**	67-20-04 70-18-05	3210	3F2
249A	Fuel System Improvement Kit 757 139V	PA-32-260/300	03/01/68	757-139V	67-26-02	2800	3F6
251B	Fuel Tank Inspection	PA-32-260/300	03/13/68	757-572V	67-26-03	2800	3F10
252	Mixture Control Cable, Inspection Of	PA-32-300	05/15/67	65451-05V		7320	3F12
253	Fuel Line Modification, Tip Tank	PA-32-260/300	07/07/67	757-151V 757-152V	67-26-02	2810	3F14
259	Storm Window Placard, PA-32-260 Cherokee	PA-32-260	11/07/67	757-314V		5610	3G2
260	Duct, Engine Air Inlet, Replacement Of The	PA-32-300	11/08/67	760-159V	67-30-06	7160	3G4
261	Aft Spar Wing Attachment Bolts, Inspection Of	PA-32-260/300	11/10/67	760-162V		5710	3G5
275	Electrical System, Modification Of The	PA-32-260/300	06/19/68	**		2400	3H8
279	Bridle Cable, Servo. Inspection Of And Modification To	PA-32	06/24/68	**		2210	3H16
281	Artificial Horizon, R.C. Allen 3", Case Leakage Of	PA-32-260/300	07/10/68	**		3420	3H24
282	Mixture Control Cable, Replacement Of The	PA-32-300	08/12/68	760-235V		7320	3I4
285	Stop Assembly, Fuel Selector Control	PA-32-260	11/22/68	760-251V		2820	3I11
291	Flight Manual Revision	PA-32S-300 PA-32-260/300	03/28/68	760-313V		3250	3J5
295	Pin, Retaining, Control Wheel	PA-32-260"B" PA-32-300"B "	04/30/69	**	69-15-01	2700	3J14
305	Drain Plugs, Carburetor Inspection Of	PA-32-260	11/25/69			7310	3K12
311A	Selector Valve, Fuel, Modification	PA-32-260/300 PA-32S-300	04/28/70	760-438V		2820	3L3
317	Rib Inspection, Vertical Fin	PA-32-260/300	11/18/70	760-451V		5530	3L14
321A	Throttle Knob Roll Pin Retaining Ring	PA-32-260/300	11/02/70	756-044V		7610	4A1
322	Vacuum Pump Adapter Drive Assembly	PA-32-260/300	09/29/70	760-477V		3710	4A3

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
327	Stabilator Balance Weight Tube Assembly Inspection	PA-32-260/300 PA-32S-300	12/09/70	**	70-26-04	2740	4A16
329A	Belt Attachment Modification, Seat	PA-32-260/300 PA-32S-300	03/25/71	760-515V	71-09-05	5340	4A23
332	Switch, Electric Trim, Inspection And Modification	PA-32-260/300	04/16/71	760-517V	72-17-15	2730	4B7
337	Seat Frame Tube Replacement, Vertically Adjustable	PA-32-260/300	03/11/71	**		2510	4B20
342	Fuel System Instructions And Modification	PA-32-260/300 PA-32S-300	09/07/71	760-560V	77-12-01	2800	4C6
350	Stabilator Hinge Attaching Bolts, Inspection Of	PA-32-260/300	03/30/72	**		5550	4D7
356	Duct, Induction Air Inlet And Induction Alternate Heat, Inspection And Replacement	PA-32-260/300 PA-32S-300	09/01/72	**		7160	4E7
357A	Terminal Replacement, Alternator Output Wire	PA-32-260/300	11/14/72	588-398V		2420	4E9
360	Hose System Modification, Air Induction	PA-32-260/300 PA-32S-300	11/09/72	**		7160	4E14
368	Antenna Protector, Transponder, Installation	PA-32-260/300	11/22/72	760-697V		3450	4F7
376	Fuel Selector Control System Modification	PA-32-260/300 PA-32S-300	04/19/73	**	77-12-01	2820	4F18
387	Alternator Installation Modification	PA-32-260/300	02/04/74	760-742V		2430	4G15
395	Rudder Pedal, Warning Improper Use Of	PA-32-260/300	11/09/73	757-436V		2720	4H9
403	Stall Warning Light Relocation	PA-32-260/300	01/29/74	760-808V	74-09-02	2780	4I9
412	Glove Compartment Modification	PA-32-260/300	04/09/74	581-025		2510	4J12
427	Air Conditioning System Modification	PA-32-300	08/09/74	760-822V		2150	4K23
428	Steering System Modification	PA-32-260/300	70/30/74	760-885V	74-18-13	3250	4L1
444	Fuel Valve Replacement	PA-32-260/300	01/15/75	760-895V		2820	5A19
448	Cable Operation Inspection, Throttle And Mixture Control	PA-32-260/300	02/19/75	**		7320	5B4
449A	Alternator (Chrysler) Modification And Wire End Terminal Replacement	PA-32-260/300	05/07/75	558-398V		2430	5B8
463	Door Forward Baggage, Inspection And Modification	PA-32-260/300	04/17/75	760-972V	75-10-03	5230	5C14
469A	Oil Cooler Assembly Inspection	PA-32-300	09/05/75	**		7920	5D4
475	Instrument Panel Dimmer Control Assembly Modifications	PA-32-260/300	07/10/75			3310	5E1
503A	Fuel Tank Line Assembly, Inboard, Inspection Of	PA-32R-300	04/19/76	**	76-11-09	2810	5H5
510B	Landing Gear, Nose, Trunnion Modification	PA-32R-300	08/31/76	761-074V	76-15-08	3220	5I1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
519A	Fuel Selector Valve Inspection And Replacement	PA-32-260/300 PA-32R-300	09/02/76	**	76-18-04	2820	5I21
520	Muffler Shroud Inspection	PA-32-300 PA-32R-300	10/18/76	**		7810	5I23
524	Induction Air Box Bolt Replacement	PA-32-300 PA-32R-300	02/02/77	**		7160	5J9
533	Fuel Gauge Calibration Inspection	PA-32-260/300	01/06/77	**	77-01-01	2840	5L8
537	Throttle Linkage Bolt Replacement	PA-32-300 PA-32R-300	01/12/77	**	80-14-02	7610	5L17
538	Engine Control Cable Inspection	PA-32-260/300 PA-32R-300	01/14/77	**		7610	5L20
541	Throttle Attachment Inspection	PA-32-260	02/15/77	**		7610	6A5
543	Starter/Magneto Switch Inspection And Replacement	PA-32-260/300 PA-32R-300	02/09/77	757-597V		7410	6A9
548	Engine Control Rod End Bearing Inspection	PA-32-260/300 PA-32R-300	03/07/77	**	77-23-03	7230	6A23
556	Electric Trim Switch Modification	PA-32-260/300	07/25/77	756-047		2730	6B20
557	Fuel Line Modification	PA-32-260	05/19/77	63882-17V		2810	6B23
563	Landing Gear, Nose, Actuator Rod End Bearing Change	PA-32R-300	05/13/77	452-357V		3230	6C14
565	Horizontal Situation Indicator, Modification To Edo Aire Mitchell; Edo Aire Mitchell Service Bulletin No. MB-13	PA-32-260/300 PA-32R-300	06/02/77	**		3420	6C20
571A	Fuel Valve Leak Check/Fuel Cap Replacement/Fuel Tank Vent Check/Fuel Line Inspection	PA-32-300 PA-32S-300	05/26/77	**	77-12-01	2810	6E5
580	Engine Cowling Scoop Drain Hole	PA-32-260	10/19/77			7100	6F13
586B	Engine Oil Coolers (Left and Right), Inspection Of The	PA-32R-300	07/24/78	16599-00V	78-01-03 78-16-08	7920	6F24
593	Nose Landing Gear Lock Hook Replacement	PA-32R-300	06/09/78			3230	6H1
616	Hydraulic Pressure Switch Inspection And Nose Gear Actuator Rod End Bearing Replacement	PA-32RT-300 PA-32RT-300T	05/01/79			2930 3230	6J19
619	Control Column Stop Modification	PA-32RT-300 PA-32RT-300T	09/22/78	763-895V	78-22-07	2710	6K4
622	Pitch Trim Re-Wiring On Aircraft Equipped With Altimatic 111C	PA-32-260/300 PA-32R-300	09/28/78	35669-60 35669-61		2210	6K14
624	Loading Limitation Placard And Manual Change	PA-32-260/300 PA-32S-300	05/24/79	763-911V		0800	6K19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
630A	Collins VIR-350 And VIR-351 Navigation Receiver Modification	PA-32-260/300 PA-32R-300 PA-32RT-300 PA-32RT-300T	02/25/80			3450	6L14
646A	Fuel Tank Vent Modification And Vent Hose Replacement	PA-32-260/300 PA-32R-300 PA-32RT-300 PA- 32RT-300T	03/05/80	**	80-14-01	2810	7C17
652	Fuel Flow Indicator Line- Replacement	PA-32RT-300T	06/15/79	67700-348	79-13-04	7330	7D9
655	Firewall Reinforcement	PA-32RT-300T	08/27/79	763-935V		5410	7D15
656	Window Curtain Rod Support Area Inspection	PA-32-260/300 PA-32R-300 PA-32RT-300 PA-32RT-300T	09/13/79	**		5520	7D17
657A	Turbo-Charger Exhaust Coupling And Tailpipe Flange Inspection	PA-32RT-300T	08/14/79	556-108		7810	7E1
669	Altimatec IIIC Autopilot Trim Servo Cable Alignment Modification	PA-32-300 PA-32R-300 PA-32RT-300 PA-32RT-300T	01/14/80	**		2210	7F10
675	Throttle Operation Pre-And Post-Flight Check	PA-32RT-300T PA-32R-301T	02/19/80	67639-013V		7610	7G21
677	Publications for Aircraft Operation	All Piper Models	05/20/80			PARA 15.0	7H4
681	Boom Microphone Isolation Relay	PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	04/24/80	456-703	80-14-03	2350	7H11
701	Rudder/Aileron Interconnect Bracket Interference	PA-32-301 PA-32-301T	12/04/80	68525-08V 419-948		2720 2710	7K16
703	Aileron BalanceWeight Attachment Inspection and Rework	PA-32-301 PA-32-301T PA-32R-301 PA-32R-301T	03/04/81	764-091V		2710	7K20
738	Part I: Nose Landing Gear Actuator Rod End Replacement	PA-32R-301 PA-32R-301T	04/20/82	452-729V		3230	8D14
738	Part II: Nose Landing Gear Actuator Rod End Inspection/Replacement	PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	04/20/82	452-729V		3230	8D15

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
747	Nose Landing Gear Actuator Attach Bolt Replacement	PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	09/17/82	86700-46V 402-869V		3230	8G3
772	Fuel Selector Inspection/Replacement	PA-32R-300 PA-32-301 PA-32-301T PA-32R-301 PA-32R-301T	04/06/84	69735-05V		2820	8J3
789A	Aft Inboard Wing Access Panel & Aft Wing Spar Modification	PA-32-260 PA-32-300	05/07/85	765-106V		5711	8L16
798	"TURBO" Marking Removal	PA-32RT-300T	12/11/84	N/A		1110	9B19
801	King Auto Pilot Servo Bridle Clamp Installation	PA-32-301/301T PA-32R-301/301T	12/11/84	**		2200	9C6
804	Battery Strap Installation	PA-32-301T	04/26/85	765-157		2430	9D12
805A	TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration)	PA-32-260 PA-32-300 PA-32-301/301T PA-32R-300 PA-32RT-300/300T PA-32R-301/301T	03/14/86	N/A		6110	9D15
811A	Ammeter Replacement	PA-32-260 PA-32-300 PA-32R-300 PA-32RT-300/300T PA-32-301/301T PA-32R-301/301T	05/12/86	**	86-17-01	2430	9F4
836A	Aluminum Wire Inspection/Replacement	PA-32-301T	08/26/86	**		2400	9J4
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	01/14/87	N/A		2800	10A7
856	Stabilator Attach Fitting Corrosion Inspection	PA-32-260 PA-32-300 PA-32-301/301T PA-32R-300 PA-32R-301/301T	02/17/87	**		5550	10A9
866A	Part I - Back Up Landing Gear Extender Removal	PA-32R-300 PA-32RT-300/300T PA-32R-301/301T	03/04/88	765-199		3236	10B22
866A	Part II - Alternate means of Compliance	PA-32R-300 PA-32RT-300/300T PA-32R-301/301T	03/04/88	N/A		3236	10B22
884	Lock Wiring Of V-Band Couplings	PA-32-301T PA-32R-301T PA-32RT-300T	04/08/88	**		7800 2100	10G20
886	Wing Spar Inspection	PA-32-260/300	06/08/88	**		5711	10H3

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
896	Shoulder Harness Installation & Usage	PA-32-260/300 PA-32-301/301T PA-32R-300 PA-32RT-300/300T PA-32R-301/301T	11/28/88	**		5340	10I13
904	Textron Lycoming Service Bulletin No. 484	PA-32-301T PA-32RT-300T PA-32R-301T	03/20/89	**		7821	10K1
906	Oildyne Hydraulic Pump Replacement	PA-32R-301 PA-32R-301T	04/10/89	**		2911	10K12
926A	Hartzell Service Bulletin No. 165E, Inspection for Cracks in Certain Three Blade "Y" Shank Aluminum Propeller Hubs	PA-32-301T PA-32R-301T	03/07/94	**		6113	10aC1
927	Hartzell Service Bulletin No. 164, Inspection for Cracks in Certain Two Blade "Y" Shank Aluminum Propeller Hubs	PA-32-300 PA-32S-300 PA-32R-300 PA-32RT-300/300T PA-32-301/301T PA-32R-301/301T	12/04/89	**		6113	10aC18
933A	Trunnion Replacement	PA-32R-301	02/20/90	67054-03		3222	10aD21
938	Wire Protection	PA-32R-301 PA-32R-301T	06/12/90	189-531 488-698		3262	10aE15
946	Forward Left Fuselage Frame Inspection and Replacement	PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	03/04/91	766-244		5311	10aG11
952	Textron Lycoming Service Bulletin No. 499 "Installation of One-Piece Exhaust Pipe"	PA-32RT-300T PA-32-301T PA-32R-301T	05/09/91	**		7821	10aH11
955	Engine Mount and Nose Landing Gear Attachment	PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	03/03/92	766-252 766-253	93-05-10	7120	10aH23
965	Inspection of Flap Lever and Bolt	PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	09/01/93	**		2750	10aJ22
968	Exhaust System Hardware and Gasket Replacement	PA-32R-301	03/11/94	**		7810	10aK21
970	Defrost System Modification	PA-32R-301	04/18/94	**		7810	10aL2
971	Exhaust System Inspection and Replacement	PA-32R-301	09/02/94	**		7810	10aL5

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
973	Engine Lower Cowling Modification	PA-32R-301	09/30/94	**		7810	10aL19
977	Inspection of Wing Rear Attach Fitting and Addition of Inspection Access Panels	PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	12/12/94	**		5740	10bA12
986	Inspection for Proper Orientation of Battery Vent Tube Assembly	PA-32R-301 II HP	09/06/95			2430	10bC22
990	Pacific Scientific Seat Belt Replacement	PA-32R-301 II HP	01/03/96	**		5346	10bD12
993	KLN-90B GPS Wiring Modification	PA-32R-301	03/18/96	**		3441	10bE4
996	Missing Rivet in Upper Door Frame, Forward and Aft	PA-32R-301 II HP	09/17/96	**		5311	10bE16
1005	Addition of Drain Holes to the Engine Induction Air Inlet Scoops	PA-32R-301 II HP	08/11/97			7162	10BG4
1006	Corrosion Inspection of Main Spar Behind Fuel Tanks	PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T PA-32R-301T II TC	08/15/97	**		0530	10bG4
1009	Replacement of the Engine Induction Air Inlet Elbow at the Fuel Injector Servo	PA-32R-301 II HP	10/06/97	**		7161	10bG18
1011	Inspection and Replacement of the Aileron Inboard Hinge Nose Rib Nutplates	PA-32-301 PA-32-301T PA-32R-301 SP PA-32R-301T SP PA-32R-301 II HP PA-32R-301T II TC	11/14/97	**		5755	10bG23
1015A	Replacement of the Ammeter Shunt Wire Fuse Assemblies	PA-32R-301 II HP	03/06/98	101166-10 101166-11		2434	10bH14
1018A	Product Improvement, Winterization Plate Kit(Revised)	PA-32R-301 II HP PA-32R-301T II TC	06/07/99	766-653		7921	10bI2
1020	Inspection of the ARTEX 110-4 ELT and ELT Attachment Bracket	PA-32R-301 II HP PA-32R-301T II TC	07/10/98	766-653		2563	10bI11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1022	Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01	PA-32-260 PA-32-300 PA-32-301 PA-32R-300 PA-32RT-300 PA-32R-301 SP PA-32R-301 II HP	09/22/98	460-632	99-05-09	7167	10bI20
1023	Inspection of Landing Gear Cylinders and Distribution of Parker Hannifin Service Bulletin SB7063	PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC	10/08/98	**		2902	10bJ6
1024	Replacement of Control System Spacers and Inspection of Aileron Cables	PA-32R-301 II HP PA-32R-301 II TC	10/01/98	**		2712	10bJ12
1025	Replacement of the Alternate Air Door	PA-32R-301T	11/21/98	**		7164	10bJ16
1026	Distribution of Parker Hannifin Airbourne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings".	PA-32-260 PA-32-300 PA-32-301 PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC	11/05/98	753-910		3711	10bJ20
1028	Inspection of the Aileron Control Rod Attach Fitting and the Addition of Safety Clips	PA-32R-301 II HP PA-32R-301T II TC	12/02/98	**		5755	10bK12
1030A	Distribution of Textron Lycoming Service Bulletin 538A, "Air Inlet tube Replacement" and Drain Improvement	PA-32R-301T II TC	09/10/99	**		7168	10bK21
1031	Horizon Engine Instruments Repair or Replacement	PA-32R-301 II HP PA-32R-301T II TC	07/14/99	**		7710/7720	10bL3
1035	Distribution of Textron Lycoming Service Bulletin 529A, "Repair of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 2"	PA-32-301T PA-32R-301T SP PA-32R-301T II TC PA-32RT-300T	09/03/99	**		7311	10bL17
1036	Garmin Service Bulletin No. 9905 'GNS430 Mod. 1"	PA-32R-301 II HP PA-32R-301T II TC	10/01/99			3426	10cA1
1039	Manifold Pressure Gauge (MAP) Wiring Modification	PA-32R-301 II HP PA-32R-301T II TC	02/14/00			7715	10cA15

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-32-260 PA-32-300/-32S-300 PA-32-301 PA-32-301T PA-32RT-300 PA-32RT-300T PA-32R-300 PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC	09/25/00	**		3714	10cB1
1048	Stainless Steel Control Cables	PA-32R-301 SP PA-32R-301 II HP PA-32R-301T II TC	01/03/01	N/A		2702	10cC9
1049	Engine Baffle Brace Installation	PA-32R-301 II HP PA-32R-301T II TC	04/09/01	766-684		7236	10cC13
1081A	Horizon Aerospace Analog Instrument Pointer Calibration	PA-32R-301 II HP PA-32R-301T II TC	12/09/02	N/A		7700	10cl12
1083C	S-TEC System 55X Autopilot	PA-32R-301 II HP PA-32R-301T II TC	05/30/02	767-318		2218	10cl19
1092B	Engine Mount Inspection	PA-32R-301 SP PA-32R-301 II HP PA-32R-301T II TC	04/28/03	38729-021 38729-022 104642-002		7121	10cK22
1131	Inspection of Cast Main Landing Gear Strut Cylinders (P/N's 65319-002, 65319-003, and 65319-004)	PA-32-260	08/18/03	65489-002 65490-000		3210	10dF10
1134	Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105)	PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 SP PA-32R-301 II HP PA-32R-301T SP PA-32R-301T II TC	06/10/03	**		2800	10dG1
1135	GMA-340 Audio Panel Wiring	PA-32R-301 II HP PA-32R-301T II TC	07/16/03	N/A		2370	10dG9
1137	Stabilator Balance Weight Tube Assembly	PA-32R-301 II HP PA-32R-301T II TC	11/06/03	N/A		2749	10dG16
1139	Control Wheel Attachment Inspection	PA-32R-301 II HP PA-32R-301T II TC	08/28/03	**		2701	10dH1
1141	Clip Nut Replacement	PA-32R-301 II HP PA-32R-301T II TC	12/09/03	477-640		5351	10dH11
1145A	Autopilot Installation and Testing	PA-32-301FT PA-32-301XTC	02/17/04	600-520 692-411		2210	10dH24

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

THIS PAGE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
350	Stabilator Hinge Attaching Bolts Inspection of	PA-34	03/30/72	**		5550	4D7
352	Pitot Static System Lines Replacement	PA-34	06/13/72	760-614V 760-615V		3030	4D12
357A	Terminal Replacement, Alternator Output Wire	PA-34	11/14/72	588-398V		2420	4E9
358	Induction Air Box Valve Inspection	PA-34	07/31/72	96776-00V	72-17-01	7160	4E11
359	Pitot Static System Instrument Lines Modification	PA-34	10/10/72	760-679V		3410	4E13
364A	Circuit Breaker Replacement, Fuel Pump, Electric	PA-34	11/16/72	454-707		2820	4F1
367	Stabilator Tip Balance Weight Inspection	PA-34	08/25/72	**	72-18-06	2740	4F5
368	Antenna Protector, Transponder Installation	PA-34	11/22/72	760-697V		3450	4F7
369	Wing Assembly, Aft, Inspection and Modification of	PA-34	09/08/72	760-696V	73-11-02	5110	4F8
370	Fuel Injector Servo Mounting Nut Inspection	PA-34	09/12/72			7310	4F10
373A	Exhaust System Inspection	PA-34	06/12/73	**	73-14-02	7810	4F12
374	Induction Air Box Replacement	PA-34	02/02/73	760-722V	72-17-01	7160	4F14
382	Fuel Tank Vent Systems, Inspection	PA-34	08/22/73			2810	4G2
390A	Trim Tab, Rudder Servo, Inspection	PA-34	05/30/73	**	73-13-01	2210	4G20
395	Rudder Pedal, Warning, Improper Use of	PA-34	11/09/73	757-436		2720	4H9
406	Oleo Struts, Main Landing Gear, Inspection and Maintenance of	PA-34	11/16/73	**	73-11-02	3210	4I15
412	Glove Compartment Modification	PA-34	04/09/74	581-025		2510	4J12
413	Nose Gear Drag Link Assembly Dimension Check	PA-34	04/16/74			3220	4J14
429	Fuel Line Chafing—Engine Nacelles, Prevention of	PA-34	08/12/74	760-877V 760-886V	74-17-08	2810	4L3
437A	Spar Straps, Inspection of Seneca	PA-34	10/16/75			5710	5A1
438	Fuel Quantity, Revised Usable	PA-34/34T	08/06/75	**	75-20-03	2840	5A6
447	Baggage Door Inspection and Modification to the Forward	PA-34/34T	02/07/75			5230	5B1
475	Instrument Panel Dimmer Control Assembly Modification	PA-34/34T	07/10/75			3310	5E1
483	Turbocharger Oil Hose Modification, Seneca II	PA-34-200T	11/12/75	761-023V	75-25-03	8010	5E23
491	Pneumatic Deicer Tubing Inspection	PA-34-200T	02/19/76	761-018V		3700	5F16

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
542	Induction Air Box Filter Locator Change	PA-34-200T	02/25/77	761-130V		7160	6A7
545	Fuselage Rivets, Inspection and Installation	PA-34/34T	02/23/77	522-898		5330	6A13
548	Engine Control Rod End Bearing Inspection	PA-34/34T	03/07/77	452-557	77-23-03	7230	6A23
553	Avionics Bus Bar Inspection and Modification	PA-34/34T	04/15/77	761-133V		2450	6B13
555	Rudder Cable Guard Inspection, Seneca II	PA-34-200T	03/09/77	62701-72V		2720	6B17
565	Horizontal Situation Indicator Modification to Edo Aire Mitchell; Edo Aire Mitchell Service Bulletin No. MB-13	PA-34-200T	06/02/77	**		3420	6C20
576	TCM TS10360 Series Engines To Disseminate Information	PA-34-200T	11/30/77			7200	6E23
579	Inspection of Vertical Fin and Stabilator Attachment Fittings	PA-34-200/200T	11/14/77	**	80-09-04	5550	6F5
584	Engine Instruments and Fuel Flow Line Inspection and Modification	PA-34-200T	12/13/77	**		7330 7700	6F20
596A	Fuel Line Inspection and Modification	PA-34-200T	09/22/78	**	78-21-03	2810	6H6
601	Inspection of Battery Box Vent	PA-34-200T	08/11/78		78-21-03	2430	6H20
602	Inspection of the Main Wing Spar Attaching Nuts	PA-34-200T	07/03/78	404-532V		5750	6I1
611	Hose Assembly Inspection and Replacement	PA-34-200T	11/14/78	**		2820	6J5
630A	Collins VIR-350 and VIR-351 Navigation Receiver Modification	PA-34-200T	02/25/80			3450	6L14
633B	Forward Baggage Door Inspection and Modification	PA-34-200 PA-34-200T	10/03/80	36521-02V	88-04-05	5230	7A10
656	Window Curtain Rod Support Area Inspection	PA-34-200T	09/13/79	**		5520	7D17
668	Avionics Master Relay Wiring Inspection	PA-34-200T	11/12/79			2450	7F6
669	Altimatec IIIC Autopilot Trim Servo Cable Alignment Modification	PA-34-200T	01/14/80	**		2210	7F10
677	Publications for Aircraft Operation	All Piper Models	05/20/80			PARA 15 0	7H4
681	Boom Microphone Isolation Relay	PA-34-200T	04/24/80	456-703 180-500	80-14-03	2350	7H11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
711	Missing Rivets, Left Hand Fuselage Station 108	PA-34-220T	03/27/81	**		5330	8A3
712A	Fuel Selector Valve Inspection and Cable Clevis Replacement	PA-34-220T	04/20/81	491-960V 764-121V		2820	8A7
718A	Seneca III Surface Deicer System	PA-34-220T	10/29/81	764-222V		3000	8B1
732	Landing Gear Selector Switch Shield	PA-34-220T	11/11/81	87431-02V 488-702V	82-04-08	3200	8C23
758	Radio Master Relay Replacement	PA-34-220T	02/14/83			2450	8H10
762	Exhaust System Heat Exchanger Inspection	PA-34-200	05/26/83	78463-10V 78463-18V	83-14-05	7810	8H21
787C	Main Landing Gear Trunnion Housing	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T IV	11/07/00	02599-002	94-13-11	3211	8L8
798	"TURBO" Marking Removal	PA-34-200T	12/11/84	N/A		1110	9B19
801	King A/P Servo Bridle Clamp Installation	PA-34-220T	12/11/84	**		2200	9C6
805A	TRW Hartzell Propeller Service Bulletin No 142B (O-ring Deterioration)	PA-34-200 PA-34-200T PA-34-220T	03/14/86	N/A		6110	9D15
811A	Ammeter Replacement	PA-34-200T	05/12/86	**	86-17-01	2430	9F4
836A	Aluminum Wire Inspection/Replacement	PA-34-200 PA-34-200T PA-34-220T	08/26/86	**		2400	9J4
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	01/14/87	N/A		2800	10A7
856	Stabilator Attach Fitting Corrosion Inspection	PA-34-200 PA-34-200T PA-34-220T	02/17/87	**		5550	10A9
872	Forward Baggage Compartment Door Latch Spring Installation And Door Assembly Inspection	PA-34-200 PA-34-200T PA-34-220T	11/09/87	765-330	88-04-05	5230	10D5
884	Lock Wiring Of V Band Couplings	PA-34-200T PA-34-220T	04/08/88	**		7800 2100	10G20
893	Nose Gear Centering Attach Belt	PA-34-200 PA-34-200T	10/11/88	400-910	92-13-05	3220	10I3
896	Shoulder Harness Installation & Usage	PA-34-200 PA-34-200T PA-34-220T	11/28/88	**		5340	10I13
899	Rudder Torque Tube Fitting Replacement	PA-34-200 PA-34-200T PA-34-220T	02/10/89	**	92-08-04	2720	10J8

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
905	Auxiliary Primer Switch Replacement	PA-34-200T PA-34-220T	04/06/89	**		7315	10K7
906	Oildyne Hydraulic Pump Replacement	PA-34-200T PA-34-220T	04/10/89	**		2911	10K12
938	Wire Protection	PA-34-220T	06/12/90	189-531 488-698		3262	10aE1
956	Main Landing Gear Trunnion Attach Fittings	PA-34-200 PA-34-200T PA-34-220T	03/03/92	**		3211	10aH10
965	Inspection of Flap Lever and Bolt	PA-34-200 PA-34-200T PA-34-220T	09/01/93	**	96-10-03	2750	10aJ3
976	Inspection for and Replacement of Components with Suspect "O" Rings	PA-34-220T	12/09/94	**		2911	10bA10
977	Inspection of Wing Rear Attach Fitting and Addition of Inspection Access Panels	PA-34-200 PA-34-200T PA-34-220T	12/12/94	**		5740	10bA12
983	Station 49.5 Frame Inspection	PA-34-220T	05/25/95	**		5310	10bC4
987	Prop Deice Timer Wiring Inspection	PA-34-220T III PA-34-220T IV	09/11/95	**		3000	10bD1
988	Pneumatic Deice Switch Relocation	PA-34-220T III PA-34-220T III (28V) PA-34-220T-IV	11/15/95	558-790 179-771		3013	10bD4
989	Inspection for Stabilator Trim Screw Assembly Attachment Hardware	PA-34-220T IV	12/20/95	**		2791	10bD8
990	Pacific Scientific Seat Belt Replacement	PA-34-220T IV	01/03/96	**		5346	10bD12
993	KLN-90B GPS Wiring Modification	PA-34-220T IV	03/18/96	**		3441	10bE4
996	Missing Rivet in Upper Door Frame, Forward and Aft	PA-34-220T (IV)	09/12/96	**		5311	10bE16
1005	Addition of Drain Holes to the Engine Induction Air Inlet Scoops	PA-34-220T (V)	08/11/97			7162	10bG1
1010	Replacement of Fuel Selector Levers	PA-34-220T V	11/03/97	766-645		2822	10bG21
1013	Replacement of Crankcase Breather System	PA-34-220T V	02/05/98	**		7925	10bH6
1014	Replacement of Battery Power Fuse	PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	03/02/98	461-681		2436	10bH11
1017	Alternator Regulator Wiring Diagram	PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	04/10/98	**		2436	10bH21
1020	Inspection of the Artex 110-4 ELT and ELT Attachment Bracket	PA-34-220T IV PA-34-220T V	07/10/98	**		2563	10bI11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1022	Inspection of Induction Air Filter and Distribution of Purolator Service Bulletin, SB090298.01	PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	09/22/98	460-632	99-05-09	7167	10bI20
1023	Inspection of Landing Gear Cylinder and Distribution of Parker Hannifin Service Bulletin SB7063	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	10/08/98	**		2902	10bJ6
1026	Distribution of Parker Hannifin Airbourne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings".	PA-34-200 PA-34-200T PA-34-220T III(28V) PA-34-220T IV	11/05/98	753-910		3711	10bJ20
1031	Horizon Engine Instruments Repair or Replacement	PA-34-220T V	07/14/99	**		7710 7720	10bL3
1038	Inspection and Modification of the Aft Spinner Bulkhead	PA-34-220T V	11/15/99	**		6117	10cA9
1039	Manifold Pressure Gauge (MAP) Wiring Modification	PA-34-220T V	02/14/00			7715	10cA15
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	09/25/00	**		3714	10cB1
1042	Heated Deice Panel Inspection	PA-34-220T V	06/09/00	31637-003		3041	10cB10
1043	Deice Control Valve Replacement	PA-34-220T V	07/13/00	**		3014	10cB15
1048	Stainless Steel Control Cables	PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	01/03/01	N/A		2702	10cC9
1081A	Horizon Aerospace Analog Instrument Pointer Calibration	PA-34-220T V	12/09/02	N/A		7700	10cI12
1083C	S-TEC System 55X Autopilot	PA-34-220T V	05/30/02	767-319		2218	10cI19
1097A	Pneumatic Deicer Deflate Valve Assembly Replacement	PA-34-220T V	02/25/02	592-676		3010	10cL16
1100A	Stabilator Trim Link Assembly	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	10/31/01	96003-000		5511	10cL12
1113	Nose Gear Down Lock Pin Inspection	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	06/05/02	95829-000 95830-000		3235	10dC3

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1123	Nose Gear Inspection and Product Improvements	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	05/07/03	767-357 767-358 767-359 767-368 693-215 95394-005	93-24-14	3220	10dD18
1127A	Combustion Heater Fuel Pump Leakage (Kelly Aerospace SIL A-110A)	PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	07/18/03	767-367 **	03-11-14	2800	10dE13
1130	Vertical Fin Contour / Rivet Check	PA-34-200 PA-34-200T PA-34-220T III PA-34-220T III (28V) PA-34-220T IV PA-34-220T V	11/11/03	767-369		5300	10dF4
1134	Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105)	PA-34-200	06/10/03	**		2800	10dG1
1135	GMA-340 Audio Panel Wiring	PA-34-220T V	07/16/03	N/A		2370	10dG9
1136	Auxiliary Fuel Pump Switch	PA-34-200T	09/02/03	588-006 (99377-029)		2800	10dG13
1137	Stabilator Balance Weight Tube Assembly	PA-34-220T V	11/06/03	N/A		2749	10dG16
1139	Control Wheel Attachment Inspection	PA-34-220T V	08/28/03	**		2701	10dH1
1141	Clip Nut Replacement	PA-34-220T V	12/09/03	477-640		5351	10dH11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
396	Propeller Stop, Low Pitch	PA-36-285	01/29/74			6110	4H11
397	Fuel Quantity Placards, Revised	PA-36-285	05/02/74	**	74-13-07	2840	4H12
402	Starter Shaft Inspection Tiara (Continental Aircraft Engine Service Bulletin #M73-20)	PA-36-285	10/05/73	**		8010	4I4
418	Lift Detector Relocation And Modification	PA-36-285	08/13/74	760-843V	74-21-02	2700	4K1
425	Wing Spar Center Section Bolts, Replacement Of	PA-36-285	06/14/74	760-871V	74-14-06	5750	4K18
439	Flap Control System, Modification Of The	PA-36-285	12/27/74	760-903V	75-01-02	2750	5A8
467	Spray Pump Windmill Assembly Modification	PA-36-285	10/29/75	**		0910	5C24
471A	Wing Attachment Fittings, Forward And Aft, Inspection And Modification	PA-36-285	07/16/76	**	77-02-06	5750	5D15
472	Main Spar Center Section Carry Through Assembly Modification Of	PA-36-285	6/6/75	760-978		5310	5D18
482	Control Stick Torque Tube Inspection Of	PA-36-285	10/22/75	**		7610	5E21
489	Muffler Clamp Installation	PA-36-285	3/12/76	761-017		7810	5F13
490	Safety Harness Installation Modification	PA-36-285	6/30/76	761-022 761-057		5340	5F14
495B	Rudder Control Horn Attachment Bolts, Inspection Of	PA-36-285/300 PA-36-375	7/13/81	**	76-05-07	2720	5G11
499	Induction Air Filter Cover Assembly	PA-36-285	3/18/76			7160	5G20
501	Wing Main Spar Lower Bolt Replacement	PA-36-285	4/27/76	761-058	76-25-02	5750	5H1
505	Precautionary Operating Placard Installation	PA-36-285	4/29/76	98000-62		1130	5H10
506	Tail Structure Modification	PA-36-285	8/23/76	761-034 761-067	77-04-02	3270	5H12
508	Fuel Tank Vents, Inspection Of	PA-36-285	6/15/76			2810	5H19
513	Engine Air Induction System Modification	PA-36-285	7/15/76	761-053		7160	5I6
516	Control Rod End Bearing	PA-36-285	1/20/77	761-095		7200 2140 2730 2710	5I13
518	Rudder Spar Hinge Inspection	PA-36-285	2/22/77	98125-04	77-21-03	5550	5I19
539	Fuel Quantity Gauge Inspection	PA-36-285	1/27/77	76784-02		2840	5L23
546	Wing Wing Tip Strobe Lights Reference FAA Airworthiness Directive, Inspection Of	PA-36-285/300	5/18/77	**		3340	6A16

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
552	Wing Spar Carry Through Assembly Inspection Of	PA-36-285	02/03/78	**	79-01-03	5710	6B9
583	Voltage Regulator/Over Voltage Relay Rewiring	PA-36-300	10/31/77	**		2430	6F18
587	Exhaust Stack Modification	PA-36-300	02/06/78	**		7810	6G5
608A	Inspection/Replacement Of Elevator And Aileron System Control Rod End Bearings	PA-36-285/300 PA-36-375	09/29/78	**	78-26-05	2710	6I18
615	Inspection Of Engine Mount And Modification If Required	PA-36-285	09/21/78	763-887	79-12-09	7120	6J16
630A	Collins VIR-350 And VIR-351 Navigation Receiver Modification	PA-36-300 PA-36-375	02/25/80			3450	6L14
677	Publications for Aircraft Operation	All Piper Models	05/20/80			PARA 15.0	7H4
713	Fuel Cell Inspection and Servicing	PA-36-285/300 PA-36-375	05/11/81	97989-00 97989-01		2810	8A10
729	Rudder Cable and Seat Belt Attachment Shackle Inspection	PA-36-285/300 PA-36-375	09/22/81	486-566		2720	8C17
744	Wing Spar and Wing Spar Carry-Through Assembly and Components Replacement	PA-36-285/300 PA-36-375	05/12/82	**		5710	8F14
771	Parking Brake Application	PA-36-285/300	05/19/84	81090-02	85-02-05	1130	8J1
797B	Fuel Port Restrictor Installation	PA-36-285/300 PA-36-375	09/01/87	566-502		2812	9B14
805A	TRW Hartzell Propeller Service Bulletin No. 142B (O-ring Deterioration)	PA-36-285/300 PA-36-375	03/14/86	N/A		6110	9D15
828	Fuselage Tubing Crack Inspection	PA-36-300 PA-36-375	04/07/86	**	92-15-15	5345	9I1
836A	Aluminum Wire Inspection/Replacement	PA-36-285/300 PA-36-375	08/26/86	**		2400	9J4
855	Use of Automobile Gasoline In Piper Aircraft	All Piston Powered Models	01/14/87	N/A		2800	10A7
926A	Hartzell Service Bulletin No. 165E, Inspection for Cracks in Certain Three Blade "Y" Shank Aluminum Propeller Hubs	PA-36-285 PA-36-300 PA-36-375	03/07/94	**		6113	10aC1
1035	Distribution of Textron Lycoming Service Bulletin 529A, "Repair of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 2"	PA-36-375	09/03/99	**		7311	10bL17
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-36-285 PA-36-300 PA-36-375	09/25/00	**		3714	10cB1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

THIS PAGE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

THIS PAGE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
600A	Aft Fuselage/Tail Cone Area Rivet Replacement	PA-38-112	04/28/78			5350	6H16
603	Fuel Gauges And Instrument Cluster Grounding Harness Installation	PA-38-112	07/25/78	**	79-17-05	2840 3310	6I2
607A	Part I - Inspect And Attain Clearance Between The Rudder Leading Edge And The Vertical Fin Trailing Edge	PA-38-112	06/02/78				6I13
607A	Part II - Install Straps To Maintain Clearance Between Rudder Leading Edge And Vertical Fin Trailing Edge	PA-38-112	06/02/78			2730	6I14
607A	Part III - Inspect And Attain Clearance Between Elevator Leading Edge And Stabilizer Trailing Edge	PA-38-112	06/02/78	763-872		2720	6I15
609A	Pilot And Copilot Control Wheel Replacement Modification	PA-38-112	07/31/78	**		2700	6I23
610	Gascolator Fuel Line Installation Inspection	PA-38-112	07/18/78	462-049		7310	6J2
613A	Installation Of Bearing Retention Plates On Bottom Rudder Hinge Bracket Assembly	PA-38-112	01/11/80	763-881	79-03-02	5550	6J12
614	Inspection Of Throttle And Mixture Control Placards For Proper Placement	PA-38-112	08/11/78	**		7610 7320	6J14
617B	Engine Mount Inspection/ Replacement	PA-38-112	01/30/81	**	81-23-07	7120	6J22
618	Inspection Of Left And Right Wing Rear Spar Attach Fittings	PA-38-112	09/05/78	**		5110	6K1
620	Tomahawk Magneto Replacement	PA-38-112	10/26/78	**		7410	6K6
628A	Inspection Of Vertical Fin Forward Spar Attachment Plate	PA-38-112	11/08/78	77553-05		5530	6L7
630A	Collins VIR-350 And VIR-351 Navigation Receiver Modification	PA-38-112	02/25/80			3450	6L14
637	Part I - Inspection of Upper Forward Vertical Fin Spar Attach Fitting	PA-38-112	12/29/78	77615-07	79-08-02	5510	7B5
637	Part II - Inspection Of Vertical Fin/Fuselage And Horizontal Tail/Vertical Fin Spar Attach Fitting Bolt	PA-38-112	12/29/78		79-08-02	5510	7B7
661	Control Column Installation Modification	PA-38-112	08/22/79		85-11-06	2700	7E12
673B	Replacement of Main Landing Gear Attachment Clamp, Bolts, And Barrel Nuts	PA-38-112	10/02/86	765-171 765-172	90-19-03	3210	7G11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
676	Nose Gear Strut Modification	PA-38-112	06/05/80	764-007		3220	7H1
677	Publications for Aircraft Operation	All Piper Models	05/20/80			PARA 15.0	7H4
686	Upper Rudder Hinge Bracket Replacement	PA-38-112	05/23/80	**	98-03-16 80-22-13	5550	7I20
709	Aileron Torque Tube Bearing Inspection	PA-38-112	07/13/81	**		2710	7L21
710	Vertical Fin Forward Spar Attachment Plate Replacement Life Limits	PA-38-112	10/10/82	**	82-27-08	5530	8A1
723	Aileron Balance Weight Rib Inspection/Reinforcement	PA-38-112	08/19/81	**	82-02-01	2710	8B18
745	Part I - Forward Fin Spar Inspection Piper Part No. 77601-03	PA-38-112	10/10/82	764-427	82-27-08	5510	8F19
745	Part II-Fuselage Bulkhead Assembly Inspection, Piper Part No. 77553-02	PA-38-112	10/10/82	77553-06	82-27-08	5310	8F20
745	Part III - Fin Spar Attachment Plate Replacement Piper Part No. 77553-05	PA-38-112	10/10/82	77553-05	82-27-08	5510	8F20
745	Part IV-Aft Vertical Fin Spar Inspection, Piper Part No. 77601-02	PA-38-112	10/10/82	**	82-27-08	5510	8F21
748	Radio Support Installation	PA-38-112	08/04/82	477-673		2320	8G6
760	Throttle Cable Inspection Replacement of Jam Nut	PA-38-112	04/16/84	02458-02		7610	8H15
763A	Upper Forward and Aft Vertical Fin Spar Inspection and Reinforcement	PA-38-112	07/25/83	764-965	83-19-01	5530	8I1
800	Elevator Control Travel Modification	PA-38-112	11/19/84	76193-02	85-11-06	2730	9C4
813	Throttle Cable Installation Inspection	PA-38-112	01/03/86	77907-002		7612	9F14
834	Rear Spar Frame Stiffener Installation (Fuselage Station 99.29)	PA-38-112	04/22/86	765-177		5310	9I23
836A	Aluminum Wire Inspection/Replacement	PA-38-112	08/26/86	**		2400	9J4
851	Carburetor Air Box Valve Assembly Inspection/Modification	PA-38-112	10/09/86	**		7163	9L16
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	01/14/87	N/A		2800	10A7
879	Rivet Inspection - Wing Skin To Spar, Top Inboard	PA-38-112	01/22/88	**		5730	10G3
890	Forward Tunnel Inspection and Flap Handle Cover Rework	PA-38-112	07/07/88	765-358		2752	10H20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
891	Wiring Modification Wing To Main Wire Harness Connectors	PA-38-112	07/15/88	764-530		2453	10H22
936	Replacement of a 90 Degree Fitting and Inspection of the Tee Fitting and Nipple at the Oil Pressure Transducer	PA-38-112	03/16/90	**		7257	10aE8
991A	Replacement or Modification of the Alternator Out Light Fuse	PA-38-112	01/29/96	**		2437	10bD16
1026	Distribution of Parker Hannifin Airborne Service Letter 48, "Inspection/Replacement of dry air pump flexible couplings."	PA-38-112	10/05/98	753-910		3711	10bJ20
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-38-112	09/25/00	**		3714	10cB1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

THIS PAGE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
677	Publications for Aircraft Operation	All Piper Models	05/20/80			PARA 15.0	7H4
780A	Part I - Flap Drive Mechanism Modification	PA-46-310P	10/10/85	765-118V		2910	8K7
780A	Part II - Flap Selector Valve Replacement	PA-46-310P	10/10/85	83729-04		2910	8K8
781	Aft Rudder Cable Inspection	PA-46-310P	06/25/84	**		2720	8K10
782A	Magneto Switch Guard Installation	PA-46-310P	04/24/85	N/A		7410	8K12
783	Interference of Elevator to Stabilizer	PA-46-310P	06/13/84	765-132V		5520	8K15
784	Pressure Outflow & Safety Valve Routing Inspection	PA-46-310P	08/07/84	557-114		2130	8K17
786	Toe Brake Cylinder Clevis Rework	PA-46-310P	08/20/84	N/A		3241	8L6
790A	Part I - Turbo Oil Scavenge Reservoir Inspection	PA-46-310P	02/14/85	**		7250	9A1
790A	Part II - Turbo Oil Scavenge Oil Line Support	PA-46-310P	02/14/85	**		7250	9A2
790A	Part III - Lower Cowl Modification	PA-46-310P	02/14/85	N/A		7250	9A3
791	Oxygen System Electrical Wiring Rerouting	PA-46-310P	08/20/84	N/A		3529	9A7
792	Fuel Supply Line Replacement & Wing Rib Modification	PA-46-310P	08/07/84	**		2814	9A13
794	Electric Fuel Pump Circuitry Modification	PA-46-310P	08/30/84	**		2820	9A20
796B	Part I - Lower Wing Rivet Replacement	PA-46-310P PA-46-350P	01/25/95	**		5733	9B8
796B	Part II - Wing to Fuselage Fairing Replacement	PA-46-310P	01/25/95	**		5733	9B9
796B	Part III - Upper Inboard Wing Rivet Replacement	PA-46-310P	01/25/95	**		5733	9B9
799	Landing Gear Control Lever Safety Tab Modification	PA-46-310P	10/26/84	**		3260	9C1
803A	Pneumatic Surface Deice Pressure Control Valve	PA-46-310P	03/21/86	765-159 84523-805		3014	9C18
805A	TRW Hartzell Propeller Service Bulletin No. 142 (O-ring Deterioration)	PA-46-310P	03/14/86	N/A		6110	9D15
808	Main And Nose Landing Gear Actuator Seal Replacement	PA-46-310P	07/10/85	**		2930	9E10
809	Nose Landing Gear Steering Rotator Inspection And Replacement	PA-46-310P	07/01/85	**		3251	9E21
810	Gear Safety Solenoid Installation Modification	PA-46-310P	07/09/85	422-166 406-385		3200	9F1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
820	Aft Wing Attach Fitting Fastener Inspection/Replacement	PA-46-310P	02/25/86	680-660		5741	9G16
824	Electric Flap Motor - Actuator Installation Rework	PA 46-310P	03/21/86	**		2753	9H11
837	Main Landing Gear Lower Torque Link Bolt Inspection	PA-46-310P	05/21/86	424-052		3213	9J8
852	Alternate Air Control Linkage Adjustment	PA-46-310P	11/14/86	N/A	87-04-01	7164	9L19
853	Fuel Drain Replacement	PA-46-310P	11/17/86	765-317		2823	10A1
854A	Deice Timer Protection - Electrical Circuit Change	PA-46-310P	10/28/87	**		3016	10A3
855	Use of Automobile Gasoline in Piper Aircraft	All Piston Powered Models	01/14/87	N/A		2800	10A7
858	Nose Landing Gear Steering Rotator Horn Attach Bolt Replacement	PA-46-310P	04/01/87	401-302 407-565		3251	10A15
862A	Electrically Operated Flap System, Actuator Tube Replacement	PA-46-310P	08/11/87	85070-02		2753	10B3
863A	Part I - Aileron Cable Routing - Wing	PA-46-310P	01/31/89	765-331		2712	10B6
863A	Part II - Phenolic Fairlead Installation	PA-46-310P	01/31/89	**		2712	10B7
865A	Part I - Freon Compressor Drive Pulley Nut Inspection And Belt Removal	PA-46-310P	07/14/87	**	87-12-12	2513	10B13
865A	Part II - TCM Mandatory Service Bulletin M87-13 "Broken Starter Adapter Shafts"	PA-46-310P	07/14/87	**		2513	10B14
871	Airframe And Powerplant Operational Limitations	PA-46-310P	10/13/87	**		7100	10C15
876B	Part I - Malibu Return To Service	PA-46-310P	04/14/88	**	87-14-02	7200	10E8
876B	Part II - Teledyne Continental Motor Service Bulletin M88-5 "Broken Starter Adapter Shafts"	PA-46-310P	04/08/88	**	88-17-03	7200	10E9
883	Additional Post Lighting - Flight and Engine Instrumentation	PA-46-310P	03/10/88	765-353		3311	10G18
884	Lock Wiring Of V-Band Couplings	PA-46-310P	04/08/88	**		7800 2100	10G20
892A	Powerplant Cooling Improvement	PA-46-310P	05/17/89	765-365	88-25-08	7520	10I1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
895	Alternate Air Box Bearing Block Modification	PA-46-310P	11/17/88	420-219		7160	10I10
896	Shoulder Harness Installation & Usage	PA-46-310P	11/28/88	**		5340	10I13
900	Missing Upper Fuselage Rivets	PA-46-310P	02/13/89	522-601		5333	10J11
913A	Malibu Return to Service	PA-46-310P	06/29/89	N/A	89-14-01	7226	10L15
915	Lycoming Service Bulletin No. 487 (Included with Lycoming Kit)	PA-46-350P	07/08/89	**	89-15-10	7311	10aA5
917	Angle Support Forward Baggage Compartment	PA-46-310P	07/19/89	765-367		2551	10aA14
919	Carpet Runner Retainer Installation	PA-46-310P	08/03/89	765-369		2520	10aB2
921	Aileron Inspection	PA-46-310P PA-46-350P	08/15/89	**		2715	10aB9
928A	Textron Lycoming Service Bulletin No. 491A, Inspection of Exhaust Transition Bolts	PA-46-350P	03/22/90	**		7800	10aC12
930	Inspection of Emergency Exit Window Fit	PA-46-350P	12/14/89	N/A		5621	10aC20
934	Inspection and Rerouting of the Manifold Pressure Line	PA-46-350P	02/08/90	**		7716	10aD12
939	Weight and Balance Plotter	PA-46-350P	06/08/90	N/A		1110	10aE4
941	Improved Engine Baffle Support	PA-46-350P	07/17/90	**		7236	10aE9
943A	Landing Gear Locking Acuator End Gland Replacement	PA-46-310P	08/15/90	763-060		3235	10aF1
944	Empennage Rivet Replacement	PA-46-310P PA-46-350P	10/05/90	**		5510 5530	10aF12
947A	Low Vacuum Annunciator Light Operation	PA-46-310P PA-46-350P	10/29/91	**		3720	10aF23
948	Inboard Wing Rib Inspection, Modification, Replacement	PA-46-310P PA-46-350P	01/25/91	**		5710	10aG3
949	Wing Rib Reinforcement	PA-46-310P PA-46-350P	02/18/91	766-247 766-248 766-249		5712	10aG10
951	Mixture Control Cable Inspection and Routing	PA-46-350P	02/18/92			7320	10aG14
953	Elevator Trim Cable Guide Tube Splice	PA-46-310P PA-46-350P	10/29/91	766-272		2730	10aG23
958	Horizontal Stabilizer Drain Hole Installation	PA-46-310P PA-46-350P	9/22/92			5510	10aH17
959	Fuselage Rivet Installation	PA-46-310P PA-46-350P	03/31/93	**		5310	10aH20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
960	Engine Mount Heat Shield	PA-46-310P PA-46-350P	03/31/93	766-267 766-268		7120	10aI3
961	Alternate Air Door Replacement and Control Linkage Inspection	PA-46-310P PA-46-350P	10/21/92	**		7160	10aI5
962	Corrosion Inspection and Protection	PA-46-310P PA-46-350P	09/29/93	**		5510	10aJ4
963	Electric Flap Cam Assembly Modification	PA-46-310P PA-46-350P	06/11/93	766-245		2750	10aI17
964B	Hydraulic Power Pak Pressure Switch Replacement	PA-46-310P PA-46-350P	12/22/96	766-278 766-277		2911	10aJ14
976	Inspection for and Replacement of Components with Suspect "O" Rings	PA-46-350P	12/09/94	**		2911	10bA10
981	Hydraulic Power Pak Lower Manifold Inspection	PA-46-310P PA-46-350P	01/17/95	**		2911	10bB15
982	Installation of Limitations Placard	PA-46-350P	04/03/95	**		1100	10bC1
985	Hydraulic System Power Pak Pressure Switch Replacement	PA-46-310P PA-46-350P	06/16/95	765-457		2911	10bC17
990	Pacific Scientific Seat Belt Replacement	PA-46-350P	01/03/96	**		5346	10bD12
993	KLN-90B GPS Wiring Modification	PA-46-350P	03/18/96	**		3441	10bE4
994	Intermittent Main Landing Gear Indication (Parker Hannifin SB7049) (Attached)	PA-46-310P PA-46-350P	03/08/96	**		2911	10bE6
995A	Turbine Inlet Temperature (T.I.T.) System Calibration and Probe Replacement	PA-46-310P PA-46-350P	04/26/96	481-389	99-15-04	7726	10bE11
997	Inspection of Jack Pad attachment Area at Wing Cutout for Radar	PA-46-310P PA-46-350P	02/07/97	766-628		5740	10bE20
999	Modification of Inertia Reel Shoulder Harness Mounting Brackets	PA-46-310P PA-46-350P	03/05/97	766-638		5346	10bF9
1000	Inspection of Engine Electrical Harness and Installation of Chafing Protection	PA-46-350P	04/25/97	49990-36 488-702		2436	10bF11
1001	Inspection for Missing Washers at Nose Gear Steering Arm Rod End	PA-46-350P	06/16/97	**		3251	10bF14
1012	Distribution of Textron Lycoming Service Bulletin 531, Inspection of turbochargers and Tailpipes	PA-46-350P	02/04/98	**		7800	10bH3
1014	Replacement of Battery Power Fuse	PA-46-350P	03/02/98	461-681		2436	10bH11
1017	Alternator Regulator Wiring Mod	PA-46-350P	04/10/98	**		2436	10bH21
1020	Inspection of the ARTEX 110-4 ELT and ELT Attachment Bracket	PA-46-350P	07/10/98	**		2563	10bI11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1021	Modification of Control Wheel Quadrant Stop and Inspection of Forward Pressure Bulkhead	PA-46-310P PA-46-350P	08/04/98	766-654		5346	10b11
1027	Modification of Forward and Aft WingAttached Fittings	PA-46-350P	11/19/98	766-656 766-657	99-16-06	5741	10bK4
1029	Distribution of Textron Lycoming Service Bulletin 534, Turbocharger Oil Drain Tank Inspection/Replacement	PA-46-350P	04/30/99			7164	10b17
1034	Battery Master Contactor Wiring Modification	PA-46-350P	08/17/99	84350-11 84350-12		2454	10bL14
1035	Distribution of Textron Lycoming Service Bulletin 529A, "Reprint of Crane/Lear Romec Service Bulletin No. 101SB020, Rev. 2"	PA-46-350P	09/03/99	**	98-18-12	7311	10bL17
1041	Distribution of Airborne Service Letter Number 56, "Inspection and Cleaning of Airborne Air Filter Elements."	PA-46-310P PA-46-350P	09/25/00	**		3714	10cB1
1046	POH Supplement Installation	PA-46-350P	11/28/00	**		2212	10cC4
1048	Stainless Steel Control Cables	PA-46-350P	01/03/01	N/A		2702	10cC9
1052	Nose Gear Steering Bungee Assy Modification	PA-46-500TP	02/26/01	766-690		3255	10cC23
1053	Outside Air Temperature Probe Relocation	PA-46-500TP	04/03/01	766-688		3416	10cD2
1054	Pilot and Co-Pilot Seat Inspection and Modification	PA-46-310P PA-46-350P PA-46-500TP	04/12/01	**		2514	10cD6
1055	Engine Control Quadrant Inspection and Modification	PA-46-500TP	05/29/01	82995-003		7601	10cD9
1056	Fuel Drain Valve Inspection and Replacement	PA-46-500TP	04/04/01	766-691		7319	10cD21
1058	Overhead Switch Panel Replacement	PA-46-500TP	05/31/01	680-839 688-497		3110	10cE3
1059	Low Pressure Engine Driven Pump Leakage Inspection	PA-46-500TP	06/11/01	461-752		7311	10cE6
1060	Brake Pedal Binding	PA-46-310P PA-46-350P PA-46-500TP	05/15/01	**		3241	10cE9
1061	Nose Landing Gear Strut Tube Snap Ring Inspection	PA-46-500TP	06/19/01	N/A		3223	10cE13
1062	Inboard Flap Drive Bellcrank Inspection and Replacement	PA-46-310P PA-46-350P PA-46-500TP	05/11/01	82905-002 82905-003	01-12-01	2755	10cE16
1063	Circuit Breaker Panel Modifications	PA-46-500TP	06/11/01	581-657		2451	10cE22

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

REVISED: 03/01/04

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1064	Mass Flow Control Valve Support Clip Installation	PA-46-500TP	06/14/01	102501-002		2125	10cF4
1065	Primary Elevator Control Cable Replacement	PA-46-500TP	07/25/01	**		2735	10cF10
1066	Cabin Door Latch Mechanism	PA-46-350P PA-46-500TP	07/10/01	767-305		5213	10cF14
1067A	Entertainment Console (Small Cabinet) Voltage Dropping Resistor Shroud Installation	PA-46-350P PA-46-500TP	08/08/01	767-301 767-302		2507	10cF17
1068	Fuel System Line Fitting Leakage	PA-46-500TP	07/19/01	**		2823	10cF20
1069	Fuel System Trim Fitting and Solenoid Valve Modification	PA-46-500TP	07/19/01	766-682		2825	10cG2
1070	Lightning Protection Rivets Installation	PA-46-500TP	07/16/01	767-303		2816	10cG5
1071	Main Landing Gear Squat Switch Safetying	PA-46-500TP	07/02/01	N/A		3237	10cG8
1072	Mass Air Control Valve Recall	PA-46-500TP	08/13/01	592-640		2138	10cG12
1073	Magnetic Flux Detector Connector	PA-46-500TP	08/13/01	599-693		3427	10cG15
1074	Cabin Bleed Air Restriction	PA-46-500TP	07/23/01	N/A		2182	10cG20
1075A	Steering Horn Modification	PA-46-310P PA-46-350P	05/05/03	85154-002 85154-012		3251	10cH1
1076	GI-106 NAV/GS Indicator Wiring Harness Inspection / Modification	PA-46-500TP	07/19/01	N/A		3316	10cH6
1077	P&WC PT6A-42A Engine Oil-to-Fuel Heater Inspection	PA-46-500TP	07/13/01	762-156		7200	10cH11
1078	Stall Warning Microswitch Bracket	PA-46-500TP	08/13/01	767-306		2226	10cI1
1080	Lear Romec Fuel Pump	PA-46-500TP	07/26/01	461-757		2820	10cI7
1082	Aft Stowage Compartment Drain	PA-46-500TP	08/13/01	766-693		2550	10cI16
1084	Flight Into Known Icing (FIKI) Certification	PA-46-500TP	09/20/01	**		3010	10cJ1
1085	Nose Landing Gear Steering Arm Chafing	PA-46-500TP	10/26/01	767-304		3220	10cJ6
1086	Generator Ammeter Relay Kit	PA-46-500TP	10/03/01	767-308		2434	10cJ10
1087B	Nose Gear Emergency Downspring Mechanism Replacement	PA-46-310P PA-46-350P PA-46-500TP	05/27/03	766-211 104723-002 104723-003		3235	10cJ13
1088	Aft Spar Splice Cap Inspection	PA-46-500TP	12/10/01	767-321		2751	10cJ18
1089	Nose Gear Squat Switch Adjustment	PA-46-500TP	11/12/01	N/A		3265	10cJ22
1090	Fuel Restrictor Assy / Fuel Return Solenoid Removal	PA-46-500TP	08/23/01	767-324		2825	10cK1
1091	Pratt & Whitney PT6A-42A Engines - Turboprop Engine Oil-to-Fuel Heater Thermal Element Replacement	PA-46-500TP	09/20/01	N/A		7200	10cK4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE BULLETIN INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1093	Alternator Isolation Diode Installation	PA-46-500TP	12/05/01	767-307		2430	10cL4
1094	Fuel System Check Valve Replacement	PA-46-500TP	10/19/01	592-670		2813	10cL7
1095	Gear Warning Horn Mute Switch	PA-46-500TP	01/18/02	766-697		3260	10cL12
1098	Pneumatic Deice System Line Inspection and Replacement	PA-46-500TP	02/01/02	102437-086		3015	10cL19
1099	Feather Solenoid Suppression Diode Kit	PA-46-500TP	01/18/02	767-328		6123	10cL23
1102	Master Electrical Panel Mounting Plate Inspection and Fuse Block Protective Cover Installation	PA-46-500TP	03/08/02	767-327		2400	10dA8
1103B	Engine Mount Inspection	PA-46-310P PA-46-350P PA-46-500TP	11/25/03	84010-002 89137-041 102460-002		7121	10dA12
1106	Nose Gear Steering System Improvement	PA-46-500TP	01/28/02	767-336 767-338		3220	10dB4
1107	Maneuvering Speed Placard Replacement	PA-46-500TP	03/07/02	692-721		1100	10dB8
1108	Flux Detector Relocation	PA-46-350P PA-46-500TP	03/11/02	767-335 767-334		3429	10dB11
1111	Float Switch Wiring Inspection	PA-46-500TP	08/19/02	602-501		2424	10dB21
1114	No. 1 GNS 530 Lighting Rewiring	PA-46-500TP	04/24/02	766-696		3457	10dC7
1121	Installation of Missing Rivets on Lower Surface of Horizontal Stabilizer Spar	PA-46-500TP	10/03/02	MS20470AD5		5510	10dD10
1126	Emergency Gear Extension Cable Bracket Modification	PA-46-350P PA-46-500TP	07/29/03	767-364		3237	10dE10
1132	Electronic Control Module Failures	PA-46-500TP	06/04/03	102226-002 102227-002 102227-006 102228-002 102228-006	04-03-32	2400	10dF14
1134	Servo Metered Fuel Pressure Port Leakage (Lycoming SB 557; Precision Airmotive SB PRS-105)	PA-46-350P	06/10/03	**		2800	10dG1
1135	GMA-340 Audio Panel Wiring	PA-46-350P PA-46-500TP	07/16/03	N/A		2370	10dG9
1139	Control Wheel Attachment Inspection	PA-46-350P PA-46-500TP	08/28/03	**		2701	10dH1
1140	Oxygen Generator Protective Cap Removal	PA-46-310P PA-46-350P PA-46-500TP	09/16/03	471-025		3500	10dH6

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

PA-46-310P
PA-46-350P
PA-46-500TP

SERVICE BULLETIN INDEX

REVISED: 07/10/01

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

GRIDS 1E8 THRU 1F24
INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

REVISED: 03/09/01

CLASSIC AIRCRAFT: B-2/E-2/F-2/
J-2/J-3/J-4/L-21/L-18/PA-11/
PA-15/PA-16/PA-17/PA-18/PA-19/
PA-20/PA-22

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
32	Aileron Cable Pulley Installation	J3	06/15/42				13A1
100	Tie Rod Nipples- J3, 8-36 Type A	J3	11/23/43				13A2
107	Plexiglass One Piece Windshield For J3 Series	J3	10/15/45				13A3
109	Winter Operation Recommendations	J3, PA-11	10/15/47				13A5
114	Top Cowl Rivets	PA-16	06/13/49				13A10
129	Inspection of Landing Gear Shock Strut End Fittings	PA-15/17	10/28/49				13A11
131	Muffler Tail Pipe Inspection	PA-11	12/30/49				13A12
136A	Chafing of Fuel Line and Fuel Valve Operation	PA-20/22	09/02/52				13A13
138	Rudder Pedal Tube Attachment	PA-20	03/09/50				13A15
140	Rudder Cable Rub Block	PA-20	03/24/50				13A16
143	Stabilizer Adjustment Cable Pulley Modification	PA-20	05/05/50				13A18
144	Fuselage Doors	PA-15/17	05/05/50				13A19
145	Auxiliary Fuel Line	PA-20	06/01/50				13A20
146	Front Seat Frame Revision	PA-20	06/01/50				13A21
150	Bungee Cable PA-18-105	PA-18	07/10/50				13A22
153	PA-20 Windshield Supports	PA-20	07/12/50				13A24
154	Addition of Felt Strips on Wing Tank Covers	PA-11/16 PA-18/20	07/12/50				13B1
155	Muffler Tail Pipe Shroud	PA-18	07/14/50				13B2
157	Loose Connections	PA-16/20	08/01/50				13B4
159	PA-20 Baffle Seal	PA-20	10/24/50				13B5
161	Duraclad Finish	PA-18/20/22	02/13/51				13B6
162	Control Sticks	PA-18	03/06/51				13B8

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
169	Manifold Pressure Gauge Installation	All 1951 Models	04/20/51				13B9
175	Nose Wheel Bumper Block Spacer Plate	PA-22	08/01/51				13B10
176	Stabilizer Adjustment Mechanism	PA-20/22	08/10/51				13B11
177	Firewalls	All Classic Models	08/10/51				13B13
178	Optional Oil Radiator Installation	PA-18	08/24/51				13B14
180	Nose Wheel Mount Stiffener Brace	PA-22	09/20/51				13B15
183A	Tail Wire Fittings	PA-18	11/12/51				13B16
186	Clearance Between Engine Mount and Tail Pipe/Clearance In Nose Wheel Steering Mechanism	PA-22	04/21/52				13B17
187	Brake Lever	PA-22	03/13/52				13B19
188	Flap Cable Installation	PA-18A	04/11/52				13B20
189	Tail Wheel Springs	PA-18A	04/17/52				13B22
194	Sealing Of Firewalls	PA-20/22	09/02/52				13B23
195	Battery Cable And Rudder Cable Interference	PA-18A	10/06/52				13B24
196	Chafing Of Oil Pressure Line	PA-18	10/06/52				13C2
203	Weight & Balance Form	PA-12	05/07/53				13C3
207	Oil Quick Drain Valve Assembly, Part No. 12956-04	PA-18 PA-22	06/18/53				13C4
209	Navigation Light Switch	All Classic Models	08/18/53				13C5
210	PA-18A Agricultural Airplane	PA-18A	08/24/53				13C6
212	Nose Wheel Shimmy Dampener, Part No. 13086-00	PA-22	10/07/53				13C8
213	Primer Lines	PA-18, 20, 22	10/07/53				13C10
214	Navigation Light Switch	All Classic Models	11/17/53				13C12

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

REVISED: 03/09/01

CLASSIC AIRCRAFT: B-2/E-2/F-2/
J-2/J-3/J-4/L-21/L-18/PA-11/
PA-15/PA-16/PA-17/PA-18/PA-19/
PA-20/PA-22

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
216A	Replacement of Aileron Hinge Bearing Blocks Part No. 10921	All Classic Models	12/14/53				13C13
220	.040 Brass Safety Wire	All Classic Models	03/29/54				13C14
221	Carburetor Air Filter	All Classic Models	05/13/57				13C17
223	Engine Support Bushing	PA-12, 16 PA-18, 18A PA-20, 22	05/17/54				13C18
228	Two Person Safety Belts	PA-12, 14, 15 PA-16, 17, 20, 22	09/29/54				13C20
233	Fuel Selector Valve	PA-18, 20, 22	10/22/54				13D3
241	Cigarette Lighters	PA-22	01/24/55				13D9
242A	Special Air Filter Kits	PA-18A	02/20/59	**		7160	13D10
243	Engine Mount	PA-22	02/08/55				13D11
247	Tail Reinforcement Agricultural Airplane	PA-18A	04/15/55				13D13
248	Auxiliary Fuel Tank	PA-22	05/13/55				13D14
258	Fuel Tank Cap	PA-22	11/30/55				13E2
259	RPM Restriction Placard	PA-18, 18A	11/30/55				13E4
260	Brake System	PA-22 (1956 Models Only)	11/30/55				13E5
283A	Inspection Forms, 100, 500, 1000 Hour	PA-18, 18A PA-22	02/26/58			General	13E24
295A	Aircraft Finishes	All Classic Models	01/03/64				13F12
298A	Obsolete Airplanes	B-2/E-2/F-2/J-2/J-3/ J-4/PA-11/15/16/17/ L-4/L-18B/ NE-1/PA-20	09/07/62			General	13F14
303A	Aircraft Finish	PA-15/16/17 PA-18/20 PA-22 ***	09/23/59			5300	13F23
312	Tooling - Piper Auto Control	PA-22	11/24/58	**		2210	13H4
318	Air Filter, Carburetor, System Modification	PA-18/18A	04/06/59	754-223		7160	13H19
321	Piper Autocontrol	PA-18, 22 ***	07/08/59			2210	13H22

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
324C	Maintenance And Inspection Of Exhaust Systems And Heat Exchanges	PA-18, 22	01/22/69		62-26-05 68-05-01	7810	13I1
327	FAA Bureau Of Flight Standards Release No. 434	All Models ***	12/28/59			General	13I11
328	Lycoming Service Letter #L126 Dated 1/24/60	PA-22	02/17/60			7200	13I19
329A	Oil Cooler Lines, Inspection Of	PA-22	05/17/60	**		7920	13J3
348	Airspeed Indicators, Replacement Of	PA-22-108	12/09/60	11339-16		3410	13K11
349	Bushings, Engine Support, Adjustment Of	PA-18/18A PA-22	12/14/60	**	61-16-05	7100	13K12
353A	Propeller Decal	PA-22-108	02/20/61			6100	13K16
355	Stainless Steel Control Cables	PA-18/18A PA-20 PA-22	02/23/61	**	61-16-05	2700	13K19
358B	Mount Assemblies, Engine And Nose Wheel Inspection	PA-22	06/07/66			7120	13K23
362B	Windshield Top Attachment, Modification Of	PA-15 PA-16/17 PA-20 PA-22	12/11/74	754-404 760-799 754-404 754-404	74-17-04	5610	13L7
369	Inspection Of Brake Cable And Pulleys	PA-22 PA-22-108	03/07/62			3240	14A5
373	Dry Vacuum Pumps (Airborne Mechanisms), Models 113A1 And 113A5 Installation Of Oil Shields	PA-22-108	03/29/62	756-143		3710	14A11
400	Tail Brace Rods	PA-20 PA-22	03/20/63	10555-02 10556-02	60-01-07	5510	14C11
405	Bearing, Nose Gear Upper Oleo, Inspection Of	PA-22	10/01/63	452-419	64-05-04	3220	14C20
406	Revision To Owners Handbook	PA-20 PA-22	09/26/63			General	14C22
410	Inspection And Lubrication Of Stabilizer	PA-22 Series	10/16/63			5500	14D6
423	Muffler And Tailpipe Support Kits	PA-22-108	05/05/64	756-803 756-804		7810	14E13
485	Scott Aviation Corporation Modification Instructions 1-298 For Constant Flow (Semi-Disposable) Mask, Scott PN 28302	All Aircraft With Subject Mask Assy.	02/08/67	756-332		3510	14J9
486A	Cylinder Head Temperature Probe Location	PA-18 PA-22	04/16/68			7720	14J13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

REVISED: 03/09/01

CLASSIC AIRCRAFT: B-2/E-2/F-2/
J-2/J-3/J-4/L-21/L-18/PA-11/
PA-15/PA-16/PA-17/PA-18/PA-19/
PA-20/PA-22

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
491	Aeromarine Instrument Company Service Bulletin No. 201	Aeromarine Airspeed Indicator Equipped Aircraft	08/08/67			3400	14J18
513	Service Memos And Service Aids	All Models	08/30/68			General	14L2
529A	Autopilot Gyro Instrument Overhaul Centers	Piper Autopilot Equipped Aircraft	01/14/70			3400	15A17
544	Revised Gyro Service Procedure	3" D.G. 1 Attitude Gyros	01/05/70			3420	15C7
573	B.F. Goodrich Service Bulletin No. E-68-36B (Sealer For B.F. Goodrich Deicer And Strap)	B. F. G. Deicer Systems	03/04/71			3020	15F17
608	Covering, Aircraft Ceconite	PA-18-150	01/31/72			5300	15J10
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	02/21/73			5500	15J21
617B	Piper Automatic Locator Transmitter Replacement	PA-18	08/30/73		72-22-03	2560	15K18
633	Inspection And Repair Of Flood Exposed Airplanes	PA-18 ***	10/09/72			5300	16A18
636	Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement)	PA-18, 22	10/24/72	**		2430	16B2
653	Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972)	PA-15 PA-16, 18, 20, 22	04/09/73	**		7610	16C14
682B	Required Inspection Of Piston Pin (Reference Lycoming Service Bulletin No. 367D)	PA-22	04/19/74			7230	16F9
695	Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38, Dated March 18, 1974)	PA-22	05/03/74	**		2210	16G13
718	Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)	PA-11	05/31/74	**		7410	16J18
740	Fuel Requirements	PA-16, 18, 20, 22	04/20/76			2800	17A3
820	Replacement Of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters	PA-18-150	07/28/80	**		2560	17J2
828	Electrical System Refinement	PA-18-150	08/28/78			2400	17J16
944	Fuel Selector Valve Inspection And Lubrication	PA-18-150	04/20/82	**		2820	18K11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1016	Strut Cuff & Door Catch Attachment Improvement	PA-20,22	11/11/95	766-269 766-270		5701	19G9
1041	Accident/Incident Reporting	All	03/10/02	N/A		N/A	19K10
1052	Life Limited Parts Marking and Disposition	All	05/21/02	N/A		0510	19L19
1069	Flight Control Cable Terminal Corrosion Inspection	All	03/31/03	N/A	CE-02-05 (SAIB)	2702	20C2

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
220	.040 Brass Safety Wire	PA-23	03/29/54				13C14
221	Carburetor Air Filter	PA-23	05/13/57				13C17
227	Service Publication To The Field	PA-23	09/24/54				13C19
229	Balancer For The Hartzell HC-82XG-2 Propeller	PA-23	10/07/54				13C21
231	Electrical System	PA-23	10/11/54				13D1
235	Flap Spar And Stabilizer Spar Reinforcement	PA-23	10/28/54				13D4
236	Cabin Heater Modification	PA-23	10/28/54				13D6
239	Cabin Draft	PA-23	01/03/55				13D7
240	Landing Gear Actuating Lever	PA-23	01/17/55				13D8
246	Engine Oil Thermostat Kit	PA-23	04/15/55				13D12
249	Heater Fuel Line	PA-23	05/24/55				13D15
250	Reference Service Bulletin #138 - Hydraulic Actuating Cylinders	PA-23	06/08/55				13D17
251	Carburetor Air Boxes	PA-23	09/16/55				13D19
252	Primer Pump	PA-23	09/16/55				13D20
255	Cabin Door Handle Bracket	PA-23	10/24/55				13D22
256	Heater Fuel Shutoff Valve	PA-23	11/21/55				13D24
266	Throttle, Prop And Mixture Control Levers	PA-23	02/19/56				13E6
270	Electrically Heated Airspeed Pitot Head	PA-23	03/09/56				13E7
271	Landing Gear Door Hinges And Hinge Brackets	PA-23	03/19/56				13E8
274	Ground Wire For Audio Speaker - Phone Selector Switch	PA-23	03/23/56				13E9
277	Brake Bleeding	PA-23	03/29/56				13E11
278A	Landing Gear Drag Link Assemblies	PA-23	02/28/57				13E18
280	Rerouting Of Engine Breather And Oil Separator Discharge	PA-23	09/11/56				13E20
281	Engine Nacelle Air Baffle	PA-23	09/12/56				13E22

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
282	Landing Gear Anti-Retracton Device	PA-23	10/01/56				13E23
283A	Inspection Forms, 100, 500, 1000 Hour	PA-23	02/26/58			0500	13E24
286	Auxiliary Fuel Valve Control Modification	PA-23	10/08/56				13F1
288B	Accessories, Optional Equipment And Modification Kits	PA-23	01/06/58			General	13F2
289	Engine Breather And Oil Separator Discharge Line Stoppage	PA-23	01/18/57				13F5
290	Elevator Horn Bushing Wear	PA-23	01/21/57				13F6
291	Wheels And Brakes	PA-23	06/05/57				13F7
292	Drag Link Assemblies	PA-23	09/05/57				13F8
293A	Cabin Heaters	PA-23	12/13/57				13F11
295A	Aircraft Finishes	PA-23	01/03/64				13F12
300B	Propeller Feathering	PA-23	03/30/59			6120	13F17
303A	Aircraft Finishes	PA-23	09/23/59				13F23
306	Carburetor Heat Shroud Support Modification	PA-23	10/10/58	754-192		7310	13G19
307	Nacelle Fairing Installation	PA-23	10/10/58	754-175		5450	13G20
312	Tooling-Piper Autocontrol	PA-23	11/24/58	**		2210	13H4
313	Elevator Control Tube Nylon Sleeve Installation Kit	PA-23	01/06/59	754-215		2730	13H5
319	Draining Of Apache Fuel Strainers	PA-23	04/13/59			7310	13H20
320	Nacelle Fairing Installation	PA-23	04/23/59			5450	13H21
321	Piper Autocontrol	PA-23	07/08/59				13H22
322A	Fuel System Control Valves	PA-23	10/12/59	**	60-03-08	7320	13H23
324C	Maintenance And Inspection Of Exhaust Systems And Heat Exchanges	PA-23/23-250	01/22/69		62-26-05 68-05-01	7810	13I1
326	PA-23 Elevator Tabs	PA-23	12/28/59			5520	13I10
330	South Wind Bulletin Dated February 22, 1960	PA-23	05/05/60	751-776		2140	13J5
333C	Radio Shelf Capacities	PA-23-235/250 UO-1	01/28/63			3400	13J13
334	Fuel Cell Filler Neck Reinforcement	PA-23-250 UO-1	06/16/60	754-332		2810	13J14
336	Modification Of Oil Pressure Lines	PA-23	06/17/60	19148-00		7930	13J17
338	Locking Of Main Cabin Door	PA-23-250	07/12/60			5210	13J20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
340	Sealing Of Fuel Cell Filler Neck Riveted Seam	PA-23-250	06/29/60			2810	13J24
345	Hartzell Service Bulletin #75- Inspection Of Hartzell Governor For Presence Of Vent Hole	PA-23-250	09/14/60			6120	13K5
350	Installation Of Brush And Retainer Plate Assembly, (Electric Propeller) Deicer B.F. Goodrich	PA-23/23-250 UO-1	12/19/60			6110	13K13
354	Reinforcement Of Aztec Stabilator Leading Edge	PA-23-250	05/25/61	30334-00		2730	13K17
359	Modification Of Fuel Cell Vent Tubes	PA-23	08/16/61			2810	13L1
363	Inspection And Modification Of Flaps	PA-23-250 UO-1	11/30/61	**		2750	13L10
367	Caps, Fuel Cell, "Thermos Bottle" Type	PA-23/23-250	02/01/62		68-13-03	2810	13L21
368	Lycoming Service Instruction No. 1049 Dated December 29, 1961	PA-23	02/07/62	**		7200	14A1
388	Removal Of Carburetor Heat Shroud Screen	PA-23-235 PA-23-250(6)	11/02/62			7160	14B12
398	Replacement Of Fuel Control Valves "O" Rings	PA-23-235 PA-23-250(6)	03/06/63	755-837		7320	14C7
404	Inspection Of Pitch Servo Assembly Chain Adjustment Screw, Altimatic And Altimatic II	PA-23/23-235 PA-23-250/23-250(6)	09/16/63	**		2210	14C17
407	Rudder Trim Tab Control Rod, Installation Of Roll Pin In, And Inspection Of	PA-23	10/04/63	480-728	63-24-03	2720	14C23
425	Lycoming Service Bulletin No. 298	PA-23-235/250 PA-23-250(6)	05/13/64	**		7200	14E17
432	Inspection Of Auxiliary Power Plug Solenoid	PA-23-250(6)	08/25/64	487-153		2400	14F10
438	Priority Valve Actuating Cable, Clamping	PA-23-250(6)	11/04/64	756-878		3250	14F21
441	Fuel System, Modification Of, And Replacement Of Electric Fuel Booster Pumps	PA-23-250(6)	01/20/65	756-880		2820	14G6
449A	Fuel Cells	PA-23-235 PA-23-250/250(6)	02/18/69		72-11-01	2810	14G16
454	Pitch Breakaway Ball Bracket (Altimatic II)	PA-23-250(6)	07/01/65	756-954		2210	14G21
462	Inspection Of Engine Mount Tubes	PA-23-250	12/09/65	31215-00 31215-01	68-07-04	7120	14H13
464A	Fuel Injection, Bendix RS	PA-23 PA-E23-250(6)	11/12/65			7310	14I1
466A	Stewart-Warner Heater Modification Kit	PA-23 PA-E23-250	08/08/67	756-995		2140	14I4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
472	Conduct Installation Modification, B.F. Goodrich Service Bulletin No. E-65-30	PA-23 PA-E23-250(6)	03/16/66	757-017		3020	14I12
474	Increase In Flap Extension Speeds	PA-23-235/250 PA-E23-250	04/21/66	757-000		2750	14I16
480	FAA Aircraft Specification No. 1A10 Item 1(1)	PA-23/E23-250	07/08/66			General	14J1
482	Altitude Limitation, 25,000 Ft. Removal Of	PA-23 PA-E23-250(6)T	09/20/66	757-063		3410	14J2
483	Airesearch Service Information Letter No. S. I. L. P-08	PA-23 PA-E23-250	08/17/66			7200	14J5
486A	Cylinder Head Temperature Probe Location	PA-23/23-235 PA-23-250	04/16/68			7720	14J13
487	Test Unit, Hydraulic Part Number 753-080 And Stand	PA-23 PA-235/250	02/13/67	753-080		0710	14J14
504	B.F. Goodrich Service Bulletin No. E-67-34	PA-23 PA-E23-250	4/8/68			3240	14K14
511	Auxiliary Power Receptacle Installation, Modification To The	PA-23-250(6)	08/30/68	760-180		2400	14K23
519	Alternator Ground Wire, Replacement And Relocation Of	PA-23-250(6)	12/31/68	760-282		2430	14L17
520	Inspection Of Turbocharger Plenum Exhaust Welds	PA-23-250(6)T	02/03/69	**		7230	14L19
522	Fuel Pump Restrictor Fitting	PA-23-250(6)T	01/14/69	760-275		2820	15A1
525	Addition Of Lock Washers To Electrical Switch Installations	PA-23-250(6)	02/28/69	407-103 407-133		2450	15A8
532	Voltage Regulation Component Grounding	PA-23-250(6)	07/07/69	760-331		2430	15B2
533	Exhaust Stack Assembly	PA-23-250(6)	11/10/69	32907-07		7810	15B5
545	Turbo (Lycoming) Aztec Owners Handbook And Power Setting Chart	PA-23-250(6)T	02/02/70	**		7220	15C10
547	Lycoming Turbocharger Aztec, Modification	PA-23-250	03/25/70	**		8120	15C15
550B	Density Control Adjustment, Turbocharger (Ref. Avco-Lycoming Dated 4/5/74)	PA-23-250(6)T	07/10/74			8120	15C21
559	Alternate Air System, Inspection Of	PA-23-250(6)T	08/03/70	32343-00		7160	15E4
560	Scott Fuel Selector Valves	PA-23-250	08/07/70	757-520		2820	15E6
562	Scott Aviation Service Bulletin No. 35-32	PA-23-235/250/ 250(6) E23-250	08/25/70	**		2820	15E10
564	Revised Hartzell Propellers	PA-23-250(6) PA-E23-250	09/28/70	**		6120	15E18
566	Spacer Bushing Installation, Autopilot Servo	PA-23 PA-E23-250(6)	11/25/70	760-472		2210	15F3

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
579	Heavy Duty Brake Disc Replacement	PA-23-250(6) PA-E23-250(6)	05/26/71	760-538		3240	15G16
580	Fuel Selector Valve Packing Lubrication	PA-23-235 PA-23-250(6) PA- E23 -250	05/24/71			2820	15G18
582A	Exhaust System (Turbocharger) Inspection And Modification (Lycoming S.B. #339A)	PA-23-250(6)T	06/03/74	**		8100	15G23
584	Circuit Breaker Switch Inspection, 90 Amp Alternator	PA-23-250(6)	07/08/71			2430	15H4
585	Inspection Of Hydraulic Lines	All Apache/Aztecs	07/09/71			2910	15H6
591	Inspection And Reinforcement Spar, Wing Front	PA-23-235/250 PA-23-250(6)	08/31/71	760-521 760-524		5710	15H12
592	Mounts, Engine Shock (Lord)	PA-23-250(6)	10/06/71	475-116 475-117		7120	15H14
593	Connector Plug, Harness, Strain Relief Hood Installation	PA-23-250(6) Alt. V & VF/D	10/11/71	760-555		2400	15H15
606A	Fuel System, Inspection And Modification	PA-23-235/250 PA-23-250(6)	08/23/72	**	72-11-01	2800	15J3
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	02/21/73			5500	15J21
613	Brake Disc Inspection, Heavy Duty (Cleveland Aircraft Products S. B. #ESB-7002)	PA-23-250(6)	05/11/72	760-538		3240	15K4
617B	Piper Automatic Locator Transmitter Replacement	PA-23-250	08/30/73		72-22-03	2560	15K18
619	Retainer Spring, Piper Part Number 83302-13, Inspection Of	PA-23-235/250/ PA-23-250(6)	06/09/72			7330 7160	15L5
627	Propeller Installation	PA-23-250(6)	09/01/72			6100	16A1
628	Control System Inspection, Stabilator Trim	PA-23-250(6)	09/18/72	31970-03		2740	16A4
629	Fuselage Frame Tube Corrosion Inspection	All Apache/Aztecs	09/15/72	760-703		5320	16A8
630	Lubrication Of Fuel Valve Selector Mechanism	PA-23-250 PA-23-250(6)	09/13/72	**		2820	16A11
633	Inspection And Repair Of Flood Exposed Airplanes	PA-23	10/09/72			5300	16A18
636	Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement)	PA-23	10/24/72	**		2430	16B2
638A	Edo-Aire Mitchell Service Letter No. ML-35 (Servo Lubrication - Rack And Pinion Type Servos)	PA-23	02/08/73			2210	16B7
641	Replacement Exhaust Stack Support Assembly	PA-23-250(6)	02/26/73	760-702		7810	16B13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
642	Alternator Inoperative Warning Light, Revised	PA-23-250(6)	02/19/73	760-711 760-712		2730	16B15
A645	Starter Vibrator Wiring Inspection	PA-23-250(6)	04/12/73	492-431 492-644		8010	16B20
653	Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972	PA-23	04/09/73	**		7610	16C14
655	Airesearch Service Bulletin No. 1172-1A; Reference Avco Lycoming Service Bulletin No. 361	PA-23-250(6) Turbo	04/10/73	**		7200	16C21
667A	Stabilator Attachment Bolts	PA-23-235/250 PA-23-250(6)	03/04/74	**	74-13-03	2740	16E1
672	Wing Rear Spar Inspection	PA-23-150/160	09/18/73	**		5710	16E12
674	Overvoltage Relay Inspection	PA-23-250(6)	01/03/74	760-787		2430	16E16
676	Weight And Balance/Equipment List Correction	PA-23-250(6)	10/04/73			3200	16E20
682B	Reference Lycoming Service Bulletin 367D	PA-23-250	04/19/74	**		7230	16F9
683	Stabilator Control Cable Attachment Fittings Inspection	PA-23-250(6)	10/03/73			2740	16F16
695	Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38, Dated March 18, 1974	PA-23	05/03/74	**		2210	16G13
696	Control Surface Balancing Recommendation	PA-23-250	05/02/74			2700	16G20
705	Oil Tanks, Turbocharger Modification Of, And Related Installation (Airesearch Service Bulletin No. 14.1.10 And 14.1.11 Dated February 6, 1974)	PA-23-250 PA-23-250(6)T	04/16/74	**		8100	16H13
707	Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973	PA-23	02/27/74	**		7710	16I11
710	Inspection Of Stabilator Control Cable And Rudder Control Cable Attachments	PA-23-250(6)	05/24/74			2740	16J1
717	Brake Assembly Cylinder Retract, Improved (Cleveland Aircraft Products Service Letter No. 7000-5)	PA-23-250(6)	09/18/74	751-507		3240	16J16
723	Glideslope Indicator Placard	PA-23-250(6)	08/14/74	**		3430	16K11
726	Cigar Lighter Placard 24 Volt	All PA-23-235/ 23-250	08/08/74	80247-02		3310	16K16
740	Fuel Requirements	PA-23	04/20/76			2800	17A3

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
786A	Refined Engine Mount Assembly	PA-23-250(6)	08/31/76	**		7120	17F15
807A	Stabilator Outboard Nose Rib Installation	PA-23-250(6)	09/08/77	761-141	78-02-03	5570	17H13
815	Radar Antenna Mounting Plate Inspection And Modification	PA-23-250(6)	03/18/78	48881-02		3440	17I15
820	Replacement Of Lithium Sulphur Dioxide (LiSO2) ELT Batteries and/or Transmitters	PA-23-250	07/28/80	**		2560	17J2
830	24 Volt Cigar Lighter Element Replacement	PA-23-250(6)	11/22/77	**		3310	17J19
846	Stabilator Assembly Lower Surface Rivet Inspection	PA-23-250	05/03/78	**		2740	17K23
853	Inspection For Cracked Flap Spars At Hinge Area	PA-23 PA-23-235/250 PA-23-250(6 Place)	06/08/79	**	81-04-05	2750	17L20
1041	Accident/Incident Reporting	All	03/10/02	N/A		N/A	19K10
1052	Life Limited Parts Marking and Disposition	All	05/21/02	N/A		0510	19L19
1069	Flight Control Cable Terminal Corrosion Inspection	All	03/31/03	N/A	CE-02-05 (SAIB)	2702	20C2

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

THIS PAGE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
177	Firewalls	PA-24 PA-30/39	08/10/51				13B13
207	Oil Quick Drain Valve Assembly, Part No 12956-04	PA-24	06/18/53				13C4
221	Carburetor Air Filter	PA-24	05/13/57				13C17
283A	Inspection Forms 100/500/1000 Hour	PA-24	02/26/58			0500	13E24
295A	Aircraft Finishes	PA-24 PA-30	01/03/64				13F12
299	Cabin Door Lower Hinge Reinforcement, Cabin Door Holder And Landing Gear Oil Level Instructions	PA-24-180 PA-24-250	06/10/58	**		5210	13F15
301	PA 24 Comanche Landing Gear	PA-24	08/12/58			3200	13F20
302	Fuel Gauge Ground Wire	PA-24-180/250	08/19/58			2840	13F21
303A	Aircraft Finish	PA-24	09/23/59			5300	13F23
305	Miscellaneous Modifications; Door Latch, Oil Separator Inlet Hose, Landing Gear Retraction Tube Arm	PA-24-180/250	10/01/58	**	58-25-05	5200 7920 3230	13G14
310	Locking Of Landing Gear Motor Release Arm	PA-24-180/250	11/10/58			3230	13H1
311	PA-24 1959 Owners Handbook	PA-24	11/22/58			General	13H3
312	Tooling - Piper Autocontrol	PA-24	11/24/58	**		2210	13H4
314A	Landing Gear Warning System	PA-24-180/250	06/08/59	754-221 754-217		3260	13H6
315	PA-24 Comanche Landing Gear Transmission Assembly	PA-24	02/04/59			3200	13H7
316	Cabin Sealing	PA-24-180/250	04/07/59	**		5300	13H16
317	50 Ampere Generator Installation	PA-24-180/250	04/06/59	754-230		2400	13H18
321	Piper Autocontrol	PA-24	07/08/59			2210	13H22
323	Defroster Operation	PA-24-180/250	11/23/59			2140	13H24
324C	Maintenance And Inspection Of Exhaust Systems And Heat Exchanger	PA-24	1/22/69		62-26-05 68-05-01	7810	13I1
325	Front Cabin Window Defroster Kit	PA-24-180/250	12/24/59	754-293		2140	13I9
333C	Radio Shelf Capacities	All PA-24	01/28/63			3400	13J13
339	Insulation Of Wiring At Starter Solenoid Switch	PA-24-180/250	07/12/60	13586-94		8010	13J21
345	Hartzell Service Bulletin #75 - Inspection Of Hartzell Governor For Presence Of Vent Hole	PA-24-250	09/14/60			6110	13K5

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
346	Relocation Of Safety Belt Buckle - Right Front Seat Only	PA-24-180/250	09/29/60			5340	13K8
347	Installation Of Dry Vacuum Pump, Exhaust Tube	PA-24-180/250	12/02/60	754-358		3710	13K9
352	Modification Of Windshield Defroster System	PA-24-180/250	12/28/60	754-380		2140	13K14
356	Installation Of Landing Gear Retraction System, 30 Amp Circuit Protector	PA-24-180/250	03/31/61	454-661	63-27-03	3230	13K21
360	Flap Retractor	PA-24-180/250	09/05/61	754-413		2750	13L3
364A	Rubatex Blocks In Detached Or Loose Wing Panels	PA-24-180/250	03/14/62			5700	13L15
365	Special Bolt For Nose Gear Drag Link	PA-24-180/250	01/03/62	22066-00		3200	13L17
366	Nose Gear Clevis	PA-24-180/250	01/03/62	20859-03	65-25-03	3220	13L19
367	Caps, Fuel Cell, "Thermos Bottle" Type	PA-24-180/250	02/01/62		68-13-03	2810	13L21
368	Lycoming Service Instruction #1049 Dated 12/29/61	PA-24-250	02/07/62	**		7200	14A1
370	Modification To Engine Breather Line	PA-24/24-250	02/23/62			7200	14A7
372	Landing Gear Switch	PA-24-250	03/08/62			3230	14A10
373	Dry Vacuum Pumps (Airborne Mechanisms) Models 113A1 And 113A5, Installation Of Oil Shields On	PA-24-180/250	03/29/62	756-143		3710	14A11
379	Landing Gear Safety Switch Harness	PA-24-180/250	08/10/62	754-475	64-22-03	3200	14A20
380	Door Hinges, Main Landing Gear, And Nose Gear Door Hinge Bushings	PA-24-180/250	08/08/62	**		3210	14A22
382	Redesigned Landing Gear Selector Switch Knob	PA-24-250	09/27/62	**		3200	14B1
393	Replacement Of Bendix Fuel Pump	PA-24-250	02/01/63	481-686		2820	14B22
395	Flap Retraction Springs	PA-24-250	02/11/63	83302-54		2750	14C1
397	Inspection Of Alternate Air Door Hinge Pin	PA-24-250	02/21/63			7160	14C5
404	Inspection Of Pitch Servo Assembly Chain Adjustment Screw Altimatic And Altimatic II	PA-24-180/250	09/16/63	**		2210	14C17
408	Installation Of Fuel Valve Control Stop	PA-30	10/09/63	756-774		7320	14D1
409	Replacement Of Nose Gear Retraction Tube	PA-30	10/09/63	21109-05	64-16-06	3230	14D4
411	Drain Holes In PA-30 Cowling	PA-30	10/17/63			7110	14D8

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
412A	Muffler And Tailpipe Support	PA-24-250	05/06/64	756-775	68-05-01	7810	14D11
414	Modification Of Right Side Exhaust Stack	PA-24-250	11/27/63	756-777 756-778		7810	14D15
415	Sealing Of The Nose Wheel Well	PA-30	12/03/63			3240	14D18
416	Heater Valve Friction Spring Installation	PA-30	12/03/63	756-779		2140	14D20
417	Replacement Of Fuel Injector Inlet Screens	PA-30	12/16/63	756-782		7310	14E1
418	Replacement Of Fuel Flow Gauge	PA-30	12/16/63	24536-00		7330	14E3
419	Inspection Of Heater Air Distribution Box Attachment Screws	PA-30	02/24/64	**		2140	14E4
420A	Removal Of Vanes From Throat Of Carburetor Air Box	PA-24-250	03/10/72		64-10-04	7200	14E6
422	Rework Of Propeller Spinner Assembly	PA-30	03/10/64	756-796		6110	14E11
424	Installation Of "Generators On" Placard	PA-30	04/20/64	**		2430	14E15
425	Lycoming Service Bulletin No. 298	PA-24-180/250	05/15/64	**		7200	14E17
426	Propeller Flange Inspection, Crankshaft (Per Lycoming Service Bulletin No. 300) And Propeller Blades, Inspection Of (Per Hartzell Service Bulletin No. 86)	PA-30	06/26/64			6110	14E22
430	Inspection Of Nose Gear Drag Link Assembly	PA-30	08/17/64			3220	14F6
431	Insulation Of Motor Mounts	PA-24-250	09/02/64	756-831		7120	14F8
433	Installation Of Placard, (Cowl Flaps Open)	PA-24-400 PA-30	09/09/64	755-881		7110	14F12
434	Lycoming Service Instruction #1110	PA-24-250	09/30/64	25006-00		7200	14F14
435	Relocation Of Nose Wheel Steering Tube Boot	PA-24-250	09/30/64	21378-00		3250	14F15
437	Replacement Of Fuel Gauge Assembly	PA-24-400	11/04/64	450-771		2820	14F19
439	Lycoming Service Bulletin No.300A	PA-30	11/13/64			6110	14G1
440	Engine Compartment Changes	PA-24-400	12/03/64	**		7200	14G4
444	Installation Of Special Steel Fittings On Auxiliary Fuel Pumps	PA-24-250	02/24/65	751-268		2810	14G9
445	Installation Of Nose Gear Drag Link Clevis Reinforcement Bracket	PA-24-180/250	04/21/65	756-911		3270	14G11
446	Fuel Leakage At the Fuel Cell Gauge	PA-24-400	03/01/65	756-902		2810	14G13
447	Inspection Of Landing Gear Transmission Retract Spring	All PA-24 PA-30	03/26/65	**		3230	14G14

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
449A	Fuel Cells	PA-24-180/250/400 PA-30	02/18/69			2810	14G16
451	Fuel System Purging Valve	PA-24-400	05/14/65	756-922	66-30-07	2810	14G18
453	Engine Mount Refinishing	PA-24-400	08/23/65	756-306		7110	14G19
459	Mixture Control Cable Shield	PA-24-400	10/06/65	25079-00		7320	14H8
460	Revision To PA-30 Service Manual And Owner's Handbook	PA-30	09/17/65			3260	14H10
461	Inspection Of Propeller Blades	PA-30	09/28/65			6110	14H11
464A	Bendix RS Fuel Injection	PA-24-250/260 PA-30	11/12/65	**		7310	14I1
465	Airworthiness Directive No. 65-25-03	PA-24/24-250	12/20/65			1617	14I3
469	Replacement Of Allowance Placard, Baggage/Passenger	PA-24-260	02/11/66	756-997		5430	14I7
470	Starter Vibrating	PA-24-400	04/01/66	492-671		8010	14I8
477	FAA Airworthiness Directive No. 66-12-2 (Temporary Revision To Airspeed Limits)	PA-30	05/18/66			3410	14I19
478	Inspection Of Baggage Door Latch Enlargements	PA-24-260	06/13/66		66-18-04	5210	14I22
481	Muffler And Tailpipe Support	PA-24-250	09/15/66	757-058	68-05-01	7810	14J2
486A	Cylinder Head Temperature Probe Location	PA-24	04/16/68			7720	14J13
490	Rajay Corporation Service Letter No. 10 (Relocation Of Turbocharger Low Oil Pressure Warning Light Wire)	PA-30	06/28/67	757-312		7930	14J16
511	Modification To The Auxiliary Power Receptacle Installation	PA-24-260 PA-39	08/30/68	760-181 760-711		2400	14K23
516	Modification Fuel Cell Vent System	PA-24-180/250	03/07/69	760-277 760-281	68-13-03	2810	14L11
518	Modification Of Exhaust Mufflers	PA-24-260	01/22/69	760-289	68-05-01	7820	14L14
525	Addition Of Lock Washers To Electrical Switch Installations	PA-30	02/28/69	**		2400	15A8
532	Voltage Regulator Component Grounding	PA-30	07/07/69	760-332		2430	15B2
539	Fuel Selector Valve Control Handle Replacement	PA-30	02/18/70	760-356 760-357		2820	15B20
541	Fuselage Nose Cone Drain Holes	PA-30	12/04/69			5350	15C1
542	Control Surface Travel And Cable Tension	PA-30	02/17/70			2700	15C3
543	Induction System Drain Tube Relocation	PA-24-260 "C"	11/17/69	760-351		7160	15C5
546A	Nose Gear Push-Pull Rod Assembly	PA-24-180/250 PA-24-400	03/10/70	757-352		3250	15C12

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
549	New Owner's Handbook	PA-30	03/20/70	**		General	15C19
552	Counter Rotating Power Plant Conversion-Kit	PA-30	05/01/70	760-368		7100	15D3
556A	Turbocharger Waste Gate Return Spring	PA-30/39	09/21/70	**		8120	15D17
557	Rajay Oil Scavenge Pump	PA-30	06/16/70	**		7250	15D19
558	Air Flow Modification Kit	PA-30	07/01/70	760-409		2700	15E1
564	Revised Hartzell Propellers	PA-30/39	09/28/70	**		6120	15E18
565	Rear Cabin Dome Light Mounting Screw	PA-24-260 PA-30/39	10/13/70			3320	15F1
566	Autopilot Servo Spacer Bushing Installation	PA-24-260 PA-30/39	11/25/70	760-472		2210	15F3
569	Engine Compartment Modifications	PA-24-260	12/28/70	760-463		7200	15F14
574	Revision To Emergency Gear Checklist	PA-24-260 PA-30/39	03/22/71			3200	15F20
575	Landing Gear (Nose) System Inspection	PA-30/39	04/08/71			3220	15F23
584	90 Amp Alternator Circuit Breaker Switch Inspection	PA-30/39	07/08/71			2430	15H4
589	Stainless Steel Fuel Selector Valve Housing	PA-30	08/18/71	757-187	83-10-01	2820	15H10
595	Wing Flap System Maintenance	PA-24-250/260/ PA-24-400 PA-30/39	10/11/71			2750	15I1
596A	Nose Landing Gear System Product Advancement Information	All PA-24 PA-30/39	09/05/75	**		3220	15I3
598	Adjustable Duct Micro Switch Inspection	PA-39	11/16/71	487-940		2140	15I9
599	Exhaust Wing Panel Corrosion Protection	PA-30/39	11/23/71			5750	15I10
605	Reissue Of Owner's Handbook	PA-24-260T	01/17/72	**		8100	15J1
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	02/21/73			5500	15J21
610	Tail Control Surface Inspection, Maintenance And Repair Information PA-24 Commanche Service Manual Temporary Revision TR 720127	All PA-24	02/28/72	**		2700	15J23
617B	Piper Automatic Locator Transmitter Replacement	PA-24 PA-39	08/30/73		72-22-03	2560	15K18
623	Inspection Of Rajay Alternate Air Valve Bracket	PA-30/39 T.C.	08/09/72	**		7160	15L14
627	Propeller Installation	PA-24-260 PA-30/39	09/01/72			6100	16A1
633	Inspection And Repair Of Flood Exposed Airplanes	PA-24 PA-39	10/09/72			5300	16A18

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
636	Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement)	PA-24 PA-30	10/24/72	**		2430	16B2
637	Rajay Service Letter No. 19, Dated September 5, 1972	PA-30/39 T.C.	10/31/72	**		7160	16B5
638A	Edo-Aire Mitchell Service Letter No. ML-35 (Servo Lubrication—Rack And Pinion Type Servos)	PA-24 PA-30	02/08/73			2210	16B7
642	Revised Alternator Inoperative Warning Light	PA-39	02/19/73	760-711		2430	16B15
648	Battery Ground Inspection And Modification	PA-24-260 "C"	03/08/73			2430	16C2
650	Inspection Of Transmission Assemblies, Landing Gear Retraction And Flap Control	PA-24-180/250 PA-24-260/400 PA-30/39	09/27/73	**		3230 2750	16C5
651	Rudder Balance Weight Arm Attachment Angle Installation Kit	PA-24-180/250 PA-24-260	02/27/73	760-732		2720	16C10
653	Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972)	PA-24 PA-30	04/09/73	**		7610	16C14
657	Fuel Selector Valve Control Handle Modification	PA-30/39	09/13/73	760-788		2820	16D3
665A	Intake Valves; Rotator Type (Reference Avco Lycoming Service Instruction No. 1280 A. 9/28/73)	PA-24-400	10/24/73	**		7160	16D16
667A	Stabilator Attachment Bolts	PA-24-260/400 PA-30	03/04/74	**	74-13-03	2740	16E1
679	Fuselage Aft Bulkhead Inspection	PA-30/39	01/21/74	760-783	74-16-08	5310	16F2
682B	Reference Lycoming Service Bulletin 367D	PA-24-250 PA-24-400 PA-30	04/19/74	**		7230	16F9
686	Inspection Of Fuel Pressure Hose Assembly	PA-24-250/260	01/03/74	17766-43		7330	16F20
687	Stabilator Modification	PA-24-250/260	06/19/74	760-747	72-22-05	2740	16F23
695	Roll Servo Inspection, Maintenance And Sheer Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38 Dated March 18, 1974)	PA-24 PA-30	05/03/74	**		2210	16G13
696	Control Surface Balancing Recommendation	PA-24 PA-30/39	05/02/74			2700	16G20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
707	Flyball Assembly To Improve RPM Control. Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973)	PA-24 PA-30/39	02/27/74	**		7710	16I11
718	Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)	PA-24	05/31/74	**		7410	16J18
751	Fin Front Spar Modification	PA-24-180-250 PA-24-260/400	07/07/75			5520	17A23
758	Bendix Ignition Switches, Inspection Of; Ref: Bendix Service Bulletin No. 583	PA-24-180/250 PA-24-260/400	05/17/76	761-065V		7410	17C2
772	Stabilator Attachment Bolts	PA-39	02/16/76	**	74-13-03	2740	17E4
777	Fin Front Spar Modification	PA-30/39	06/16/76		76-18-05	2740	17E12
782B	Landing Gear Manual Extension System And Nose Gear Down Lock Spring Installation	PA-24 PA-24-250/260 PA-24-400 PA-30/39	03/21/77	**	77-13-21	3230	17E23
787	Aileron Spar Inspection And Reinforcement	PA-24/24-250/260 PA-24-400 PA-30/39	12/01/76	760-914	77-08-01	5750	17F17
850	Aileron Nose Rib Inspection/Reinforcement	All PA-24 All PA-30/39	04/18/79		79-20-10	5750	17L8
851	PART A - Fuel Valve Internal Leak Check	PA-24-400 PA-30/39	08/31/78	**	79-12-08	2810	17L11
851	PART B - Fuel System Draining Procedure-Water Contamination	PA-30/39	08/31/78	**	79-12-08	2810	17L12
851	PART C - Fuel System Draining Procedures-Water Contamination	PA-24-400	08/31/78		79-12-08	2810	17L14
1041	Accident/Incident Reporting	All	03/10/02	N/A		N/A	19K10
1052	Life Limited Parts Marking and Disposition	All	05/21/02	N/A		0510	19L19
1069	Flight Control Cable Terminal Corrosion Inspection	All	03/31/03	N/A	CE-02-05 (SAIB)	2702	20C2

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

GRIDS 1G22 THRU 1G24
INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
177	Firewalls	PA-28 PA-28R	08/10/51				13B13
295A	Aircraft Finishes	PA-28	01/03/64				13F12
324C	Maintenance And Inspection Of Exhaust Systems And Heat Exchanges	PA-28	01/22/69		62-26-05 68-05-01	7810	13I1
371A	Propeller Bolt Torque	PA-28	04/17/62			6120	14A9
373	Installation Of Oil Shields On Dry Vacuum Pumps (Airborne Mechanisms, Models 113A1 And 113A5)	PA-28-150/160	03/29/62			3710	14A11
374	Modification Of Bulkhead To Prevent Control Cable Interference	PA-28-150/160	04/10/62	754-461V		5310	14A13
375	Control Shaft-Left Hand, Installation Of Micarta Sleeve On	PA-28-150/160	04/12/62	62852-00V		2700	14A15
381	Replacement Of Wing Panels Service	PA-28-150/160	07/09/62	**		5730	14A23
386	Miscellaneous Airframe Modifications	PA-28-150/160	09/04/62	**		5300 5320 5550	14B7
389	Inspection Of Exhaust Stacks	PA-28-150/160	12/11/62	**	62-26-05	7810	14B13
390	Cherokee Gas Cap Placard	PA-28-150/160/180	01/03/63	62142-00V		2810	14B16
391	Cherokee Sun Visors	PA-28-150/160/180	01/11/63	63230-00V		2510	14B18
394	Radio And Auto Control Cooling Kits	PA-28	02/04/63	754-477V 754-494V		2300	14B23
396	Inspection Of Shaft Assembly (On Control T-Bar And Control Wheels).Double Sprocket	PA-28-150/160	02/14/63	62818-00V	64-06-06	2710	14C2
402	Installation of Heat Shield Kit	PA-28	05/22/63	756-727		2140	14C13
413	Inspection Of Nose Gear (Upper) Oleo Bearing	PA-28-150/160/180	11/25/63	452-419		3230	14D13
421	Inspection Of Oil Coolers	PA-28-235	03/04/64	18622-00		7920	14E9
425	Lycoming Service Bulletin No. 298 (Ac Fuel Pump Vent Restriction)	PA-28-140/150/160 PA-28-180/235	05/13/64	**		2800	14E17
427	Fuel Cooling Modification	PA-28-150/160/180	06/29/64	**		2820	14F2
429	Replacement Of Oil Coolers	PA-28-235	08/10/64	**		7920	14F3
436	Check Of Alternator Through Bolts	PA-28-140/150/160 PA-28-180/235	10/09/64	753-210V		2430	14F17
442	Lycoming Service Instruction No. 1110 (Ac Fuel Pump Replacement)	PA-28-140/150/160 PA-28-180/235	12/14/64	**		2820	14G7
443	Oil Line Relocation Kit	PA-28-150/160/180	01/27/65	756-905V		7920	14G8
450	Stabilator Trim Installation	PA-28-140/150/160 PA-28-180/235	09/24/65	**		2740	14G17

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

REVISED: 04/01/02

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
456	Cherokee 235 Constant Speed Propeller Control	PA-28-235	06/04/65	756-959V		6120	14H2
457	Plastic On The Cherokee C Spinners	PA-28-150/160/180	06/29/65	756-963V	66-20-05	6110	14H3
458	Throttle Clamp	PA-28-140/150/160 PA-28-180/235	10/08/65	554-860V		7610	14H5
471A	Inspection Of Propeller Spinner And Spinner Attaching Bulkhead	PA-28-150/160/180	05/23/66	**	66-20-05	6110	14I9
473	Sensenich Service Bulletin No. R-11 (Inspection Of Mid-Blade Area Of 76 EMM And 76 EMMS Propellers)	PA-28-180	03/01/66			6110	14I14
484	Fuel System Operating Procedures	PA-28-235	12/20/66			2800	14J7
486A	Cylinder Head Temperature Probe Location	PA-28	04/16/68			7720	14J13
494	Inspection Of Cherokee Landing Gears	PA-28-140/150/160 PA-28-180/235	11/07/67	**		3200	14J24
495	Inspection Of Constant Speed Propeller Control Cable	PA-28-235	01/29/68	**		6120	14K2
501	Oil Sump Drain Valve	PA-28R-180	05/02/68	756-517		7160	14K10
503	Inspection Of Oil Cooler Hose	PA-28-140	04/18/68			7920	14K13
526	Sensenich Service Bulletin No. R-13	PA-28	05/15/69	760-325V		6100	15A11
527D	Inspection Of Control Wheels	PA-28-140/150/160 PA-28-180/235	06/21/78	**	69-22-02	2700	15A14
534A	Availability Of Engine Oil Quick Drain Valve	PA-28R-200	01/07/70	492-172V		7920	15B7
535A	Rudder Trim Locking Pin	PA-28-140/180/235 PA-28R-180/200	09/26/69			2720	15B9
561	Inspection Of Cherokee Muffler Assembly	PA-28-140/150/160/S160 PA-28-180/S180	08/12/70	99482-00V 99482-02V		7820	15E8
566	Autopilot Servo Spacer Bushing Installation	PA-28-140/180/235 PA-28R-180/200	11/25/70	**		2210	15F3
567	Flight Manual Supplement (Expanded Center Of Gravity Range)	PA-28-180/235	01/25/71	**		3200	15F6
568	Inspection Of Engine Mount Tubes	PA-28R-180/200	01/05/71	**		7120	15F8
571	Flap Handle Assembly Modification	PA-28 PA-28R-180/200	03/30/71	400-673		2750	15F15
576	Stabilator Balance Weight Tube Replacement	PA-28-140/150/160 PA-28-180/S180/235 PA-28R-180/200	04/20/71			5510	15G2
577	Replacement Bridle Cable Servo Clamp	PA-28-140/150/160 PA-28-180/235 PA-28R-180	06/01/71	757-863V		2210	15G8
581	Inspection Of Aileron Hinge Doubler	PA-28 PA-28R-180/200	07/12/71	760-540V		5550	15G20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
587	Engine Baffle Modification	PA-28R-200	09/16/71	760-558V		7230	15H9
600	Main Landing Gear Torque Link Inspection	PA-28 Fixed Gear	01/04/72	65691-00V	72-08-06	3210	15I12
607	Emergency Gear Lever Knob	PA-28R-180/200	02/18/72	66980-02V	72-04-03	3200	15J9
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	02/21/73			5500	15J21
611	Repositioning Of Oil Cooler Hose	PA-28-140	04/28/72	760-599V		7920	15J24
612A	Fuel Leakage - Fuel Sender Unit	PA-28 PA-28R-180/200	06/08/72	68101-00V		7330	15K1
614	Stabilator Attachment Fittings Bolt Torque	PA-28 PA-28R-180/200	06/15/72		72-14-07	2740	15K6
615	Stabilator Drain Holes	PA-28 PA-28R-180/200	07/06/72			2740	15K8
616	Main Landing Gear Trunnion Repair	PA-28R-180/200	08/03/72	**		3210	15K14
617B	Piper Automatic Locator Transmitter Replacement	PA-28 PA-28R	08/30/73		72-22-03	2560	15K18
620	Forward Cabin Door Reinforcement	PA-28-140/150/160 PA-28-180/235/28S-180 PA-28R-180/200	02/23/73	760-729V		5210	15L8
621	Main Landing Gear Torque Link Replacement	PA-28 Fixed Gear	11/09/72	78032-00V		3210	15L10
626	Landing Gear Bolt Lubrication	PA-28R-180/200	11/20/72			3200	15L23
634	Revision Pilot's Operating Manual	PA-28R-200	12/14/72	**		1200	16A23
636	Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement	PA-28	10/24/72	**		2430	16B2
638A	Edo-Aire Mitchell Service Letter No. ML-35 (Servo Lubrication - Rack And Pinion Type Servos)	PA-28	02/08/73			2210	16B7
644	Precautionary Throttle Operating Placard	PA-28-140/150/160	02/08/73	76406-00V	72-24-02	7610	16B19
647	Seat Back Stop Modification	PA-28-140/180/235 PA-28R-200	03/31/73	760-740V		2510	16C1
649	Airplane Flight Manual/Weight And Balance Revision	PA-28-235	05/03/73	**		0800	16C4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

REVISED: 03/01/02

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
653	Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972)	PA-28 PA-28R	04/09/73	**		7610	16C14
662	Engine Mount Bolt Torque	PA-28 PA-28R-180/200	07/06/73	AN960-616		7120	16D10
665A	Hoses, Engine Oil, Inspection Of Intake Valves, Rotator Type Knob, Emergency Gear Lever	PA-28R-200	10/24/73	**		7160	16D16
670A	Throttle Control Modification	PA-28-140	06/24/74	760-780V 760-872V	74-13-04	7610	16E7
671	Rudder Bar Assembly Inspection And Modification	PA-28 PA-28R-180/200	10/05/73			2720	16E9
682B	Required Inspection Of Piston Pin (Reference Lycoming Service Bulletin No 367D)	PA-28 PA-28R	04/19/74			7230	16F9
684	Landing Gear Lubrication	PA-28R-200	01/09/74			3200	16F18
695	Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No ML-38, Dated March 18, 1974)	PA-28	05/03/74	**		2210	16G13
700	Toe Brake System Modification	PA-28-140/151 PA-28-180/235 PA-28R-200	04/09/74	760-842V		3240	16H5
707	Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No 75, Dated November 16, 1973)	PA-28 PA-28R	02/27/74	**		7710	16I11
715	Emergency Locator Transmitter Switch Cover Modification	PA-28-140/151 PA-28-180/235 PA-28R-200	09/27/74	760-876V		2560	16J12
718	Bendix Magneto Bulletin No 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)	PA-28R	05/31/74	**		7410	16J18
720	Fuel Quantity Placard Inspection, Section I, Landing Light WIRE Rerouting, Section II	PA-28-235	06/26/74	**	74-18-06	2840 3340	16K2
731	Cherokee Warrior Product Refinement Program	PA-28-151	10/15/74	760-857V		1. 2800 2. 7160 3. 7920 4. 7110 5. 3340 6. 6110 7. 7230	16L1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
734	Bendix ADF-T-12 C/D Installation Inspection And Modification	PA-28 PA-28R-200	12/03/74	760-857V		3450	16L8
735	Muffler Shroud Modification	PA28-151/180	12/11/74			7820	16L11
738A	Modification Of The Overhead Fresh Air Vent System	PA-28 PA-28R-200	01/14/75	760-900V 760-901V 760-902V		2120	16L20
740	Fuel Requirements	PA-28	04/20/76			2800	17A3
744	Steering System Modification	PA-28-140/151 PA-28-180/235	04/24/75			3250	17A13
745	Inspection Of Wing Main Spar Attach Bolts	PA-28 (Kits) PA-28R-200 (Kits)	04/24/75	404-890		5710	17A14
747	Inspection Of Throttle And Mixture Control Attachments	PA-28-180/235 PA-28R-200	05/28/75	**		7610	17A18
749	Torque Link Greaser Bolt Replacement Kit	PA-28-140/150/151 PA-28-160/180/181/235	10/14/75	790-910V		3210	17A21
756	Glideslope Indicator Placard, Dual (King Radio Installations Only)	PA-28-151/180/235 PA-28R-200	01/06/76	69669-112V		3430	17B22
758	Bendix Ignition Switches. Inspection Of; Re: Bendix Service Bulletin No 583	PA-28-140/151 PA-28-180/181/235 PA-28R-180/200	05/17/76	761-065V		7410	17C2
760	Inspection Of Main Landing Gear Castings	PA-28-140/150/151/160 PA-28-180/235	11/12/75	**		3210	17C12
761	Magnetic Compass Relocation Kit	PA-28-140/150/151 PA-28-180/235 PA-28R-180/200	11/17/75	760-795V		3440	17C14
762	Modification Of ELT Remote Switches	PA-28-140/151/180 PA-28-181/235 PA-28R-200	01/26/76	760-009V		2560	17C15
763A	Seat Retention Mechanism Inspection, Rear Leg Quick- Disconnect	PA-28-180/235 PA-28R-180/200	11/14/75	**	75-24-02	2510	17C16
785	Carburetor Induction Air Shroud Modification	PA-28-151	09/15/76	**		7160	17F13
788	Air Conditioning Installation	PA-28-140/180/181 PA-28R-200	09/03/76	79584-02V 79589-05V		2150	17F19
793	Flap Warning Placard	PA-28 PA-28R-180/200 PA-28R-201/201T	01/06/77	35664-02		2750	17G5
796	Lower Cowl Drain Inspection	PA-28-150/160 PA-28-180/181/235	03/30/77			7100	17G10
800	Refinement Of Narco ADF-140 Installation Performance	PA-28-140/151 PA-28-180/181/235 PA-28R-200	02/25/77	**		3450	17G19
808	Hydraulic Pump Terminal Inspection	PA-28R-201T	06/08/77	**		2910	17H14

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

REVISED: 03/15/00

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
810	Backup Diaphragm Replacement Landing Gear Extender	PA-28R-180/200 PA-28R-201/201T	04/15/77	761-138V		3230	17H18
813	Vertically Adjustable Seat Refinement	PA-28-140/151/161 PA-28-180/181 PA-28R-200/201/201T PA-28R-235	06/09/77	**		2510	17I8
814	Refinement Program Cherokee III And Turbo Arrow III	PA-28R-201 PA-28R-201T	09/26/77			5300	17I10
814	Part I - Engine Mount Painting	PA-28R-201T	09/26/77	763-415V		7100	17I10
814	Part II - Aileron Bellcrank Stop Assembly	PA-28R-201 PA-28R-201T	09/26/77	761-142V		2710	17I11
814	Part III - Winterization Plate	PA-28R-201T	09/26/77	37793-02V		7200	17I11
814	Part IV - Landing Light Wire Rework	PA-28R-201T	09/26/77			3340	17I12
814	Part V - Exhaust Heat Shield	PA-28R-201T	09/26/77	486-648V		7810	17I12
820	Replacement Of Lithium Sulphur Dioxide (LiSO2) ELT Batteries and/or Transmitters	PA-28-140/151/161 PA-28-180/181 PA-28-235 PA-28-236 PA-28R-200/201 PA-28R-201T PA-28RT-201 PA-28RT-201T PA-44-180	07/28/80	**		2560	17J2
826	Spinner Bulkhead Doubler	PA-28-151/161	08/25/77	35667-02V		6110	17J14
832	Wheel Well Reinforcement	PA-28R-180/200/201 PA-28R-201T	01/25/78			3240	17J21
836	Inspection And Modification Narco ADF-140/141 Antenna	PA-28 PA-28R-200 PA-28R-201/201T	02/09/78	**		3450	17K4
842	Main Landing Gear Torque Link Greaser Bolt Inspection And Replacement	PA-28-140/150/151 PA-28-160/161 PA-28-180/181 PA-28-235	09/26/78	760-910V		3210	17K17
845	Engine Breather Tube Winterization Kit	PA-28 PA-28R-180/200 PA-28R-201	07/07/78	763-828V		7250	17K22
848	Exhaust Heat Shield	PA-28R-201T	06/21/78	763-843V		7810	17L4
856	Fuel Drain Cover Replacement	PA-28-235	09/15/78	763-883V	78-23-01	2810	18A21
859	Landing Light Installation Modification	PA-28-151/161	11/08/78	760-854V		3340	18B2
860	Engine Exhaust System Modification	PA-44-180	12/04/79	**		7810	18B4
861	Part I - Forward Facing Seat Back Modification	PA-28-140/151/161 PA-28-180/181/235/236 PA-28R-200/201 PA-28R-201T PA-44-180	11/13/78	763-890V		2520	18B7

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
862	Main Landing Gear And Strut Fairing Replacement	PA-28-161/181 PA-28-236	03/30/79	763-918V		3210	18B11
863	Master Relay Diode Assembly - Refinement	PA-28-181 PA-28R-201 PA-28R-201T	11/17/78			2450	18B13
864	Part I - Forward Cabin Door Stop (Striker Plate) Installation	PA-28-140/151/161 PA-28-181/235/236 PA-28R-200/201 PA-28R-201T	12/08/78	**		5210	18B16
864	Part II - Cabin Heat Control Refinement	PA-28-140/151 PA-28-161/180/181 PA-28-235/236 PA-28R-180/200/201 PA-28R-201T	12/08/78	763-870V 763-871V		2140	18B19
864	Part III - Turn And Slip Indicator Conversion, Vacuum To Electric Provision	PA-28-140/150 PA-28-160/180 PA-28-235	12/08/78	763-874		3420	18B20
867	Part I - Engine Baffles Reinforcement	PA-44-180	10/10/79	**		7230	18C4
867	Part II - Replacement Of Nose Landing Gear Micro Switch Bracket	PA-44-180	10/10/79	763-925V		3230	18C5
867	Part III - Cowl Fastener Relocation	PA-44-180	10/10/79	420-690		7110	18C5
867	Part IV - Cabin Heater Air Inlet Valve Modification	PA-44-180	10/10/79	**		2140	18C6
867	Part V - Battery Box Drain Clamp Replacement	PA-44-180	10/10/79	454-983		2430	18C7
867	Part VI - Tachometer And Manifold Pressure Gauges Available Light Increase	PA-44-180	10/10/79			7710	18C7
867	Part VII - Landing Light Grounding Strap Installation	PA-44-180	10/10/79	**		3340	18C8
891	Air Induction Filter Retainer Improvement	PA-28-151/161	03/04/81	87349-02V		7160	18F24
895A	Magneto Switch Modification	PA-28R-201 PA-28RT-201T	03/19/81	153-010 488-396		7430	18G8
899	Part I - Aft Spinner Bulkhead Refinement	PA-28-161	10/03/80	36757-003V		6110	18G16
899	Part II - Forward Spinner Bulkhead Refinement	PA-28-161	10/03/80	**		6110	18G17
901	Cabin Air Intake Duct Modification	PA-28-161/181/236 PA-28RT-201/201T PA-44-180	09/02/80	764-013V		2120	18G22

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
903A	Alternator Belt Installation (Air Conditioned Models)	Any Textron-Lycoming Powered PA-28	03/11/96	62833-82		2431	18H2
905	Compass Deviation-Battery Ground Wire Replacement	PA-28RT-201	01/21/81	764-087V		2430	18H7
906	Lower Cowl Exhaust Fairing Replacement	PA-44-180	04/21/81	**		7110	18H8
907	Weight And Balance Plotter Modification	PA-44-180	01/22/81	764-040V		0800	18H10
908	Instrument Panel Lighting - Century 21 And 41 Autopilot Installation	PA-28-161/181 PA-28-236 PA-28RT-201 PA-28RT-201T	12/20/80			3310	18H11
910	Engine Oil Quick Drain Valve	PA-28R-200/201 PA-28RT-201	12/29/80	87369-26V 492-172V	81-11-02	7920	18H17
915	Firewall Reinforcement	PA-44-180	04/14/81	764-103V		5410	18I7
920	Required Placard Adhesion Check	PA-28-161/181 PA-28-201T PA-28-236 PA-28R-201/201T PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	06/29/81			2500	18I19
933	Engine Baffle Seal Security	PA-44-180 PA-44-180T	11/23/81	189-780		7230	18J20
951	Aft Fuselage Moisture Drain	PA-28-236 PA-28RT-201	10/06/82	764-386V		2120	18L2
988	Nose Landing Gear Modification	PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T PA-44-180 PA-44-180T	07/29/86	**	94-14-14	3225	19D1
997	Wing Removal And Reinstallation; Reference Airworthiness Directive 87-08 08	PA-28-140 PA-28-150/160/180 PA-28-151/161 PA-28-181 PA-28-235 PA-28R-180 PA-28R-200 PA-28R-201/201T PA-28RT-201/201T	05/14/87	**	87-08-08	5711	19D24
1019A	Alternator Support Bracket Improvement	PA-28-181 III	01/22/98	101103-02 418-421		2412	19H1
1024	Induction Airbox Air Valve Busing Improvement	PA-28-181	08/04/99	**		7164	19H20
1027	Manifold Pressure Line Filters Addition	PA-44-180	11/05/99	560-686 **		7164	19I7

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1028A	Induction Airbox Inspection/Repair and Inlet Air Duct Replacement	PA-28-181 III	01/04/00	766-666 85479-003 85489-011		7164	19I11
1029	Recognition Light Circuit Breaker Inspection/Replacement	PA-28R-201	02/03/00	454-708 87369-053		2454	19I15
1033	Air Conditioning Hose Replacement	PA-28-181 III	07/09/01	566-419 454-868		2155	19J4
1034	Compass Accuracy Improvement Modification	PA-44-180	07/20/01	766-699		3447	19J9
1038	Combustion Heater Fuel Pump Replacement	PA-44-180 PA-44-180T	09/04/01	766-686		2148	19K1
1040	Alternator Drive Belt Conversion Kit for Aircraft Equipped with Optional Factory Installed Air Conditioning	PA-28-180 PA-28-181 PA-28R-200 PA-28R-201 PA-28RT-201	11/28/01	767-310		2410	19K7
1041	Accident/Incident Reporting	All	03/10/02	N/A		N/A	19K10
1045	Electric Fuel Pump Upgrade	PA-28R-201	03/26/02	461-758		2825	19K21
1047	Pilot Sidepost Handgrip Kit	PA-28-161 Cadet PA-28-161 PA-28R-201 PA-44-180 PA-44-180T	05/28/02	767-343		2510	19L3
1052	Life Limited Parts Marking and Disposition	All	05/21/02	N/A		0510	19L19
1060	Engine Primer Hose Improvement	PA-44-180	02/11/03	63901-200 63901-201		7300	20A23
1063	Stabilator Bellcrank Bracket Assembly Inspection	PA-28RT-201 PA-28RT-201T PA-44-180 PA-44-180T	04/21/03	N/A		2792	20B7
1066	Ignition Harness Routing Inspection	PA-28-181 III	04/24/03	189-549		7420	20B17
1069	Flight Control Cable Terminal Corrosion Inspection	All	03/31/03	N/A	CE-02-05 (SAIB)	2702	20C2
1074	S-TEC Autopilot Component Seating Procedure	All	11/03/03	N/A		2210	20C14

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

THIS PAGE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
487	Test Unit, Hydraulic (And Fabricated Jack Stand)	PA-31/31-300	02/13/67	753-080		0710	14J14
492	Replacement Of: (I) Landing Gear Selector Handle (And Associated Link Rod To Power Pak), General Instructions For Inspection And Operation Of, And (II) Nose Gear Idler Link Assy.	PA-31	09/06/67	**		3200 3220	14J20
497	Manifold Pressure Gauge Filter Assembly	PA-31	01/30/68	760-171		7710	14K4
498	Nose Gear Idler Link Assembly (Identification Tag)	PA-31	03/01/68	760-170		3230	14K5
500	Altimatec III Series- (I) Radio Coupler (II) Amplifier Replacement	PA-31	03/22/68	760-191 760-192		3400	14K7
502	Navajo Cabin Heat Modification	PA-31	03/18/68	760-187 760-188		2140	14K12
504	B. F. Goodrich Service Bulletin No. E-67-34	PA-31	04/08/68			3240	14K14
505A	Fuselage Drain Holes	PA-31	05/02/68			5300	14K16
506	Main Landing Gear (Outboard) Door Actuator Bracket	PA-31	05/02/68	757-178		3210	14K18
507	ADF Installation Spacer	PA-31	05/22/68	760-211		3400	14K19
508	Propeller Counterweight Attachment Bolt Clearance	PA-31/31-300	07/09/68	43556-00		6120	14K20
509	Pneumatic Pump Air Inlet Relocation	PA-31	06/24/68	760-200		3710	14K22
512	Attachment Of Rudder Tab Hinge Brackets	PA-31/31-300	10/08/68	760-243		2720	14L1
514	Flight Control Cable Systems	PA-31/31-300	09/09/68			2210	14L3
517	Beacon (Rotating) Attachment Screws-Shock Mounted Beacon	PA-31/31-300	10/23/68			3340	14L13
523	Modification To The Fuselage Bulkhead	PA-31/31-300	04/09/69	760-295		5310	15A3
524	Weldon Electric Fuel Pump Modification	PA-31/31-300	05/20/69	760-316 760-317		2810	15A5
530	Hydraulic Fluid Level Gauge "O" Ring Replacement	PA-31/31-300	05/23/69	484-815		2910	15A22
531	Cowl Flap Support Assembly	PA-31/31-300	08/22/69	760-330		7110	15A24
532	Voltage Regulation Component Grounding	PA-31/31-300	07/07/69	760-333		2430	15B2
537	Landing Gear Door Hinge Bracket Reinforcement	PA-31/31-300	10/16/69	760-348		3230	15B15
538	Inspection Of Propeller Blade Shank (Hartzell Service Bulletin No. 94)	PA-31 (2 Blade Props)	10/23/69			6110	15B17

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
548	Inspection Of The Right Engine Control System Installation	PA-31/31-300	03/16/70			7610	15C17
550B	Turbocharger Density Control Adjustment	PA-31 PA-31-350	07/10/74			8120	15C21
553	Equipment (Required) Pressurized Navajo Service Support	PA-31P	05/20/70	**		2130	15D12
555	Inspection Of Nose Gear Idler Link Assembly	PA-31/31-300	07/08/70			3220	15D15
562	Scott Aviation Service Bulletin No. 35-32	PA-31-300	08/25/70	**		3500	15E10
566	Autopilot Servo Spacer Bushing Installation	PA-31-300	11/25/70	760-473		2210	15F3
573	B F Goodrich Service Bulletin No. E-68-36B (Sealer For B F. Goodrich Deicer And Strap)	PA-31 PA-31-350 PA-31-P	03/04/71			3020	15F17
578A	Reference Lycoming Service Bulletin 335	PA-31	08/29/72	**		2820	15G13
580	Fuel Selector Valve Packing Lubrication	PA-31/31-300 PA-31-P	05/24/71	760-504		2820	15G18
593	Connector Plug, Harness Strain Relief Hood Installation	PA-31, Alt. V Or Alt. V/FD	10/11/71	760-556		2400	15H15
594	Inspection Of Flap Track And Rudder Tip Rib Assemblies	PA-31-300	10/08/71	**		5750 5510	15H19
603	Hartzell Service Letter No. 70	PA-31P	02/08/72	**		6110	15I17
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	02/21/73			5500	15J21
617B	Piper Automatic Locator Transmitter Replacement	PA-31 PA-31-350 PA-31P	08/30/73		72-22-03	2560	15K18
619	Inspection Of Retainer Spring Piper Part No. 83302-13	PA-31/31-300	06/09/72	83302 13		7330 7160	15L5
630	Lubrication Of Fuel Selector Valve Mechanism	PA-31/31-300 PA-31P	09/13/72	**		2820	16A11
631A	Wiring Inspection, Alternator Switch And Circuit Breaker Panel	PA-31/31-300	04/25/73	**		2430	16A13
633	Inspection And Repair Of Flood Exposed Airplanes	PA-31 PA-31-350 PA-31P	10/09/72			5300	16A18
635	Lycoming Service Bulletin No. 356 (Addition Of Alternator Bracket Support)	PA-31	10/16/72	**		2400	16A24
636	Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement)	PA-31 PA-31-350 PA-31P	10/24/72	**		2430	16B2

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
639	Alternator Field Switch Guard Modification	PA-31-P	12/20/72	760-721		2430	16B11
642	Revised Alternator Inoperative Warning Light	PA-31	02/19/73	760-713		2430	16B15
643	Control Shaft Collar Restraining Strap	PA-31/31-300 PA-31P	02/05/73	760-723	76-04-11	2700	16B17
653	Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265 Dated December 15, 1972)	PA-31	04/09/73	**		7610	16C14
654	Heater Control System Modification	PA-31-350	04/18/73	**		2140	16C17
655	Turbocharger Modification; Airesearch Service Bulletin No. 1172-1A(Reference Avco Lycoming Service Bulletin No. 361, Dated February 16, 1973)	PA-31 PA-31-350 PA-31P	04/10/73	**		8120	16C21
656	King Area Nav Operation Limitation Placard	PA-31-310 PA-31-350 PA-31-P	05/15/73	696-1109-00		3450 3400	16D2
658	Static System Line Modification	PA-31-350	06/14/73	760-750		2350	16D5
660	Revised Alternator Ground Wire Installation	PA-31-310 PA-31-350	07/06/73	760-778		2430	16D7
665A	Intake Valves, Rotator Type	PA-31/31-300 PA-31-350	10/24/73	**		7160	16D16
666	Propeller Governor Speed Adjusting Shaft, Lever And Lever Clamp Screw Replacement (Reference Woodward Service Bulletin No. 33549, Dated May 1973)	PA-31P	09/13/73	**		6120	16D18
674	Over Voltage Relay Inspection	PA-31-300/310 PA-31P	01/03/74	760-787		2430	16E16
675	Magneto Switch Guard Installation	PA-31-300/310 PA-31-350 PA-31P	09/17/73	760-789 760-790	74-26-10	2430	16E18
680	Receiver Dehydrator Relocation	PA-31-310 PA-31-350	11/29/73	760-803		2710	16F5
681	Inspection Of Elevator Balance Weight Bolts	PA-31-350	10/24/73	**		2730	16F7
682B	Required Inspection Of Piston Pin (Reference Lycoming Service Bulletin No. 367D)	PA-31 PA-31-350 PA-31P	04/19/74	**		7230	16F9
685	Installation Alternator Field Wire Clamp	PA-31P	10/24/73	760-807		2420	16F19

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
688	Unfeathering Accumulator Maintenance And Preventive Maintenance (Reference Woodward Service Bulletin No 33551, Dated August, 1973)	PA-31P	10/24/73			6120	16G1
690A	Cylinder (Engine) Baffle Removal And Cylinder Head Temperature Probe Relocation	PA-31-350	03/04/74			7720	16G4
691	Cigar Lighter Circuit Protector Replacement	PA-31P	11/12/73	760-809		3310	16G6
692	Heater System Modification	PA-31-350	02/12/74	760-804		2140	16G8
694	(I) Tailpipe Support Installation, (II) Exhaust Manifold Clamp Inspection (Reference Avco Lycoming Service Bulletin No. 368, Dated November 23, 1973)	PA-31P	05/07/74	760-837		7810	16G10
696	Control Surface Balancing Recommendation	PA-31/31-300 PA-31-350 PA-31P	5/2/74			2700	16G20
697	Fuselage Addition Of Drain Holes	PA-31-300/310 PA-31-350	3/14/74			5300	16G22
698	Ground Handling (Towing) Recommendations	PA-31-300/310 PA-31-350	2/26/74			3200	16G24
699	Fuel Vent Line Check Valve Installation (Reference Avco Lycoming Service Bulletin No. 362A; Dated December 14, 1973)	PA-31P	2/12/74	LW-13324		2810	16H2
701	Overvoltage Relays, Wiring Of; Alternator Paralleling System	PA-31P	3/14/74	**		2430	16H6
707	Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973)	PA-31 PA-31-350 PA-31P	2/27/74	**		7710	16I11
709	Inspection Of Pneumatic Pump Mounting Flanges	PA-31P	5/1/74			3710	16I17
711	Inspection Of Submerged Fuel Pumps	PA-31P	5/30/74	48812-00		2820	16J4
712	T-Bolt Clamping Bands, High Tensile (Reference Avco Lycoming Service Bulletin No. 372A, Dated March 15, 1974)	PA-31-350	5/15/74	LW-13886		8120	16J7
713	Static Air Sump Installation	PA-31-310 PA-31-350 PA-31-P	8/21/74	760-864		3410	16J9
716	Moisture Seal, Cross Shaft Support Tube (Reference Avco Lycoming Service Bulletin No. 375A, Dated May 10, 1974)	PA-31P	6/3/74	**		7200	16J13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
718	Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22. 1974)	PA-31 PA-31-350 PA-31-P	5/31/74	**		7410	16J18
719	Deicer Boot Installation Throttle Control Cable	PA-31P	8/28/74	760-874		7610	16K1
722	Fuel System Modification	PA-31-350	8/27/74	760-873		2800	16K9
723	Glideslope Indicator Placard	PA-31/31-300 PA-31-350 PA-31P	8/14/74	SK 2359		3430	16K11
725	Fuel Pressure Gauge Modification	PA-31-350	9/19/74	54209-02		7330	16K14
726	Cigar Lighter Placard	PA-31P	8/8/74	80247-02		3310	16K16
730	Air Conditioning System Modification	PA-31-350	8/20/74	760-881		2150	16K23
733	Pilot And Copilot Cabin Heat Refinement	PA-31-350	4/21/75	760-924		2140	16L7
739	Cabin Door Refinement	PA-31-300/31-310 PA-31 -350	6/2/75	**	78-05-05	5210	17A1
741	Radome Weather Seal	PA-31P	1/23/75	760-919 760-920		5340	17A7
752A	Replacement Of Alternator Ground Wire	PA-31P	10/30/75	760-988		2420	17B2
753	Propeller Feather Assist Spring Assembly Installation Reference Attached Hartzell Service Letter No. 101	PA-31-300/310/ 325 PA-31-350	7/16/76	**		6120	17B3
755C	Part I - Landing Gear Lock Actuator Rod And Rod End Bearing Assemblies Inspection And Lubrication	PA-31/31-300 PA-31-325 PA-31-350 T-1020 PA-31P	11/4/85	**		3235	17B13
755C	Part II - Landing Gear Lock Actuator Rod Replacement	PA-31/31-300 PA-31-325 PA-31-350 T-1020 PA-31P	11/4/85	764-958		3235	17B15
755C	Part III - Installation Of Anti-Rotation Stops	PA-31 PA-31-325 PA-31 -350 T-1020 PA-31P-350	11/4/85	**		3235	17B16
764A	Wing Flap System Maintenance Procedure	PA-31-300/325 PA-31-350 PA-31P	7/17/79		81-11-03	2750	17C19
766	Inspection Of Cleveland Brake Discs	PA-31-325 PA-31-350	1/6/77	**		3240	17D9
770	Aileron Sprocket/Chain Inspection	PA-31-300/325 PA-31-350 PA-31 P	1/27/77	**		2710	17D18

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
773	Nose Cone ("Radome") Latch System Refinement	PA-31P	6/28/76	761-012		5340	17E7
778	Elevator Butt Rib Refinement	PA-31P	6/14/76	54755-02		5520	17E14
781	Cockpit Forward Bulkhead/ Floorboard Sealing	PA-31-350	10/22/76	**		5310 5320	17E21
783	Inspection Of Air Conditioning System Capillary Sensor	PA-31P	9/20/76	**		2150	17F7
784	Landing Gear Hydraulic System Refinement	PA-31-300	9/27/76	491-050 484-459		2920	1 7F10
789	Inspection Of Elevator Bellcrank And Elevator Co ntrol Rod	PA-31-300/325 PA-31-350 PA-31P	10/6/77	**		2730	17F21
798	Cabin Headliner/Oxygen Cover Panel Refinement	PA-31P	2/4/77			2520 3520	17G13
801	Goodyear Tri-Metallic Brakes, Maintenance And Operation; Ref: Goodyear Service Letter "PA-31-350/31 P/31T SL-1" Dated January 15, 1977	PA-31-350 PA-31P	2/25/77			3240	17G21
802	Main Landing Gear Door Hinge Attachment Screw Replacement	PA-31/31-325 PA-31-350 PA-31P	3/9/77	761-128		3210	17G24
803A	Cabin Door Latch System Refinement	PA-31-300/325 PA-31-350	11/3/77	55633-03	78-05-05	5210	17H1
816	Powerpak Reservoir Replacement (Wiebel Hydraulic Powerpaks)	PA-31-350 PA-31P	12/19/77	763-831		2910	17I18
820	Replacement Of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters	PA-31/31-300 PA-31-325 PA-31-350	7/28/80	**		2560	17J2
821	Right Engine Cowl Louver Installation Kit	PA-31-350	3/7/78	763-802		7110	17J6
823	Heater/Evaporator Return Air Duct Hose Replacement	PA-31P	2/10/78	49478-02		2120	17J10
829	Emergency Exit Window Latch Modification	PA-31P	11/14/77	763-809		5620	17J18
830	24 Volt Cigar Lighter Element Replacement	PA-31 PA-31-325 PA-31-350 PA-31P	11/22/77	**		3310	17J19
833	Cabin Pressurization System Rupture Disc Elimination	PA-31P	4/10/78			2130	17J22
834	Flap Electrical System Refinement	PA-31/300/325 PA-31-350 PA-31P	3/3/78	**		2750	17J24
844	Heater System Rewiring	PA-31-350	4/24/78			2140	17K20

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
847	Avionics Emergency Bus Power Switch Guard Installation	PA-31P	8/13/79	**		2450	17L2
866	Windshield Wiper Arm Retaining Wire Installation	PA-31/31-300 PA-31-325 PA-31-350 PA-31P	12/7/79	151-295		5610	18C1
872	Alternator Wiring Inspection	PA-31/31-300 PA-31-325 PA-31-350	6/7/79	588-594		2430	18D6
873	Stall Warning System Refinement	PA-31 PA-31-325 PA-31-350	5/8/79			2700	18D9
874	Low Fuel Warning Sensor Sealing	PA-31 PA-31-325 PA-31-350	10/19/79	**		2840	18D12
875	Engine Front Baffle Replacement	PA-31 PA-31-325 PA-31-350	5/11/81	764-093	93-23-13	7230	18D16
878A	Oil Breather Tube Inspection/ Alignment	PA-31/31-300 PA-31-325 PA-31-350	3/6/81			7220	18E13
879	Razor Inverter Replacement	PA-31 PA-31-325 PA-31-350	5/20/80	467-488		3320	18E18
883	Wing Flap Rivet Installation	PA-31P	10/20/79	**		5750	18F8
885	Aileron And Elevator Control Systems Hardware Replacement	PA-31/31-300 PA-31-325 PA-31-350	3/10/81	763-996		5550	18F13
886	Master Switch Replacement	PA-31 PA-31-325 PA-31-350	1/6/81	764-090		2450	18F15
887	Starter And Battery Cable Inspection	PA-31 PA-31-325 PA-31-350	5/29/81	**		8010 2430	18F16
894	Heater Modification	PA-31-350	9/4/80	764-005		2140	18G7
904	Sealing Procedures To Prevent Water Leaks	PA-31/31-300 PA-31-325 PA-31-350	3/11/81	**		5210	18H5
912	Main Landing Gear Downlock Hook Rivet Replacement	PA-31/300/325 PA-31-350	3/5/81	420-890 422-241		3230	18H24
916	Elevator Control Stop Screw Replacement	PA-31/31-300 PA-31-350 PA-31P	7/17/81	**		2730	18I8
917	Portable Fire Extinguisher Inspection	PA-31 PA-31-325 PA-31-350	7/20/81	459-839 459-848		2620	18I11
921	Main Landing Gear Lock Rod Attachment Fork Replacement	PA-31P	4/21/82	764-127		3230	18I21

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
935	ELT Antenna Inspection	PA-31 PA-31-325 PA-31-350	3/26/82	**		2560	18J23
958	Flap Travel Restriction Supplementary Kit	PA-31/31-300 PA-31-325 PA-31-350 PA-31P	10/25/82	764-920L		5750	18L18
959	Flap System Modification	PA-31/31-300 PA-31-325 PA-31-350 PA-31P	6/10/83			5750	19A1
959	Part I - Calco Flap System Installation	PA-31/31-300 PA-31-325 PA-31-350	6/10/83	764-938L		5750	19A1
959	Part II - Flap Transmission Replacement (Dukes 20:1 To Calco 40:1)	PA-31/31-300 PA-31-325 PA-31-350 PA-31P	6/10/83	764-957L		5750	19A2
987	Main Landing Gear Mount Bolt Inspection	PA-31/31-300 PA-31-325 PA-31-350 T-1020 PA-31P PA-31P-350	7/25/86	400-384		3213	19C22
1041	Accident/Incident Reporting	All	03/10/02	N/A		N/A	19K10
1052	Life Limited Parts Marking and Disposition	All	05/21/02	N/A		0510	19L19
1069	Flight Control Cable Terminal Corrosion Inspection	All	03/31/03	N/A	CE-02-05 (SAIB)	2702	20C2

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

THIS PAGE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

GRIDS 1H20 THRU 1H24
INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	02/21/73			5500	15J21
736	M-4D Automatic Flight Control System Modification	PA-31T1	12/03/74	**		2210	16L14
741	Radome Weather Seal	PA-31T	01/23/75	760-919 760-920		5340	17A7
743	Cabin Altitude Controller Relocation	PA-31T	02/19/75	760-921		2130	17A12
755C	Part I - Landing Gear Lock Actuator Rod And Rod End Bearing Assemblies Inspection And Lubrication	PA-31T/31T1 PA-31-31T2/31T3 PA-42	11/04/85	**		3235	17B13
755C	Part II - LandingGearLock Actuator Rod Replacement	PA-31T/31T1 PA-31-31T2/31T3 PA-42	11/04/85	764-958		3235	17B15
755C	Part III - Installation Of Anti-Rotation Stops	PA-31T1	11/04/85	**		3235	17B16
764A	Wing Flap System Maintenance Procedure	PA-31T PA-31T1	07/17/79			2750	17C19
770	Aileron Sprocket/Chain Inspection	PA-31T	01/27/77	**		2710	17D18
773	Nose Cone ("Radome") Latch System Refinement	PA-31T	06/28/76	761-012		5340	17E7
779	Heater Fuel Pressure Relief Valve Inspection	PA-31T	08/16/76	**		2140	17E16
780	New Engine Top Mounts	PA-31T	06/08/76	761-612 761-613		7120	17E19
783	Inspection Of Air Conditioning System Capillary Sensor	PA-31T	09/20/76	**		2150	17F7
789	Inspection Of Elevator Bellcrank And Elevator Control Rod	PA-31T	10/06/77	**		2730	17F21
790	Paralleling Relay Terminal Strip Tab	PA-31T	09/21/76			2450	17G1
794	Wing Tip Tank Drain Hose Replacement	PA-31T	01/04/77	80007-37		5720	17G7
798	Cabin Headliner/Oxygen Cover Panel Refinement	PA-31T	02/04/77			2520 3520	17G13
801	Goodyear Tri-Metallic Brakes, Maintenance And Operation; Goodyear SL-1 Dated January 15, 1977	PA-31T	02/25/77			3240	17G21
802	Main Landing Gear Door Hinge Attachment Screw Replacement	PA-31T	03/09/77	761-128		3210	17G24
804	Heater System Maintenance And Operation	PA-31T	02/08/77	**		2140	17H4
805	Engine Ignition Exciter Box Relocation	PA-31T	03/18/77	761-126		7420	17H9

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
806	Air Scoop Lip Deicer Rewiring/ Hour Meter Harness Revision	PA-31T	02/22/77	456-763		3020 3120	17H10
809	Engine Oil Breather Tube Extension	PA-31T	04/06/77	55997-03		7920	17H16
811	Inspection And Relocation Oil Cooler Inlet Hose	PA-31T	04/26/77	80026-05		7920	17H19
816	Powerpak Reservoir Replacement (Wiebel Hydraulic Powerpaks)	PA-31T	12/19/77	763-831		2910	17I18
817	Propeller Synchronizer System Refinement	PA-31T	02/13/78	560-807		6120	17I20
819A	Air Conditioning Compressor Drive Belt Alignment Procedure	PA-31T	08/31/77	49186-02		2150	17I23
820	Replacement Of Lithium Sulphur Dioxide (LiSO2) ELT Batteries and/or Transmitters	PA-31T PA-31T1	07/28/80	**		2560	17J2
822	Engine Compartment Fire Extinguisher Switch Protection	PA-31T	07/12/77	**		2620	17J8
823	Heater/Evaporator Return Air Duct Hose Replacement	PA-31T	02/10/78	49478-02		2120	17J10
829	Emergency Exit Window Latch Modification	PA-31T	11/14/77	763-809		5620	17J18
830	24 Volt Cigar Lighter Element Replacement	PA-31T	11/22/77			3310	17J19
831	Heater Fuel Pressure Regulator Valve Installation	PA-31T	01/10/78	761-139		2140	17J20
833	Cabin Pressurization System Rupture Disc Elimination	PA-31T	04/10/78			2130	17J22
834	Flap Electrical System Refinement	PA-31T	03/03/78			2750	17J24
835B	Stability Augmentation System Refinement	PA-31T	06/20/80	763-830		2220	17K2
840	Air Conditioning System Refinements	PA-31T PA-31T1	08/29/80			2150	17K12
840	Part I - Condenser Fan Motor Support Bracket Replacement	PA-31T	08/29/80	764-034			17K12
840	Part II - Unpressurized Air Source Annunciator Light And Freon Pressure Limiting Device Installation	PA-31T PA-31T1	08/29/80	764-035			17K13
841	Heater Spark Plug Replacement Or Modification	PA-31T PA-31T1	01/07/80	763-495		2140	17K14
847	Avionics Emergency Bus Power Switch Guard Installation	PA-31T	08/13/79	**		2450	17L2
854	Generator Airscoop Door Replacement	PA-31T PA-31T1	01/03/79	763-875		8000	17L22

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

PA-31T/31T1
PA-31T2/31T3
PA-42

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
857	Propeller Beta Switch Replacement	PA-31T PA-31T1	02/07/79	763-839		6120	18A22
866	Windshield Wiper Arm Retaining Wire Installation	PA-31T PA-31T1	12/07/79	151-295		5610	18C1
868	Wing Flap Selector Switch Positive Detent Kit Installation	PA-31T PA-31T1	03/26/78	763-894		2750	18C16
871	Pedestal Control Assembly Inspection	PA-31T PA-31T1	03/07/79			7600	18D3
883	Wing Flap Rivet Installation	PA-31T PA-31T1	10/20/79	**		5750	18F8
888	Lift Transducer Case Rewire	PA-42	07/21/81	764-098		3050	18F21
890	Janitrol Heater Conversion	PA-31T PA-31T1	10/15/79	763-963		2140	18F23
893A	Gyro Indicator Relay Replacement	PA-31T1	05/21/80	**		3420	18G5
896	Landing Gear - Left Main, Torque Link And Safety Switch Deflector Replacement	PA-31T PA-31T1	05/23/80	764-014		3210	18G11
902A	Gyro Slaving Panel Switch Modification	PA-31T PA-31T1	04/15/81	29299-R2		3420	18G24
913A	Part I - Torque Transmitter Electrical Connector Restraint	PA-31T PA-31T1	03/16/83	764-105		7710	18I3
913A	Part II - Torque Transmitter Relocation/Isolation	PA-31T PA-31T1 PA-42	03/16/83	764-126 764-947L		7710	18I3
916	Elevator Control Stop Screw Replacement	PA-31T PA-31T1	07/17/81	**		2730	18I8
917	Portable Fire Extinguisher Inspection	PA-42	07/20/81	459-839 459-848		2620	18I11
921	Main Landing Gear Lock Rod Attachment Fork Replacement	PA-31T PA-31T1 PA-31T2	04/21/82	764-127		3230	18I21
922	Autopilot Rudder Servo Motor Access	PA-42	08/02/82	420-217		5320	18I22
924	Maximum Operating Airspeed (VMO)	PA-31T1	01/20/82	764-150 764-151		3410	18J2
925	Bleed Air Line Inspection/ Generator Cooling Scoop Cam Loc Receptacle Removal	PA-42	07/21/81	**		7110	18J3
926	Deice Relay Shelf Modification And Diode Addition	PA-42	07/21/81	**		2450	18J6
928	Pedestal Support Channel Assembly Removal	PA-42	09/29/81	404-829		7600	18J11
929	Pitch Servo Bridle Clamp Instruction	PA-42	02/11/82			2210	18J13
930	Powerplant Cowl Drain Inspection/ Modification	PA-42	07/21/81			7100	18J15

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
932	Pressurization Control Wiring Rework	PA-42	11/19/82	764-403		2130	18J19
935	ELT Antenna Inspection	PA-42	03/26/82	**		2560	18J23
937	Nose Gear Actuator Hose Replacement	PA-42	05/24/82	**		3210	18K1
941	Nose Wheel Shimmy Dampener Replacement	PA-31T PA-31T2	09/21/82	456-010		3250	18K5
942	Flap Handle Travel Inspection	PA-42	04/04/82	77196-03		2750	18K7
943	Pilot's Right Rudder Pedal Torque Tube Retention	PA-42	11/04/81	424-059		2720	18K9
945	Cowl Inlet Lip Screw Replacement	PA-42	02/16/82	414-468 406-561		5440	18K14
949	Elevator Trim Mechanism Modification And Enclosure Installation	PA-42	09/24/82	764-411L		2730	18K23
950	Battery Ventilation Tube Inspection	PA-42	06/08/82	420-202		2430	18K24
952	Engine Dual Drive Oil Supply Line Oil Pressure Snubber Relocation	PA-42	12/10/82	764-414		7920	18L3
954	Nose Landing Gear Strut Placard Inspection Replacement	PA-42	02/02/83	72236-02		3220	18L9
956	Cabin Door Cable Assembly Inspection And Modification	PA31T PA-31T1 PA-31T2	05/17/82	47716-04 57462-03		5210	18L11
960	Aft Fuselage Drain Holes Inspection	PA-42	12/03/82			5560	19A4
961	Environmental Control System Wiring Modification	PA-42	01/05/83	**		2100	19A7
962	Pitch Trim Drum Shaft Roll Pin Security	PA-42	03/18/83	MS20995-C32		2731	19A10
964	Avionics Bay Blanket Modification	PA-31T2	04/29/83	764-946		3400	19A14
969	Wing Tip Ground Strap Installation	PA-31T1 PA-31T3	07/11/84	**		2360	19A24
977	Dynamic Stability Improvement Kit	PA-31T	03/02/85	765-158		2730	19B21
979	Emergency Pressurization Bleed Air Valve Modification	PA-42	01/08/85	**		7530	19C1
983	Engine Air Inlet Duct Assembly Reinforcement	PA-42 PA-42-720	03/14/86	**		7161	19C12
986	Series Start Circuit Change Modification	PA-42-1000	07/22/86	765-194		2453	19C20
993	Engine Air Inlet Drain Holes	PA-42-1000	01/05/87	N/A		7162	19D13

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
994	Propeller Ground Clearance	PA-42-1000	01/12/87	**		3223	19D15
998	Remote Control Circuit Breaker (RCCB) Ground Wire Installation	PA-42-1000	07/08/87	765-322		2451	19E4
1002	Overhead Panel Map Light Switch Installation	PA-42-1000	04/08/88	84112-03		3314	19E14
1003	Oxygen Shutoff Valve Assembly	PA-42-720 PA-42-720R PA-421000	08/19/88	**		3510	19E17
1013	Improved Elevator Trim Cover Replacement	PA-42 PA-42-720 PA-42-720R	10/11/94	**		5510	19G1
1014	Addition of Grease Fitting to Nose Gear Steering Arm Bracket	PA-42 PA-42-720 PA-42-720R	10/17/94	**		3250	19G1
1015	Replacement of EATON Brand Electrical Contactor Box	PA-42-1000	07/14/95	766-296 557-125		2436	19G6
1017	Engine Fire Extinguisher System Rewire and Distribution of Walter Kidde Service Bulletin 899857-26-365	PA-42 PA-42-720	03/07/97	766-617		2623	19G11
1041	Accident/Incident Reporting	All	03/10/02	N/A		N/A	19K10
1052	Life Limited Parts Marking and Disposition	All	05/21/02	N/A		0510	19L19
1054	Propeller Control Arm Attachment Inspection	PA-31T PA-31T1 PA-31T2 PA-31T3	10/10/02	51623-000		6120	20A3
1069	Flight Control Cable Terminal Corrosion Inspection	All	03/31/03	N/A	CE-02-05 (SAIB)	2702	20C2

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

THIS PAGE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
177	Firewalls	PA-32 PA-32R	08/10/51				13B13
467	Alternator - Regulator System Modification	PA-32-260	01/10/66	756-992V		2430	14I5
475	Inspection Of Landing Gear Strut Exposure	PA-32-260	07/06/66			3210	14I17
476	Replacement Of Fuel Selector Valve	PA-32-260	04/26/66	492-104V	67-03-07	2820	14I18
484	Fuel System Operating Procedures	PA-32	12/20/66			2800	14J7
486A	Cylinder Head Temperature Probe Location	PA-32	04/16/68			7720	14J13
494	Inspection Of Cherokee Landing Gears	PA-32-260/300	11/07/67			3200	14J24
495	Inspection Of Control Cable- Constant Speed Propellers	PA-32-260/300	01/29/68	**		6120	14K2
499	Owners Handbook Revision	PA-32-260	03/14/68			General	14K6
527D	Inspection Of Control Wheels	PA-32-260/300	06/21/78	**	69-22-02	2700	15A14
535A	Rudder Trim Locking Pin	PA-32-260/300	09/26/69			2720	15B9
566	Autopilot Servo Spacer Bushing Installation	PA-32-260/300	09/25/70	760-508V		2210	15F3
571	Flap Handle Assembly Modification	PA-32-260/300	03/30/71	760-531V		2750	15F15
576	Stabilator Balance Weight Tube Replacement	PA-32-260/300	04/20/71	**		5570	15G2
577	Servo Bridle Cable Clamp Replacement	PA-32-260/300	06/01/71	757-863V		2210	15G8
581	Inspection Of Aileron Hinge Doublers	PA-32-260/300	07/12/71	760-540V		5550	15G20
600	Main Landing Gear Torque Link Inspection	PA-32-260/300	01/04/72	65691-00V	72-08-06	3210	15I12
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	02/21/73			5500	15J21
612A	Fuel Leakage - Fuel Sender Unit	PA-32-260/300	06/08/72	68101-00V		7330	15K1
614	Stabilator Attachment Fittings Bolt Torque	PA-32-260/300	06/15/72		72-14-07	2740	15K6
615	Stabilator Drain Holes	PA-32-260/300	07/06/72			2740	15K8
617B	Piper Automatic Locator Transmitter Replacement	PA-32	08/30/73		72-22-03	2560	15K18

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
620	Forward Cabin Door Reinforcement	PA-32-260/300	02/02/73	760-729V		5210	15L8
621	Main Landing Gear Torque Link Replacement	PA-32-260/300	11/09/72	**		3210	15L10
624	Altimatec IIIB-1 Gyro Horizon Fitting Installations	PA-32-300	09/01/72	458 840		3420	15L17
636	Prestolite Service Bulletin No. ASM-8 (Alternator Fan Replacement)	PA-32	10/24/72	**		2430	16B2
647	Seat Back Stop Modification	PA-32-260/300	03/31/73	760-740V		2510	16C1
653	Throttle Lever And Shaft, Serrated (Reference Avco Lycoming Service Instruction No. 1265, Dated December 15, 1972)	PA-32	04/09/73	**		7610	16C14
662	Engine Mount Bolt Torque	PA-32-260/300	07/06/73	AN960-616		7120	16D10
665A	Rotator Type Intake Valves	PA-32-300	10/24/73	**		7160	16D16
671	Inspection And Modification Rudder Bar Assembly	PA-32-260/300	10/05/73			2720	16E9
682B	Required Inspection Of Piston Pin (Reference Lycoming Service Bulletin No. 367D)	PA-32	04/19/74	**		7230	16F9
695	Roll Servo Inspection, Maintenance And Shear Pin Installation (Reference Attached Edo-Aire Mitchell Service Letter No. ML-38, Dated March 18, 1974)	PA-32	05/03/74	**		2210	16G13
700	Toe Brake System Modification	PA-32-260/300	04/09/74	760-842V		3240	16H5
707	Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973)	PA-32	02/27/74	**		7710	16I11
708	Nose Wheel Steering System Inspection	PA-32-260/300	06/07/74	**		3250	16I14
715	Emergency Locator Transmitter Switch Cover Modification	PA-32-260/300	09/27/74	760-876V		2560	16J12
718	Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)	PA-32	05/31/74	**		7410	16J18
732	Steering Stop Replacement	PA-32-260/300	09/30/74	95061-129		3250	16L6
734	Bendix ADF-T-12 C/D Installation Inspection And Modification	PA-32-260/300	12/03/74	760-857V		3450	16L8
738A	Modification Of The Overhead Fresh Air Vent System	PA-32-260/300	01/14/75	**		2120	16L20
745	Inspection Of Wing Mainspar Attach Bolts	PA-32-260/300	04/24/75	404-890		5710	17A14

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
747	Inspection Of Throttle Mixture Control Attachments	PA-32-260/300	05/28/75	**		7610	17A18
749	Torque Link Greaser Bolt Replacement Kit	PA-32-260/300	10/14/75	760-910V		3210	17A21
750	Rain Gutter Installation	PA-32-260/300	08/15/75	760-975V		5210	17A22
756	Dual Glideslope Indicator Placard (King Radio Installations Only)	PA-32-260/300	01/06/76	69669-112V		3430	17B22
758	Inspection Of Bendix Ignition Switches; Re: Bendix Service Bulletin No. 583	PA-32-260/300 PA-32R-300	05/17/76	761-065V		7410	17C2
761	Magnetic Compass Relocation Kit	PA-32-260/300	11/17/75	760-695V		3440	17C14
762	Modification Of ELT Remote Switches	PA-32-260/300 PA-32R-300	01/26/76	761-009V		2560	17C15
763A	Rear Leg Quick-Disconnect Seat Retention Mechanism Inspection	PA-32-260/300	11/14/75	**	75-24-02	2570	17C16
768	Aileron Balance Cable Pulley Support Bracket Modification	PA-32R-300	05/25/76	761-042V		2710	17D14
788	Air Conditioning Installations	PA-32-300 PA-32R-300	09/03/76	79584-02V 79589-05V		2150	17F19
791	Electrical System Refinement	PA-32R-300	02/24/77	761-087V		2400	17G3
793	Flap Warning Placard	PA-32-260/300 PA-32S-300 PA-32R-300	01/06/77	35664-02		2750	17G5
796	Lower Cowl Drain Inspection	PA-32-260	03/30/77			7100	17G10
797	Front Seat Modification (Aircraft With Club Seating Only)	PA-32-260/300 PA-32R-300	02/25/77	761-110V		2510	17G12
800	Performance Refinement Of Narco ADF - 140 Installation	PA-32-260/300 PA-32R-300	02/25/77	**		3450	17G19
808	Hydraulic Pump Terminal Inspection	PA-32R-300	06/08/77	**		2910	17H14
810	Landing Gear Extender, Backup, Diaphragm Replacement	PA-32R-300	04/15/77	761-138V		3230	17H18
813	Vertically Adjustable Seat Refinement	PA-32-260/300 PA-32R-300	06/09/77	**		2510	17I8
820	Replacement Of Lithium Sulphur Dioxide (LiSO2) ELT Batteries and/or Transmitters	PA-32-260/300 PA-32R-300 PA-32RT-300/300T	07/28/80	**		2560	17J2
836	Inspection And Modification Narco ADF-140/141 Antenna	PA-32-260 PA-32-300 PA-32R-300	02/09/78	**		3450	17K4
837	Inspection Of Elbow Assembly Engine Air Filter	PA-32-300 PA-32R-300	05/22/78			7160	17K7

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
842	Main Landing Gear Torque Link Greaser Bolt Inspection And Replacement	PA-32-260/300	09/26/78	760-910V		3210	17K17
861	Part I - Forward Facing Seat Back Modification	PA-32-260/300 PA-32R-300 PA-32RT-300/300T	11/13/78	763-890V		2520	18B7
861	Part II - Rear Facing (Club) Seat Back Retention	PA-32-260/300 PA-32RT-300/300T	11/13/78	408 834V		2520	18B8
862	Main Landing Gear And Strut Fairing Replacement	PA-32-260 PA-32-300	09/26/78	760-910V		3210	18B11
864	Part I - Forward Cabin Door Stop (Striker Plate) Installation	PA-32-260/300 PA-32RT-300/300T	12/08/78	**		5210	18B16
864	Part II - Cabin Heat Control Refinement	PA-32-260/300 PA-32RT-300/300T	12/08/78	763-870V 763-871V		2140	18B19
864	Part III - Turn And Slip Indicator Conversion, Vacuum To Electric Provision	PA-32-260	12/08/78	763-874		3420	18B20
864	Part IV - Induction Sump Drain Valve	PA-32R-300 PA-32RT-300	12/08/78	763-887V		7160	18B21
869	Part I - Installation Of Top Cowl Exhaust System Heat Shields	PA-32RT-300T	09/10/79	753-910V		7810	18C18
869	Part II - Modification Of Fuel Boost Pump Outlet Fitting	PA-32RT-300T	09/10/79	**		2820	18C19
869	Part III - Tachometer Cable Rerouting	PA-32-300 PA-32R-300 PA-32RT-300 PA-32RT-300T	09/10/79	763-916V		7710	18C20
882A	Part I - Rudder Skin Inspection And Modification	PA-32RT-300 PA-32RT-300T	11/12/81	763-936V	79-26-04	5540	18F4
882A	Part II - Rudder Skin Replacement	PA-32RT-300 PA-32RT-300T	11/12/81	763-940V	79-26-04	5540	18F6
884	Fuel Quantity Sender Check	PA-32-260/300	09/15/80	68101-002V		2840	18F11
895A	Magneto Switch Modification	PA-32-301	03/19/81	153-010 488-396		7430	18G8
900	Air Induction Valve Assembly Support Reinforcement	PA-32R-301T	07/30/80	**		7160	18G19
901	Cabin Air Intake Duct Modification	PA-32-301/301T PA-32R-301/301T	09/02/80	764-013V		2120	18G22
903A	Alternator Belt Installation (Air Conditioned Models)	Any Textron-Lycoming Powered PA-32	03/11/96	62833-82		2431	18H2
908	Instrument Panel Lighting - Century 21 And 41 Autopilot Installation	PA-32-301/301T PA-32R-301/301T	12/20/80			3310	18H11

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
920	Required Placard Adhesion Check	PA-32-260 PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	06/29/81			2500	18I19
923A	Cabin Heat Cable Heatshield Installation	PA-32-301T PA-32R-301T PA-32RT-300T	02/12/82	764-138V 764-137V		2140	18I24
927	Nose Landing Gear Refinement	PA-32R-300 PA-32RT-300 PA-32RT-300T PA-32R-301 PA-32R-301T	10/02/81	764-135V	81-24-07	3220	18J10
934	Bottom Cowl Modification	PA-32-300 PA-32-301	11/23/81	764-136V		7110	18J22
947	Pressure Switch Relocation Manifold Pressure Gauge	PA-32RT-300T PA-32R-301T PA-32-301T	02/05/82	764-216V		7710	18K19
948	Heated Windshield Panel Sealing And Gyro Filter Protection	PA-32R-301T	02/05/82	**		5610	18K20
997	Wing Removal And Reinstallation; Reference Airworthiness Directive 87-08-08	PA-32-260 PA-32-300	05/14/87	**	87-08-08	5711	19D24
1032	Improved Fuel Quantity Senders Available	PA-32R-301 II HP PA-32R-301T II TC	03/13/01	686-202 686-203		2842	19J1
1033	Air Conditioning Hose Replacement	PA-32R-301 II HP PA-32R-301T II TC	07/09/01	566-419 454-868		2155	19J4
1040	Alternator Drive Belt Conversion Kit for Aircraft Equipped with Optional Factory Installed Air Conditioning	PA-32-300 PA-32-301 PA-32-301T PA-32R-300 PA-32R-301 PA-32R-301T PA-32RT-300 PA-32RT-300T	11/28/01	767-310		2410	19K7
1041	Accident/Incident Reporting	All	03/10/02	N/A		N/A	19K10
1043	Oil Cooler Kit	PA-32R-301T II TC	04/25/02	767-332		7921	19K15
1049	Voltage Regulator Replacement	PA-32R-301 II HP PA-32R-301T II TC	04/30/02	68804-007 68804-006		2424	19L9
1052	Life Limited Parts Marking and Disposition	All	05/21/02	N/A		0510	19L19
1069	Flight Control Cable Terminal Corrosion Inspection	All	03/31/03	N/A	CE-02-05 (SAIB)	2702	20C2
1074	S-TEC Autopilot Component Seating Procedure	All	11/03/03	N/A		2210	20C14

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

THIS PAGE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	02/21/73			5500	15J21
614	Stabilator Attachment Fittings Bolt Torque	PA-34	06/15/72		72-14-07	2740	15K6
615	Stabilator Drain Holes	PA-34	07/06/72			2740	15K8
617B	Piper Automatic Locator Transmitter	PA-34	08/30/73		73-07-02	2560	15K18
618	Alternator Fan Replacement	PA-34	010/8/73	754-827V	72-15-02	2430	15L1
620	Forward Cabin Door Reinforcement	PA-34-200	02/23/73	760-729V		5210	15L8
622	Cabin Heater/Defroster Modification	PA-34	08/24/72	760-692V 760-693V		2140	15L12
624	Altimatic IIIB-1 Gyro Horizon Fitting Installation	PA-34	09/01/72	458-840		3400	15L17
625	Heat Exchangers And Heat Silencers Modification	PA-34	11/13/72	69471-21V		2140	15L20
626	Landing Gear Bolt Lubrication	PA-34	11/20/72			3200	15L23
647	Seat Back Stop Modification	PA-34-200	03/31/73	760-740V		2510	16C1
661	Engine Firewall Modification	PA-34-200	06/26/73	760-758V		5410	16D8
663	Stabilator Drain Hole Inspection (Deicer Equipped Aircraft Only)	PA-34-200	05/25/73			5300	16D11
664	Wing Skin/Rib Inspection And Modification	PA-34-200	04/17/74	760-771V		5710	16D13
665A	Intake Valves, RotatorType	PA-34-200	10/24/73	**		7160	16D16
668A	Engine Cowl Modifications	PA-34-200	08/07/74	**		7110	16E4
669	Aileron/Rudder Interconnect Cable System Modification	PA-34-200	04/16/74	760-776V		2710	16E6
671	Rudder Bar Assembly Inspection And Modification	PA-34-200	10/05/73			2720	16E9
673	Exhaust System Replacement	PA-34-200	09/28/73	760-764V		7810	16E14
677A	Propeller Spinner And Propeller Damper Installation Kits	PA-34-200	11/14/73	760-766V 760-781V		6110	16E22
682B	Required Inspection Of Piston Pin (Reference Lycoming Service Bulletin No. 367D)	PA-34	04/19/74	**		7230	16F9
684	Landing Gear Lubrication	PA-34-200	01/09/74			3200	16F18
700	Toe Brake System Modification	PA-34-200	04/09/74	760-842V		3240	16H5
704A	Inspection Of Fuel Crossfeed Drain Valves	PA-34-200	11/25/74	492-202V		2820	16H10

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
706	Propeller Damper Compression Spring (Reference Hartzell Service Bulletin No. 103 Dated 2/20/74)	PA-34-200	05/06/74	760-853V		6120	16I3
707	Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973)	PA-34	02/27/74	**		7710	16I11
714	Rudder Trim Modification	PA-34-200	06/04/74	760-800V	73-13-01	2720	16J11
715	Emergency Locator Transmitter Switch Cover Modification	PA-34-200	09/27/74	760-876B		2560	16J12
718	Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)	PA-34	05/31/74	**		7410	16J18
734	Bendix ADF-T-12 C/D Installation Inspection And Modification	PA-34-200	12/03/74	760-857V		3450	16L8
737	Manifold Pressure Gauge Line Modification	PA-34-200	12/02/74	760-765V		7710	16L19
738A	Modification Of The Overhead Fresh Air Vent System	PA-34-200	01/14/75	**		2120	16L20
742	Seneca II Refinement Modifications	PA-34-200T	05/09/75	**		1. 7110 2. 5200 3. 2740 4. 3400 5. 7410	17A8
747	Inspection Of Throttle And Mixture Control Attachments	PA-34-200	05/28/75	**		7610	17A18
750	Rain Gutter Installation	PA-34-200	08/15/75	760-975V		5210	17A22
754	Auxiliary Fuel System Modification	PA-34-200T	07/31/75	760-926V		2810	17B12
756	Glideslope, Dual, Indicator Placard (King Radio Installation Only)	PA-34-200/200T	01/06/76	69669-112V		3430	17B22
757	Aft Wing Modification (Optional)	PA-34-200	10/22/75	**		5710	17C1
761	Magnetic Compass Relocation Kit	PA-34-200/200T	11/17/75	760-795V		3440	17C14
762	Modification Of ELT Remote Switches	PA-34-200/200T	01/26/76	761-009V		2560	17C15
763A	Rear Leg Quick-Disconnect Seat Retention Mechanism Inspection	PA-34-200/200T	11/14/75	**	75-24-02	2510	17C16
769	Cold Weather Starting Procedures	PA-34-200T	03/10/76	**		7200	17D15
792	Optional Cold Weather Priming System Installation	PA-34-200T	12/10/76	761-094V		7310	17G4
793	Flap Warning Placard	PA-34-200/200T	01/06/77	35664-02		2750	17G5
795	Oil Cooler Baffle Winterization Modification	PA-34-200T	02/08/77	**		7230	17G9
797	Front Seat Modification (Aircraft With Club Seating Only)	PA-34-200T	02/25/77	761-110V		2510	17G12

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
800	Refinement Of Narco ADF-140 Installation Performance	PA-34-200T	02/25/77	**		3450	17G19
808	Hydraulic Pump Terminal Inspection	PA-34-200/200T	06/08/77	**		2910	17H14
813	Vertically Adjustable Seat Refinement	PA-34-200/200T	06/09/77	**		2510	17I8
818	Outside Air Temperature Gauge Replacement	PA-34-200T	10/19/77	99479-03V		3410	17I22
820	Replacement Of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters	PA-34-200 PA-34-200T	07/28/80	**	79-18-05	2560	17J2
836	Inspection And Modification Narco ADF-140/141 Antenna	PA-34-200T	02/09/78	**		3450	17K4
839	Main Landing Gear Trunnion Bushings	PA-34-200T	09/27/78	67026-10		3210	17K10
852	Nose Gear Placard (P/N 582 943V)	PA-34-200/200T	09/14/78	582-943V		3220	17L17
858	Inspection Of The Landing Gear Relay Wiring	PA-34-200T	10/10/78			3230	18A24
861	Part I - Forward Facing Seat Back Modification	PA-34-200 PA-34-200T	11/13/78	763-890V		2520	18B7
861	Part II - Rear Facing (Club) Seat Back Retention	PA-34-200T	11/13/78	408-834V		2520	18B8
881	Wiring Harness Protective Sleeve Installation	PA-34-200T	11/13/79	**		2400	18F1
889	Pneumatic Pump Inlet Filter Relocation	PA-34-200T	11/06/79	763-919V		3710	18F22
898	King KN5 - 80 Area Navigation System Cooling	PA-34-200T PA-34-220T	05/28/82	764-385V		2300	18G15
920	Required Placard Adhesion Check	PA-34-200T PA-34-220T	06/29/81			2500	18I19
946B	KN5 - 81 Wiring Change	PA-34-220T	09/01/82			3450	18K15
948	Heated Windshield Panel Sealing And Gyro Filter Protection	PA-34-220T	02/05/82	**		5610	18K20
963	Radio Master Relay Retrofit	PA-34-200T	11/09/83	**		2450	19A12
966	Tachometer Generator Mounting Modification	PA-34-220T	12/19/83	764-942V		7710	19A18
1020	Relocation of Signal Ground for Cylinder Head and Oil Temperature Sensors	PA-34-220T V	08/27/98	**		7701	19H4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1021	Distribution of Teledyne Continental Motors Service Bulletin SB 98-8 "Number One and Three Cylinder Intake Tube Modification" and subsequent modification of the engine installation to facilitate compliance.	PA-34-220T V	01/27/99	**		7313	19H7
1025	Replacement of Existing Cylinder Head Temperature Wires with Shielded Wiring.	PA-34-220T	10/01/99	**		7701	19I1
1031	Fuel Pump Cooling Inlet Installation	PA-34-220T V	12/11/00	766-678		7311	19I22
1036	Teledyne Continental Motors Service Information Letter SIL 01-2, "Precision Airmotive Corporation SIL RS-59"	PA-34-220T V	11/05/01	554-321		7318	19J14
1041	Accident/Incident Reporting	All	03/10/02	N/A		N/A	19K10
1048A	DDMP May Provide Erroneous Information in the Percent Power Query Mode at High Altitudes	PA-34-220T V	05/30/03	680-475		7700	19L6
1052	Life Limited Parts Marking and Disposition	All	05/21/02	N/A		0510	19L19
1069	Flight Control Cable Terminal Corrosion Inspection	All	03/31/03	N/A	CE-02-05 (SAIB)	2702	20C2
1074	S-TEC Autopilot Component Seating Procedure	All	11/03/03	N/A		2210	20C14
1078	Improved Flap Potentiometer	PA-34-220T V	01/19/04	100661-003		2751	20D4

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

THIS PAGE INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

**GRIDS 1118 THRU 1124
INTENTIONALLY BLANK**

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
177	Firewalls	PA-36	08/10/51				13B13
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	02/21/73			5500	15J21
633	Inspection And Repair Of Flood Exposed Airplanes	PA-36	10/09/72			5300	16A18
652A	Pilot And Maintenance Training Program	PA-36	06/14/73			0500	16C11
659	Seat Back Modification	PA-36	05/09/74	760-797V		2510	16D6
678	Relocation Of Throttle Control Rod End	PA-36	12/12/73			7610	16E24
682B	Required Inspection Of Piston Pin (Reference Lycoming Service Bulletin No. 367D)	PA-36	04/19/74	**		7230	16F9
693	Upper Cowl Support Modification	PA-36	03/29/74	760-811V		7110	16G9
707	Flyball Assembly To Improve RPM Control, Modified (Reference Hartzell Service Letter No. 75, Dated November 16, 1973)	PA-36	02/27/74	**		7710	16I11
718	Bendix Magneto Bulletin No. 566 (Reference Avco Lycoming Service Bulletin 373, Dated March 22, 1974)	PA-36	05/31/74	**		7410	16J18
727	Spray Pump Windmill Assembly Modification (Reference Agrinautics Service Bulletin No. SP-74-1 Dated April 30, 1974)	PA-36	08/08/74	**		0910	16K17
729	Elevator Control System Modification	PA-36	04/06/74	760-879V		2730	16K22
746	Air Filtration	PA-36	07/10/75	**		7160	17A16
759	Fuselage Forward Bottom Panel Reinforcement	PA-36	03/26/76	760-999		5310	17C11
765	Oil Change And Pre-Start Procedures	PA-36	11/26/75			7920	17D5
767	Replacement Of Parking Brake Valve	PA-36	01/28/76	98384-00		3240	17D12
771	Engine Care And Operational Tips, Tiara 6-285	PA-36	05/18/76			7200	17E1
774	Engine Cowl Modification	PA-36	05/18/76	761-062		7110	17E9
776	Fitting Installation Flap Control Bellcrank Grease	PA-36	10/11/76	761-068		2750	17E11
820	Replacement Of Lithium Sulphur Dioxide (LiS02) ELT Batteries and/or Transmitters	PA-36-285/300 PA-36-375	07/28/80	**		2560	17J2

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
825	Cockpit Door Emergency Release Refinement	PA-36-285 PA-36-300	11/30/78	763-811		5210	17J12
838	Manifold Pressure Gauge Line Filter Installation	PA-36-300	03/14/78	763-835		7710	17K9
849	Stabilizer Refinement	PA-36-300	10/31/78			5530	17L5
892	Engine Air Induction System Modification	PA-36-285 PA-36-300 PA-36-375	03/21/80	99849-14 555-846		7160	18G3
897	Rudder Attachment Hardware Replacement	PA-36-285/300 PA-36-375	06/02/80	**		5540	18G12
1041	Accident/Incident Reporting	All	03/10/02	N/A		N/A	19K10
1052	Life Limited Parts Marking and Disposition	All	05/21/02	N/A		0510	19L19
1069	Flight Control Cable Terminal Corrosion Inspection	All	03/31/03	N/A	CE-02-05 (SAIB)	2702	20C2

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
177	Firewalls	PA-38-112	08/10/51				13B13
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	02/21/73			5500	15J21
820	Replacement Of Lithium Sulphur Dioxide (LiSO2) ELT Batteries and/or Transmitters	PA-38-112	07/28/80	**		2560	17J2
855	Tomahawk Product Refinement Program	PA-38-112	10/20/78	**		1. 2520 2. 2510 3. 5300 4. 6110 5. 7810 6. 2520 7. 5340 8. 3210 9. 2740 2560 10. 5210 11. 2820 12. 5530 13. 2750 14. 3220 15. 5300 16. 2140	18A1
865	Elevator Trim System Inspection/Modification	PA-38-112	01/22/78	77878-02		2730	18B22
870	Upper Rudder Fairing Clearance Inspection	PA-38-112	07/05/79			5350	18C23
876	Additional Flow Strip Installation	PA-38-112	04/12/79	**	83-14-08	5720	18D17
877	Part I - Seat Cover Attachment Replacement	PA-38-112	04/30/79	455-001		2510	18D19
877	Part II - Aft Bulkhead Stiffener Channel Installation	PA-38-112	04/30/79	77554-06		5310	18D20
877	Part III - Placards Replacement	PA-38-112	04/30/79	763-932		2500	18D21
877	Part IV - Fuel Selector Handle Inspection	PA-38-112	04/30/79			2820	18D22
877	Part V - Stabilizer Drain Holes Addition	PA-38-112	04/30/79	**		5300	18D22
877	Part VI - Compass Compensation	PA-38-112	04/30/79	**		3440	18D23
877	Part VII - Main Gear Alignment	PA-38-112	04/30/79	**		3210	18D24
877	Part VIII - Elevator Stop Attachment	PA-38-112	04/30/79	**		5520	18E5
877	Part IX - Elevator Leading Edge Straps	PA-38-112	04/30/79	77618-D2 420-200		5720	18E5

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
895A	Magneto Switch Modification	PA-38-112	03/19/81	153-010 488-396		7430	18G8
909	Magneto Switch Replacement	PA-38-112	06/09/81	688 178	93-05-06	7430	18H14
911	Aft Spinner Bulkhead Replacement	PA-38-112	04/22/81	77710-04 77710-06		6110	18H21
931	Nose Gear Fork Assembly Improvement	PA-38-112	08/25/81	764-213		3220	18J17
944	Fuel Selector Valve Inspection And Lubrication	PA-38-112	04/20/82	**		2820	18K11
1041	Accident/Incident Reporting	All	03/10/02	N/A		N/A	19K10
1052	Life Limited Parts Marking and Disposition	All	05/21/02	N/A		0510	19L19
1069	Flight Control Cable Terminal Corrosion Inspection	All	03/31/03	N/A	CE-02-05 (SAIB)	2702	20C2

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
177	Firewalls	PA-46-310P	08/10/51				13B13
609	Control Surfaces Inspection And Maintenance Guidelines	All Models	02/21/73			5500	15J21
938	Forward Baggage Door Modification	PA-46-310P	07/10/84	765-109V		5230	18K4
965	Hydraulic Pump Installation Modification	PA-46-310P	09/25/85	765-161		2910	19A16
967	Lower Cabin Door Modification	PA-46-310P	06/28/84	765-104V		5210	19A20
968A	Oil Filler Door/Top Cowl Modification	PA-46-310P	07/28/86	**		7250	19A22
970	Main Landing Gear Door Link	PA-46-310P	08/07/84	**		3216	19B3
971B	Engine Baffle Modification And Aftercooler Clip Installation	PA-46-310P	02/23/87	**		7230	19B6
972	PART I - Hydraulic Pressure Gauge Line Fitting Replacement	PA-46-310P	08/20/84	762-643V		2930	19B9
972	PART II - Hydraulic Pressure Gauge Line Poppet Spring Replacement	PA-46-310P	08/20/84	764-874V		2930	19B9
973	Lower Cabin Door Step Up - Stop Installation	PA-46-310P	08/20/84	765-107V		5260	19B13
974	Fiberglass Nose Cowl Replacement	PA-46-310P	08/20/84	**		5430	19B15
975	Lower Cabin Door Duct Seal & Chain Stand-Off	PA-46-310P	02/13/85	765-135V		2120	19B17
976	Seat Pan Reinforcement	PA-46-310P	08/20/84	765-103V		2506	19B19
978	Cabin Heat Valve Modification	PA-46-310P	01/15/86	765-176		2140	19B23
981	Engine Tachometer Replacement	PA-46-310P	10/22/85	765-183		7710	19C7
982	Turbo Inlet Temperature Probe Wiring Modification	PA-46-310P	02/04/86	588-859		7728	19C9
984	Hydraulic Pump Annunciator And Controller Installation	PA-46-310P	07/15/86	**		2917	19C15
985	PART I - Teledyne Continental Motors Special Service Notice No. 3-86. "TSIO-520BE Engine"	PA-46-310P	04/18/86			7230	19C17
985	PART II - Alternate Air Intake Assembly Modification	PA-46-310P	04/18/86	765-198	87-04-01	7160	19C17
989	Stiffener Installation - Induction Air Panel	PA-46-310P	08/20/86	765-304		7102	19D3
990	Engine And Airframe Operational Characteristics And Operating Limitations	PA-46-310P	11/17/86	N/A		1100	19D5
991	Pilot/Copilot Oxygen System Modification	PA-46-310P	11/18/86	**		3512	19D9

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

REVISED: 06/04/02

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
992	Stereo System Power Supply Modification	PA-46-310P	11/19/86	584-387		2334	19D11
995A	Landing Gear Actuator Switch Modification - Gar Kenyon	PA-46-310P	05/28/87	407-560		3266	19D18
996	Engine Mount Heat Shield Installation	PA-46-310P	03/05/87	765-323		7120	19D22
999	Air Conditioner Compressor Mount - Shim Installation	PA-46-310P	07/17/87	84044-10 84044-11		2152	19E6
1000	Nose Gear Door Hinge Support Modification	PA-46-310P	10/16/87	765-347		3226	19E9
1001	Engine Mount Inspection/Modification	PA-46-310P	12/09/87	84010-48		7121	19E11
1004	Addition of Main Gear Door Protection Pad	PA-46-310P PA-46-350P	05/23/89	**		3216	19E20
1005	Nose Bowl Modification	PA-46-350P	06/08/89	766-215		5422	19E23
1006	Fuel Vent Line Protection	PA-46-310P	08/25/89	63913-199 488-702		3216	19F1
1007	Engine Air/Oil Separator Improvement	PA-46-350P	09/25/89	42414-00 02565-02		7251	19F3
1008	Operational Caution: Inoperative Turbine Inlet Temperature System	PA-46-350P	06/22/90	N/A		7200	19F5
1009	Bendix/King Installation Bulletin No. 312, Water Damage to the Pitch and Yaw Capstans and Servos	PA-46-310P PA-46-350P	09/19/90	**		2212	19F7
1010	Modification of Engine Baffle	PA-46-350P	01/19/94	**		7230	19F14
1011	Nose Gear Trunnion Replacement	PA-46-310P	04/27/94	766-211		7230	19F16
1012	Aileron Control Cable Replacement	PA-46-310P PA-46-350P	11/30/94	**		2710	19F23
1018A	Improved Intercooler Attachment Clips	PA-46-350P	09/13/99	89082-05		7236	18G23
1022	Lower Cowling Assembly Modification	PA-46-350P	02/12/99	766-658		5432	19H15
1023	Improved Security of the Pressure Controls Cable	PA-46-350P	04/12/99	**		2125	19H17
1026	Storm Window Seal Improvement Kit	PA-46-350P	11/03/99	766-659		5614	19I5
1030	Fuel Quantity System Improvement	PA-46-350P	05/31/00	766-673 766-674		2842	19I19
1035	Concorde Lead Acid Battery Conditioning	PA-46-500TP	07/20/01	N/A		2432	19J12
1037	Power Lever / Manual Override (MOR) Knob	PA-46-500TP	07/26/01	N/A		7611	19J21
1039	Replacement TIT Probe Availability	PA-46-350P	01/31/02	686-205	99-15-04	7726	19K4
1041	Accident/Incident Reporting	All	03/10/02	N/A		N/A	19K10

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
1046A	Generator Control Unit (GCU) Rewire Kit	PA-46-500TP	09/27/02	767-329		2430	19L1
1051	Gullwing Door Rub Strip Installation	PA-46-500TP	01/21/03	104644-004		7110	19L15
1052	Life Limited Parts Marking and Disposition	All	05/21/02	N/A		0510	19L19
1053	Engine Starter Motor Replacement	PA-46-350P	10/16/02	767-337		8011	20A1
1055	Executive Table Stow Adjustments	PA-46-500TP	06/20/03	N/A		2520	20A6
1056	Accessory Cooling Air Inlet Drain Hose Routing Inspection	PA-46-500TP	02/19/03	**		7500	20A9
1057	Upper Wing Skin Inspection and Reinforcement	PA-46-310P PA-46-350P PA-46-500TP	01/29/03	767-352 767-353		5730	20A12
1058	Horizontal Stabilizer Maintenance Manual Correction	PA-46-500TP	02/17/03	767-005		5510	20A16
1059	Tailcone Gusset Installation Kit	PA-46-500TP	03/03/03	767-356		5300	20A19
1062	Lower Torque Link Bolt Inspection	PA-46-500TP	02/13/03	**		3213	20B4
1067	Steering Bellows Improvement	PA-46-500TP	03/31/03	691-527		3250	20B20
1069	Flight Control Cable Terminal Corrosion Inspection	All	03/31/03	N/A	CE-02-05 (SAIB)	2702	20C2
1072	Possible Magnetization of ELT Antenna	PA-46-500TP	06/04/03	762-362		2300	20C9
1074	S-TEC Autopilot Component Seating Procedure	All	11/03/03	N/A		2210	20C14
1075	Higher Capacity Battery Availability	PA-46-500TP	10/27/03	601-910 767-375		2432	20C19
1076	Stall Warning Computer Verification	PA-46-500TP	01/09/04	600-517 599-161		3418	20C22
1077	Magic 1500 Autopilot Go-Around Switch Wire Security	PA-46-500TP	12/03/03	767-376		2200	20D1

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.

SERVICE LETTER INDEX

NUMBER	SUBJECT	MODELS AFFECTED	DATE	PART/KIT NO.	A.D. NO.	ATA CODE	GRID
--------	---------	--------------------	------	-----------------	-------------	-------------	------

GRIDS 1J8 THRU 1L24
INTENTIONALLY BLANK

* Reference latest FAA Bi-Weekly Listing for current A.D. Information.

** Reference appropriate service bulletin for material identification and/or appropriate aircraft model.

*** All Piper airplanes exposed to flood waters in Susquehanna River Basin as a result of Hurricane Agnes, 1972.