



SERVICE BULLETIN

No. 256

Piper Aircraft Corporation

"F.A.A. DOA EA-1 Approved"

Lock Haven, Pennsylvania, U.S.A.

August 25, 1967

<u>Subject:</u>	Replacement of Pneumatic Pump Hose
<u>Models Affected:</u>	PA-31 Navajo
<u>Serial Numbers Affected:</u>	31-2 to 31-58 incl.
<u>Compliance Date:</u>	Prior to but not later than next 50 hours of operation
<u>Reason For Bulletin:</u>	Replacement of Pneumatic Pump Outlet Hose, part number 82371-107 (Pump to Firewall)
<u>Material Required:</u>	Pneumatic Pump Hose Replacement Kit 757 175
<u>Availability of Parts:</u>	Piper Dealer
<u>Warranty Parts Allowed:</u>	Pneumatic Pump Hose Replacement Kit 757 175
<u>Warranty Labor Allowed:</u>	One (1) Hour
<u>Expiration Date of Warranty:</u>	January 31, 1968
<u>Disposition of Replaced Parts:</u>	Comply with Warranty and Credit Claim procedure
