



SERVICE BULLETIN

No. 262

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

"FAA DOA EA-1 Approved"

December 19, 1967

<u>Subject:</u>	Insulation of Solenoid Terminals
<u>Models Affected:</u>	PA-31 Navajo
<u>Serial Numbers Affected:</u>	31-2 to 31-94 incl., 31-96 to 31-101, 31-103
<u>Compliance Date:</u>	Prior to but not later than next 100 hours of operation
<u>Reason For Bulletin:</u>	To provide materials and instructions for the insulation of wire terminals at the battery, landing and taxi light solenoids.
<u>Material Required:</u>	Contained in Kit No. 757 185
<u>Installation Instructions:</u>	Contained in Kit No. 757 185
<u>Availability of Parts:</u>	Piper Dealer
<u>Warranty Parts Allowed:</u>	Kit No. 757 185
<u>Warranty Labor Allowed:</u>	One (1) Hour
<u>Expiration Date of Warranty:</u>	June 30, 1968

NOTE

Compliance card, contained in Kit No. 757 185, must be filled out and returned to Piper Aircraft Corporation.
