



SERVICE BULLETIN

No. 268

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

"F.A.A. DOA EA-1 Approved"

February 28, 1968

<u>Subject:</u>	Manifold and Check Valve Assembly
<u>Models Affected:</u>	PA-31 Navajo
<u>Serial Numbers Affected:</u>	31-2, 31-4 to 31-6 incl., 31-8 to 31-103 incl., 31-105 to 31-111 incl., 31-113 to 31-122 incl., 31-124, 31-125, 31-127, 31-129, 31-130, 31-135.
<u>Compliance Date:</u>	Prior to but not later than the next 100 hours of operation
<u>Reason for Bulletin:</u>	Availability of an improved manifold and check valve assembly for installation in the pneumatic system of the above referenced aircraft.
<u>Material Required:</u>	Manifold and Check Valve Replacement Kit 760 174
<u>Installation Instructions:</u>	Contained in Kit No. 760 174
<u>Warranty Parts Allowed:</u>	Manifold and Check Valve Replacement Kit 760 174
<u>Warranty Labor Allowed:</u>	Three (3) Hours
<u>Expiration Date of Warranty:</u>	August 31, 1968
<u>Disposition of Replaced Parts:</u>	Comply with Warranty and Credit Claim procedure
