



# SERVICE LETTER

No. 854

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

January 3, 1979

M

Subject:

Generator Airscoop Door Replacement

Models Affected:

PA-31T1 Cheyenne I  
PA-31T Cheyenne II

Serial Numbers Affected:

31T-7804001 through 31T-7904005  
31T-7400002 through 31T-7920019

Compliance Time:

At owner/operator's discretion.

Purpose:

A new rubber generator airscoop door with improved service life has been developed and is now available as a replacement for the existing door.

This service release announces availability of the replacement Kit and furnishes order information.

Instructions:

Instructions for installation are contained in Airscoop Door Replacement Kit, Piper Part Number 763 875.

Material Required:

One (1) each per aircraft, Airscoop Door Replacement Kit, Piper Part Number 763 875, at a suggested list price of \$11.45C each.

Availability of Parts:

Your Piper Field Service Facility.

Effectivity Date:

This Service Release is effective upon receipt.

Summary:

Please contact your Piper Field Service Facility to make arrangements for compliance with the provisions of this Service Release.