



SERVICE LETTER

No. 890

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

October 15, 1979 M

Subject:

Janitrol Heater Conversion

Models Affected:

PA-31T Cheyenne II
PA-31T1 Cheyenne I

Serial Numbers Affected:

31T-7820067 to 31T-7920041
31T-7904008 to 31T-7904015

Compliance Time:

At owner/operator's discretion.

Purpose:

This Service Release announces the availability of a Heater Conversion Kit designed to improve the reliability of the Janitrol Combustion Heater (Janitrol Model 10E21-1 (Phase II)) installed in the above-listed aircraft.

Instructions:

Installation instructions are included with Heater Conversion Kit, Piper Part Number 763 963.

Material Required:

One (1) each per aircraft Kit-Heater Conversion, Piper Part Number 763 963.

Availability of Parts:

Your Piper Field Service Facility.

Effectivity Date:

This Service Release is effective upon receipt.

Summary:

Please contact your Piper Field Service Facility to make arrangements for the installation of the above-described Heater Conversion Kit.

NOTE:

Aircraft equipped with Heater Model 62D33, 62D33-1, 62D33-2 (Phase I), or 62D33 Series Heaters modified with Piper Kit Number 761 139, will be addressed in a revision to this Service Letter.