



S.A. 31T-1
June 25, 1981

Modification FAA DOA EA-1 Approved

To: All Piper CORPAC's
Attention: CORPAC Service Administrator
Subject: Listing of Starter/Generator Installations in
Pilot's Operating Handbook (Report: 2124)
Equipment List

Models Affected: PA-31T1 Cheyenne I
Serial Numbers Affected: 31T-8104001 through 31T-8104010,
31T-8104020, 31T-8104021,
31T-8104023 through 31T-8104034

Compliance Time: At earliest opportunity; not to exceed next
scheduled Maintenance Event.

Purpose:

To insure that the Starter/Generators installed in the above-listed airplanes are appropriately identified in the Equipment List of the Pilot's Operating Handbook.

Instructions:

1. In Section 6, Weight and Balance, of the Pilot's Operating Handbook (Report: 2124), locate Item No. 71 in Electrical Equipment section of the Equipment List.
2. For aircraft with Serial Numbers 31T-8104001 through 31T-8104010, 31T-8104021, 31T-8104023 through 31T-8104034, use opaque typing correction fluid or eraser to delete "X" marked for Lear-Siegler installations. Mark "X" to designate Auxelec installations.
3. Aircraft Serial Number 31T-8104020 has one Lear-Siegler and one Auxlec Starter/Generator installed. One of each must be marked "X".
4. Make logbook entry of compliance with this service release.

(over)

Material Required:

Not Applicable.

Availability of Parts:

Not Applicable.

Effectivity Date:

This Service Release is effective upon receipt.

Summary:

Please advise current owner/operator of affected aircraft to arrange for compliance with this service release in accordance with Compliance Time, above.