



SERVICE LETTER

No. 656

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

May 15, 1973 M

Subject:

King Area Nav Operation Limitation Placard

Models Affected:

PA-31 Navajo

PA-31-350 Navajo Chieftain

PA-31P Navajo

Serial Numbers Affected:

31-7300907, 31-7300933, 31-7300934, 31-7300943 and
31-7300946

31-7305008 and 31-7305012

31P-7300111, 31P-7300113, 31P-7300115, 31P-7300125
and 31P-7300127

Compliance Time:

Immediately subsequent to receipt of placards.

Purpose:

The above referenced aircraft had King KN-74 or KNC-610 area navigational equipment factory installed under the provisions of the Custom Installation Program. Use of the area navigation system is limited to VFR flight only; a placard which states "Area Navigation Use Limited to VFR Only" is being supplied with copies of this Service Letter for affected aircraft.

NOTE: Please refer to FAA Advisory Circular 90-45 for guidelines relative to the implementation of area navigation (RNAV) within the national air space system.

Instructions:

Apply placard to the instrument panel, the radio face plate or the radio panel within two inches of the computer.

Material Required:

One (1) each per aircraft Placard, (King) Part No. 696-1109-00.

Availability of Parts:

Your Piper Dealer.

Effectivity Date:

This Service Letter is effective May 28, 1973.

Summary:

Service Publication Compliance forms are being supplied to Distributors with the above referenced aircraft in their area of operations. Subsequent to installation of the above placard the affected aircraft owner/operator must sign the form and leave the form with his Piper Dealer.